

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 21

T. S.

R 9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

**50**

CONT - - - -  
Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
April 16, 1987  
C.S. 62/40

1/4 Cor. Sec. 7 only, T.21-8)  
Found - Witness post and sign bears east 1 1/2 ft. set by L. Roberts  
PLS #1039 in 1985 condition report. (C.S. 63/18)  
East 1/4 sec. cor. for 12 only (1967 BLM BC/I.P.) bears South  
79.7 ft. (agrees well with Roberts 1985 report). 1967 resurvey  
shows a dist. between BC/I.P. as 80.52 ft.  
Set - 1945 GLO cap & pipe is returned to plumb position and is sur-  
rounded by a 2 ft. dia. 1 ft. high mound of sandstone. Brass  
cap faces south.  
(A search was made for original evidence but none was found.)  
New BTs - 14" D. fir with a double blaze scribed "1/4 S7 CS BT" bears  
N.1 1/4°E., 23.8 ft.  
13" dia. D. fir with a double blaze scribed "1/4 S7 CS BT"  
bears N.82°E., 21.1 ft.  
Brass cap/iron pipe is approx 30 ft. south of a E-W ridge on a steep south-  
east slope.

4/16/87

Les Roberts  
L.S. #1039  
Nov. 26, 1986  
C.S. 63/50

Center 1/4 Corner for Section 9  
(Note: Corner referenced out April 17, 1986 for planned logging  
activity. See C.S. 63/50 for notes.)

**51**

CONDITION REPORT  
Found - 1 1/2" x 36" iron pipe set in M90-13 has been up-rooted by recent  
logging activity. Ren. #33  
18" Fir stump, N.10°E., 8.7 ft. (scribe vis.) 1981 BT.  
20" Fir, S.79°W., 38.4 ft. (scribe vis.) 1981 BT.  
Set - Re-set 1 1/2" x 36" iron pipe by using R.P. hubs set on 4/17/86.  
Buried purplemagnetic marker under 36" iron pipe.  
Set metal fence post, with survey attention sign attached to,  
beside iron pipe. Painted BTs red.

11/26/86

**52**

Les Roberts  
L.S. #1039  
For: I.P. Co.  
December 1989  
M 109-42  
C.S. 63/102

1/4 Corner for Sections 30 and 31  
Set - 3/4" x 36" finned alum. rod with 3 1/2" alum. cap. Buried purple  
magnetic marker beside 36" alum. rod. Set 72" alum. post with  
land survey monument sign bolted to, beside alum. cap.  
New BTs - 10" alder, S.58°W., 6.6 ft. bark scribed/painted red.  
10" hemlock, N.57°W., 16.2 ft. scribed/painted red.  
10" alder, N.3°E., 18.0 ft. bark scribed/painted red.  
11" alder, S.31°E., 21.8 ft. bark scribed/painted red.  
Corner lies on S.E. slope about 200 ft. east of ridge. Ridge bears S.45°W.  
and N.45°E.

12/22/89

**53**

Section corner for Secs. 25 and 36 only of T.21-10  
Found - 1919 GLO brass cap with pipe broken off.  
38" fir, N.65°W., 58.5 ft. scar vis., (1919 BT rec. N.65°W, 58.1)  
20" hemlock, N.81°W., 20.8 ft. scribe vis., No record.  
Set - 3/4" x 36" alum. rod with a 3 1/2" alum. cap beside broken  
pipe. Buried purple magnetic marker beside 36" alum. rod.  
Set 72" alum. post, with land survey monument sign bolted  
to, beside alum. cap.  
New BTs - 16" hemlock, S.42°E., 41.5 ft. scribed/painted red.  
19" Hemlock, S.69°W., 6.7 ft. scribed/painted red.  
Corner falls on NE slope about 125 ft. north of ridge. Ridge bears N.35°W.  
and S.35°E.

12/21/89

**54**

West 1/4 Corner, Section 31 only.  
Found - 1" iron pipe with 2 1/2" brass cap. I.P. had rusted in two at  
ground level. (1919 GLO BC)  
58" cedar with axe marks bears N.07°E., 47.94 ft. to side center.  
A stump hole where Fir BT was blown out of and slid down hill  
bears S.76°E., 19.14 ft. to center of hole.  
Set - A 2" alum. cap on a 3/4" x 30" I.R. along side old monument.  
Cap mkd.: Stuntzner Eng. T21S R9W | S31 W 1/4 1990 LS 2244  
New BTs - A 56" cedar w/face scribed W1/4 S31 BT and tag bears S.25°E.,  
52.93 ft. to a spike in side center.  
A 58" cedar w/face scribed W 1/4 S31 BT and tag bears N.07°E.,  
47.94 ft. to a spke in side center.