

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 9 W. R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 91881

Douglas County Surveyors Office  
Randall Smith, Stephen Flause, J. Pike  
May 20, 1992  
C.S. 64/26

1/4 Corner for Sections 21 & 22.

59

Found - 2 1/2" dia. brass cap marked 'T20S R9W 1/4 21|22 1983 PLS 1039' (mismarked) on a 1 1/2" O.D. iron pipe, firmly set and protrudes approx. 3" above ground. A 1/2" dia. 36" long steel rebar post with a yellow boundary sign is loosely set at north edge of found brass cap. Sign and post were temporarily removed from monument vicinity to relieve magnetic influence on compass bearings. See Renewal # 45.

Accessories Found -

8" Cedar now a 2 1/2' tall by 24" dia. rotted stump with no scribing visible bears N.79°E., 17.2 ft. (rec. N.71 1/2°E., 17.2ft.) (orig. BT

16" Fir now a fallen and rotted 18" dia. fir with a previously opened blaze showing the scribing "1/4 S". The base and root hole of which bears N.10°W., 26.4 ft. (as per record)

Evidence of an original line tree is also found.

48" Cedar now a rotted and broken 42" D.B.H. by 20ft. tall cedar snag with 2 notches on the north edge and 3 notches on the south edge of its trunk, bears north 31.7 ft. (as per record)

Evidence of two bearing trees from renewal # 45.

29" Hemlock now a 31" dia. 5 ft tall stump with a partially healed double blaze revealing the scribing "1/4 S22 BT" w/brass washer bears N.68 1/4°E., 47.6 ft. (rec. N.70°E., 47.6 ft.)

56" Cedar now a 58" D.B.H. with a partially healed double blaze revealing the scribing "E1/4 S21" w/brass washer bears South 12.2ft. (record S.6°W., 12.2 ft. Bearing to brass washer is S.4°E.)

Monument set - Township designation on found brass cap should read T.21S. not T.20S. Brass cap markings were corrected in field.

New Accessories -

8" D.B.H. Hemlock double blazed and scribed "1/4S S22 CS BT" bears S.86°E., 32.4 ft.

Rebar and attached sign are returned to position at N. edge of Monument

Note - Monument is on a north south cutting line on steep N.N.E. slope.

Monument is approx. 500 ft. westerly from a logging rd. running in a northerly direction.

6/10/92

Section Corner for Sections 5 & 6 T. 21 S. R. 9 W. Ren No. 7  
and Sections 31 & 32 T. 20 S. R. 9 W.

60

Found - 2 1/2" BLM Brass cap with the following accessories:

17" Maple N 8°E, 22.1'

11" Maple N 42°W, 22.4'

17" Maple S 47°W, 21.1'

Fir BT is uprooted. (Ren. No. 7)

New BT- 20" Alder S 30°E 30.8'. Barkscribed "T21S R9W S5 BT" 2/93

Robert Ward, Jr  
For: International  
Paper Co.  
Feb. 1993  
M 116 - 61

Cor. for Secs. 19 & 30 T21-8 only

61

Found - 1945 GLO brass cap

52" D.Fir stump, badly burned, bears S.20°E., 135 lks. (1945)

54" D.Fir uprooted stump, bears N.17 1/4°E., 360 lks., no visible marks. (1945)

13" D.Fir, bears N.54°E., 7.3, with a healed face, not tagged. (REN. #22)22

15" D.Fir, bears S.59°E., 19.1', with a healed face, not tagged. (REN. #22)22

New BTs- 14" D.Fir, bears N.6°E., 26.3', scribed "T21S R8W S19 BT"

12" D.Fir, bears S.62°E., 4.8', scribed "T21S R8W S30 BT"

15" D.Fir, bears S.4°E., 16.7', scribed "T21S R8W S30 BT"

12" D.Fir, bears N.59°W., 21.0', scribed "T21S R9W X BT"

1/4 Cor. for Sec. 19 T21-8 only

62

Found - 1945 GLO Brass Cap  
13" D.Fir, bears S.56°E., 33.5', with healed face.

New BTs- 15" D.Fir, bears N.1°W., 12.1', scribed "1/4 X BT"

16" D.Fir, bears S.3°W., 9.5', scribed "1/4 X BT"

11" D.Fir, bears N.61°W., 10.7', scribed "1/4 X BT"