

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 10 W. R. W. W. M.

YOKE-CHAPMAN CO., EUGENE, ORE. 3181

H.L. Eppstein
Wit: F. Cain
W. Dailey
Jan. 25,
1929

Ren. Co. Vol. 1
Pg. 7

Bruce R.
Rogers, Dep.
April, 1965
C. S. File
No. 54/1

Vernon "Ray" Tracy
J. Heritage & E. West
March 15, 1967
C.S. File No. 54/1

Township Corner

S36	S31	T20S
S 1	S 6	T21S

R11W R10W

Set Corner from old Witness Tree in Section 6, Maple.
Set - 2" x 4" Galv. Iron Pipe, Mkd: new trees as follows:
4" Fir Bears S.77°15'E. 65 lks.
10" Maple bears S.27°W. 17 lks.
20" Maple bears N.14°W. 23 lks.
No trees near in Section 31.

Wit. Corner to Sec. Cor. to Secs. 32 and 33, only. Found - 16" Fir, now 30" Snag N.65°W. 37.6 ft., chopped out, fd. good scrbing. GLO 1919 Brass Cap at Corner. No trace of N. E. BT.
Set - Brass Cap 34 ft. South of Corner Mkd: County Surveyor's Office, 1965
T21S R10W S32/S33
T22S (35 FT. No. to Cor)
New BT's: 26" Fir N.17°E. 6.8 ft. Mkd: W.C. T22SR10W S5 CS BT.
24" Fir S.75°E. 15.4 ft. Mkd: W.C. T22SR10W S5 CS BT.

Section Corner to Sections 1 - 2 - 11 - 12
Found - 1919 GLO Brass Cap with pipe broken off at ground level, 17" down & from top, & 1919 BT's, as follows:
16", now 18" Alder, almost dead, face rotted away, no scribe., N. 44 1/2 °E. 8.6 ft.
12", now 14" Alder, 20' high snag, S. 52° E. 8.6 ft., frag scribe marks on unhealed blaze.
12", now 15" Alder, nearly dead, S. 32° W. 13.9 ft., unhealed blaze, face rotted, no scribe.
No trace of N.W. Bt.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office (Set in place of old I.P.) 1967
T 21 S R 10 W.
S 2 | S 1
S 11 | S 12
New BT's: 10" Hemlock N. 13° E 15.1 ft. mkd. T21S R10W S1 CS BT.
14" Hemlock S. 79° E. 25.6 ft. mkd. T21S R10W S12 CS BT.
8" Hemlock S. 10° W. 36.7 ft. mkd. T21S R10W S11 CS BT.
15" Hemlock N. 84° W. 25.2 ft. mkd. T21S R10W S 2 CS BT.
Note - This corner lies approx. 150 ft. west of Rd. #217.
Reset Old Brass alongside.

Apr. '70-Tom McCullough Set 1 fence post ± 5 ft. north facing east (C.S. File 55/148)
MICROFILM TO HERE 10/67

West 1/4 Corner to Section 11 only.
Found - 1" Iron pipe filled with concrete at corner point, Brass Cap broken off and gone.
Orig. 36", now 46" Hemlock, alive, S. 70° E. 31.7 ft., shows good scar.
Rescribed: "1/4 S11 CS BT".
N.E. Orig. BT. gone.
Call on creek to north and call dist. betwn 1/4 S10 & 1/4 S11 fits good.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968
T 21 S R 10 W
1/4 | S 11
New BT: 14" Hemlock N. 89° E. 62.9 ft. mkd. "1/4 S11 CS BT.
Note - Deposit old pipe alongside new monument.
This corner lies on very steep northerly slope 46 ft. S. of creek.
3/13/68

East 1/4 Corner to Section 10 only.
Found - 1" Iron Pipe filled with concrete, badly rusted and Brass Cap broken off.
Orig. 36" now 46" Fir N.38°W. 15.8 ft., alive, shows good scar.
S.W. BT. gone, find hole where it would have been.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968
T 21 S R 10 W
1/4 | S 10
New BT's: 9" Cedar N.68°W. 13.1 ft. mkd. 1/4 S10 CS BT.
12" Hemlock N. 6° W. 26.0 ft. mkd. 1/4 S10 CS BT.
Note - Deposit old pipe & brass cap alongside new monument.
This corner lies approx. 70 ft. S. of top of spur ridge, course W.
3/13/68

C.S. 54/1

FD-12/83
1795/79
E. Blum