

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 10 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

6

$\frac{1}{4}$  Corner to Section 2 and 11.  
Found - 1" Iron Pipe, filled with concrete with brass cap broken off & remains of Orig. BT's:  
Orig. 14" Hemlock, now only decayed remains of stump with part of old axe blaze, S.17°E. 33.0 ft., no scribe.  
Orig. 40" Hemlock N.70°W. 12.5 ft., now only partial decayed shell of stump, no scribe found.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968  
T 21 S R 10 W  
 $\frac{1}{4}$   $\frac{S}{S 11}$   $\frac{2}{11}$

New BT's: 5" Hemlock N.69°E. 20.1 ft. mkd.  $\frac{1}{4}$  S2 CS BT.  
14" Hemlock S.52°E. 45.3 ft. mkd.  $\frac{1}{4}$  S11 CS BT.

Note - Deposit old pipe & cap alongside new monument.  
This corner lies on E. side of creek 2 ft. wide, course NW.  
3/13/68

C. S. File No. 54/1

TOWNSHIP CORNER - Twps. 20 & 21 S. - R.s. 10 & 11W.

FDOKPER  
SUNTZNER  
M109-13  
10/89

Found -  $\frac{3}{4}$ " I. Pipe & BT's. called for in Ren. #2, T20-10W. - Ren #1 T21-10W  
20", now 28" Maple N.14°W. 15.2 ft., alive, shows good scar. Do not open.  
10", now 16" Maple, alive, S.27°W. 11.2 ft., shows good scar. Do not open.  
4", now 20" Fir, alive, S.77 $\frac{1}{2}$ °E. 42.9 ft., faint scar.

(Rescribed: T21S R10W S6 CS BT)  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968  
T 20 S 11 W S36/S31 10  
T 21 S W S 1 S 6 W

New BT: 14" D. Fir N. 80°E. 83.6 ft. mkd. T20S R10W S31 CS BT.  
Note - This corner lies on very steep S. slope about 300 ft. N. of Smith River Road. Deposit old corner pipe alongside brass cap.  
3/27/68

C. S. File No. 53/66

**RE-RENEWED SECTION CORNER NO. #131**

North  $\frac{1}{4}$  Corner to Section 2 only, T21-10W.  
Found - No trace of Brass Cap, but 1951 BT's., as follows:  
60", now 60" D. Fir, S.6°E. 63.4 ft., alive, blaze pitched over & healing.

20", now 26" Hemlock, alive, S.47°W. 36.3 ft., scribemarks visible on partially healed blaze.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968  
(Set 6' steel fence post) alongside Brass Cap  
T20S R10W  $\frac{1}{4}$   $\frac{S}{S 2}$   
T21S

Note - The  $\frac{1}{4}$  Cor. of Sec. 35, T20-10W bears N. 87 3/4° W. 13.9 ft.  
This corner lies on edge of new logging road, course N.30W-S.30E.  
5/8/68

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
May, 1968  
C. S. File No. 54/1

8

South  $\frac{1}{4}$  Corner to Section 35 only, T20-10W.  
Found - No trace of Brass Cap, but 1951 BT's., as follows:  
20", now 24" Hemlock, alive, N. 45 $\frac{1}{2}$ °E., 45.5 ft., scribe marks visible on nearly healed blaze.  
24", now 26" Hemlock, alive, N. 54 $\frac{1}{2}$ ° W. 92.4 ft., scribe marks visible on partially healed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968  
(Set 6' Steel Fence Post alongside B. C.)  
T20S R10W  $\frac{1}{4}$   $\frac{S}{S 35}$   
T21S

Note - The  $\frac{1}{4}$  corner of Sec. 2, T21-10W bears S.87 3/4° E. 13.9 ft. & 14 ft. west of new logging road, course N.30°W.-S.30°E.  
5/8/68

9

Section Corner to Sections 5 and 4, T22-10W.  
Found - 2" I. Pipe, filled with concrete, & brass cap, broken off, at corner with 1919 BT's. as follows:

14", now 32" Fir, alive, S.75°E. 26.4 ft., shows good scar, We do not open. Rescribe: "T22S R10W S4 CS BT".  
12", now 20" Alder, alive, S.31°W. 39.6 ft., shows scar. We Rescribe: "T22S R10W S5 CS BT."

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968  
(Deposit old pipe & B.C.)  
T 21 S R 10 W  
T 22 S S 5 S 4 10W

We used Orig. BT's. to rescribe because new trees would be too far.  
Note - This corner lies on steep N.W. slope 50' E. of small ravine, course N.E. & approx. 220 ft. W. of top of spur, sloping N.E. Dense salmonberry & vine maple brush.  
5/15/68

10