

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

11

Witness Corner to Sections 32 & 33, T21-10W.  
Found - 1965 County Surveyor's Brass Cap & Stumps of BT's, as recorded in Ren. #2. 20  
26" Fir Stump N. 17° E. 6.8 ft., scribe visible on pitched blaze.  
24" Fir Stump S. 75° E. 15.4 ft., scribe visible on pitched blaze.  
Set - 6 ft. Steel Fence Post alongside Brass Cap.  
Note - No trees available for new bearing trees. Corner lies 35 ft. S. of U.S.F.S. Rd. #2173 on top of cut bank in logged off area.

12

Section Corner to Sections 35 and 36, T21-10W.  
Found - Orig. BT's., as recorded in 1919, as follows:  
14", now 26" Fir, turned out & slid downhill, N.39°E. 25.7 ft.  
60", now 65" Fir, 50 ft. high snag, N.53°W. 54.1 ft., open & find scribe  
No trace of I.P. or Brass Cap set in 1919.  
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968 T21S S 35 | S 36 R10W T22S  
New BT's: 14" Maple N.59°W. 47.3 ft. mkd. T21S R10W S35 CS BT.  
16" D.Fir N.11°E. 57.2 ft. mkd. T21S R10W S36 CS BT.  
Note - This corner lies on E-W cutting line on very steep, N.E. slope.  
Set 6 ft. steel fence post alongside Brass Cap. 5/15/68

13

1/4 Corner to Sections 19 and 20.  
Found - 1919 G.L.O. Brass Cap, broken off, concrete filled I. Pipe under logs and road construction debris., & Orig. BT's., marked in 1919, as follows:  
14", now 26" Hemlock, alive, S.79°E. 28.4 ft., shows good scar. We do not open.  
12", now 24" Alder, N.36°W. 31.7 ft., turned out, shows scar on lower side.  
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968 T 21 S R 10 W 1/4 S 19 | S 20  
New BT's: 9" Hemlock N. 78° E. 25.2 ft. mkd. 1/4 S20 CS BT.  
13" Maple S. 76° W. 17.5 ft. mkd. 1/4 S 19 CS BT. (in bark)  
Note - This corner lies on steep N. slope approx. 66 ft. N. of U.S.F.S. Rd. #2138. Deposit old corner material alongside B. Cap.

14

Section Corner to Sections 33 & 34, T21-10W.  
Found - 1919 GLO Brass Cap, broken off & concrete-filled I. Pipe, in place.  
Orig. 22", now 38" Fir, alive, N.54 1/4°E. 31.0 ft., shows good scar. We do not open. Rescribe: "T21S R10W S34 CS BT".  
Orig. 20", now 35" Fir, alive, N.83°W. 42.2 ft., shows good scar. We do not open. Rescribe: "T21S R10W S33 CS BT."  
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968 T 21 S R 10 W S 33 | S 34 T 22S R 10 W  
We Rescribed Orig. BT's. because nothing other than Alders close to North. This corner lies on very steep south slope approx. 175 ft. W. of top of ridge, course S.E.- N.W.

15

North 1/4 Corner Section 2, T22S R10W.  
Found - 1919 GLO Brass Cap, broken off, concrete filled pipe in place, alongside Corner Tree, a badly decayed stump.  
Orig. (1894) 40" Fir, now badly decayed snag, N.75°E. 15.2 ft., we open & find "1/4 S7" scribe.  
Orig. (1919) 8", now 9" Fir, S.5°E. 9.9 ft. (Rec.S.5°W.) now snag, we open & find "S7 1/4" scribe.  
1919 16", now 22" Fir, alive, S.73°W. 7.9 ft., shows scar.  
We Rescribe: "1/4 S 2 CS BT".  
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1968 T21S R10W 1/4 S 2 T22S  
On the north side of corner stump at the place where bearings and distances meet. Deposit corner material alongside Brass Cap.  
New BT: 16" D.Fir S.22°E. 26.2 ft. mkd. 1/4 S 2 CS BT.  
Note - This corner lies on very steep S.E. slope approx. 75.0 ft. west of ravine, course south.

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
May, 1968  
C. S. File NO. 54/1