

Douglas County Surveyor's Record of
Government Corners Renewed

T.21 S. T.S. R. 10 W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

16

$\frac{1}{4}$ Corner Section 32, T21-10W. *SOUTH*
Found - I.P., filled with concrete. Brass Cap, broken off and found
in dug when excavating for new monument.
10", now 16" Alder N.35°E. 13.9 ft. (Rec. 10.6') alive, we open
& find edge of axe blaze., badly decayed.
Only hole where N.W. BT. probably stood, fits record bear. & Dat.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T21S R10W $\frac{1}{4}$ S.32
T22S
(Deposit old corner material alongside)
New BT's: 12" D. Fir N.45°E. 26.0 ft. mkd. $\frac{1}{4}$ S32 CS BT".
7" D. Fir N.11°W. 13.9 ft. mkd. $\frac{1}{4}$ S32 CS BT".
Note - This corner lies on steep N.W. slope 50 ft. W. of spur,
sloping N.W.

17

North $\frac{1}{4}$ Corner Section 5, T22-10W.
Found - 1919 GLO Brass Cap, buried & broken off, concrete-filled
I. Pipe in place.
6", now 8" Cherry, down & decayed, laying across I.P., S.83°E.
15.8 ft., no scribe found.
8", now 18" Alder, alive, S.25°W. (Rec. S.20°W) 16.5 ft., shows
scar, we do not open. Rescribe in bark: $\frac{1}{4}$ S5 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1968 T21S $\frac{1}{4}$ S 5 R10W
T22S
(Deposit old corner material alongside)
New BT's: 26" D. Fir S.21°W. 39.7 ft. mkd. $\frac{1}{4}$ S5 CS BT".
14" D. Fir S.42°W. 58.5 ft. mkd. $\frac{1}{4}$ S5 CS BT".
Note - This corner lies 297 ft. W. of U.S.F.S. line, tag on top
of ridge, sloping N.W.

18

Section Corner to Sections 2 and 1, T22-10W.
Found - 1963 Cadastral Brass Cap & BT's., as follows:
26" Sawed Fir Stump S.51 $\frac{1}{2}$ °W. 25.7 ft., scribe visible.
1919 BT's. down. 1919 Brass Cap gone.
Set - 6 ft. Steel fence post alongside Brass Cap.
New BT's: 18" Alder S.72°E. 41.0 ft. mkd. T22S R10W S1 CS BT.
16" Alder S.51°E. 36.1 ft. mkd. T22S R10W S1 CS BT.
Note - This corner lies on very steep, N.W. slope near N.E. corner
of clear cut unit & approx. 100 ft. W. & 75 ft. south of
solid rock ravine, course N.W.

19

$\frac{1}{4}$ Corner to Section ~~36~~ ³⁵, T21-10W
Found - 1919 Brass Cap, broken off, concrete-filled I.P. in place.
6", now 7" Fir, decayed stub, N.21°E. 10.6 ft., shows
fragmentary scribe.
16", now 22" Fir, N.79°W. 4.0 ft. Alive, shows good scar.
We do not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T21S R10W $\frac{1}{4}$ S.35
T22S
(Deposit old corner material alongside)
New BT's: 10" D. Fir N.76°E. 13.7 ft. mkd. $\frac{1}{4}$ S35 CS BT.
22" D. Fir N.79°W. 4.0 ft. Rescribed: $\frac{1}{4}$ S35 CS BT.
Note - This corner lies on steep S.W. slope approx. 85.0 ft. W. of top
of spur, ridge sloping south.

20

Witness Corner to Sec. Cor. to Sections 32 & 33 only, T21-10W.
Found - 1965 C.S. Brass Cap & sawed stumps of BT's, as follows:
See Renewals No. 2 and No. 11.
26" Fir Stump N. 17° E. 6.8 ft., scribe visible. Set 5/8" x 30"
I. R. on bearing at 5.4 ft. from Wit. Cor. at base of BT.
24" Fir Stump S.75°E. 16.9 ft. (not 15.4') scribe visible.
Set 5/8" x 30" I.R. 15.6 ft. from Wit. Cor. at base of BT.
Set - 6 ft. Steel Fence Post alongside Brass Cap.
No trees available for new BT's. Witness Corner lies on top of
cut bank 35 ft. S. of U.S.F.S. Rd. #2138. At true corner point, set
5/8" I.R. x 15" Sandstone in roadway flush with surface 3.0 ft. W. of
ditch line.
Witness Corner bears South 34 feet. - See next page for further details - - - - -

5/24/68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
May 21, 1968
C. S. File No. 54/1