

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

(continued)

The 5/8" x 30" I. Rod's set at base of Witness Corner BT's., as follows;  
from 5/8"x15" I.R. set at true corner point on edge of roadway:  
5/8"x30" I.R. bears S. 19° E. 58.3 ft. This rod is 6" above ground at  
base of Witness Corner BT. to S. E.  
5/8"x30" I.R. bears S. 3° E. 28.0 ft. This rod is 6" above ground at  
base of Witness Corner BT. to N.E.

South 1/4 Corner to Section 36, T21-10W. 21

Found - 1919 G.L.O. Brass Cap laying on ground, pipe broken off 10" below surface.

Orig. 8", now 9" Fir Snag, N. 24° E. 25.1 ft., "36" scribe visible on open blaze, badly decayed.

Orig. 6", now 24" Fir, alive, N.55°W. (Rec.N65W) 13.9 ft., shows fair scar. We do not open. Rescribed "1/4 S36 CS BT".

Set - Brass Cap at Cor.Mkd: County Surveyor's T 21 S R10W 1/4 S 36  
Office, 1968 T 22 S

Deposit old corner material alongside brass cap.

New BT's: 28" D.Fir N. 25° E. 45.3 ft. mkd. "1/4 S 36 CS BT".

Note - This corner lies on moderate southerly slope in timber & brush, approx. 348 ft. S.88°W. of N1/4 Sec. 1, T22-10W, see below.

North 1/4 Corner to Section 1 only, T22-10W. 22

Found - 1919 GLO Brass Cap, in place, pipe badly rusted.

Orig. 8", now 22" Fir, alive, S.11°E. 29.0 ft., shows good scar.

Orig. 8", now 10" Fir, decayed remains of stump only, S.35°W.

26.4 ft., find partial old blaze & reverse scribe in stump.

Set - Brass Cap at Cor.Mkd: County Surveyor's T 21 S R10W 1/4 S 1  
Office, 1968 T 22 S

New BT's: 18" D.Fir S. 60° E. 25.8 ft. mkd. "1/4 S1 CS BT".

14" Alder S. 49° W. 18.1 ft. mkd. "1/4 S1 CS BT".

Deposit old corner pipe & brass cap alongside. This corner lies on moderate southerly slope approx. 348 ft. N.88°E. of S.1/4 Sec. 36, 21-10, above.  
6/10/68

East 2 1/4 Corner to Section 25, T21-11W. 23

Found - Concrete-filled I.P. in place. - No trace GLO Brass Cap.

Orig. 6", now 22" Fir, alive, S.40°W. 21.1 ft., shows good scar.

We do not open. Rescribed "1/4 S25 CS BT".

Orig. 14", now 22" Fir, down, N.37°W. 17.2 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R11W 1/4 S25 R10W  
Office, 1968

New BT: 24" D.Fir N. 52° W. 43.8 ft. mkd. "1/4 S25 CS BT".

Note - This corner lies 47.2 ft. S. of the W1/4 Cor. Sec. 30 on very steep N.E. slope & approx. 43 ft. S. of top of spur sloping NE.  
7/18/68

West 1/4 Corner Section 30, T21-10W. 24

Found 1919 GLO Brass Cap, broken off, concrete-filled I.P. in place.

Orig. 16", now 30" Fir, alive, N.44°E. 21.1 ft., shows good scar.

We do not open. Rescribe "1/4 S30 CS BT".

Orig. 14", now 24" Fir, alive, S.38°E. 29.7 ft., shows good scar.

We do not open. Rescribe "1/4 S30 BT CS".

Set - Brass Cap at Cor. Mkd: County Surveyor's T21S R11W 1/4 S 30 R10W  
Office, 1968

No new tree marked, none close.

Note - This corner lies about 132 ft. S. of small creek, course SE on very steep N.E. slope. The E1/4 Cor. Sec. 25 bears S. 47.2 ft., record 49.5 ft.

West 1/4 Corner Section 19, T21-10W. 25

Found - 1919 GLO Brass Cap, broken off of concrete-filled I.P. in place.

16", now 34" Fir, alive, N.31°E. 29.7 ft., shows good scar.

We do not open. Rescribe "1/4 S19 CS BT".

18", now 32" Fir, alive, S. 11° E. 77.9 ft., shows good scar.

We do not open. Rescribe

Set - Brass Cap at Cor. Mkd: County Surveyor's T21S R11W 1/4 S 19 R10W  
(Deposit old pipe alongsd.) Office, 1968

New BT: 20" D.Fir N.75°E. 63.8 ft. mkd. "1/4 S19 CSBT. No other trees close.

This cor. lies on very steep S.slope 16' N. of small creek course E., across creek there is mouth of small ravine.

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
June & July, 1968  
C. S. File No. 54/1