

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 10 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

26

Section Corner to Sections 28 and 27 only. *North*
Found - Corner Stone, broken in half with 3 chiseled notched on East edge, Stone in place.
Orig. 14", now 28" Fir, alive, S. 64° W. 20.5 ft. shows good scar #127
We do not open. Rescribe "T21S R10W S28 CS BT."
Orig. Alder to S.E. gone, hole where it stood fits bear. & dist.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 10 W
(Deposit Cor. Stones at Office, 1968 S 28 | S 27
Base of Brass Cap)
New BT: 14" D. Fir S. 3° E. 16.2 ft. mkd. T21S R10W S27 CS BT.
Note - This corner lies on very steep N.W. slope about 75' W. of station 33 * 79 on USFS "L" Line for road, not yet constructed.

27

Section Corner to Sections 21 and 22 only.
Found - 1919 GLO Brass Cap properly marked & firmly set, pipe badly rusted.
Orig. 10", now 12" Fir Snag, N. 30° E. (Rec. N20E) 10.6 ft., most of blaze rotted away, possible scribe visible.
Orig. 20", now 28" Fir, alive, N. 29° W. 19.1 ft., shows very good scar.
We do not open. Rescribe "T21S R10W S21 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 10 W
(Deposit old corner material alongside Office, 1968 S 21 | S 22)
New BT: 20" D. Fir N. 57° E. 29.3 ft. mkd. T21S R10W S22 CS BT.
Note - This corner lies about 155 ft. E. of top of ridge, course NE - SW. Record distance is 297 ft. E. of corner of Sections 27 & 28 (above)

28

1/4 Corner to Sections 35 and 36.
Found - 1919 GLO Brass Cap, broken off from concrete filled pipe, still in place.
Orig. 16", now 24" Fir, alive, N. 6° E. 6.6 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R 10 W
(Deposit old corner material alongside Office, 1968 1/4 S 35 | S 36)
New BT's: 18" D. Fir N. 34 1/2° W. 33.1 ft. mkd. "1/4 S35 CS BT".
15" D. Fir S. 27° E. 32.3 ft. mkd. "1/4 S36 CS BT".
This corner lies on steep S.W. slope 1 chain S. of small spur, SW.

29

1/4 Corner to Section 33 only, T21-10W.
Found - Concrete-filled I.P. at corner point, broken off & brass cap on ground alongside.
Orig. 5", now 10" Fir, alive, N. 23° E. 18.5 ft., good scar.
We Rescribe above old scar, "1/4 S33 CS BT".
Orig. 8", now 14" Fir, alive, N. 76° W. 15.2 ft., good scar.
We Rescribe above old scar, "1/4 S33 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R10W 1/4 S 33
Office, 1968 T 22 S
This corner lies 25 ft. W. of rock spur, sloping S. 40° W. on steep W. slope.

30

North 1/4 Corner to Section 4 only, T22-10W.
Found - Concrete-filled I. Pipe & Brass Cap, broken off.
No trace of Cherrywood around location of S.W. O.B.T.
Call on spur ridge to west fits good.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R10W 1/4 S 4
Office, 1968 T 22 S
New BT's: 15" D. Fir S. 87° E. 18.5 ft. mkd. "1/4 S4 CS BT".
32" D. Fir S. 22° W. 16.5 ft. mkd. "1/4 S4 CS BT".
This corner lies about 160 ft. E. of spur, ridge, sloping S.

31

Section Corner Thus: S 36 / S 31 9W T20S
R10W S 1 / T21S
Found - GLO Brass Cap properly marked in 1951
16", now 17" Cedar, N. 66 1/2° E. 17.2 ft., shows good scar.
16", now 19" Cedar N. 57° W. 34.3 ft., scribe visible, "S".
New BT: 24" Maple S. 24° E. 29.8 ft. mkd: "T21S R10W S1 CS BT".
Also tagged other Bearing Trees.

9/30/69

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July, 1968
C. S. File No. 54/1

SEPT. 68

John M.
Powell & Crew
Sept, 1969
C. S. File
No.
53/66