

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

38

S. W. Corner Section 19, T21-9W.  
Corner obliterated by slide from the newly constructed road.  
Found - Orig. BT. 1894 Survey by Alonzo Gesner who re-established  
Sec. Cor. from this BT: 34" Fir bears N.49°45'W. for  
72 lks. to face of tree. Find axe marks & a grown-over face.  
Set - 1/2" x 18" reinforcing rod 8" into solid sandstone on West,  
facing slope.  
Marked: 30" Fir bears N. 45° 00' W. for 84 ft. to centerline.  
(Tree faced and scrbd. "Sec. Cor.")  
36" Fir bears N.9°00'E. for 62 ft. to centerline tree.  
(Tree faced and scribed "Sec. 19 Cor.")

12/30/71

C. Wylie Smith III  
For. B. L. M.  
C.S. File No. 55/230

39

EAST 1/4 Corner, Section 25 only.  
Found - 1919 GLO Brass Cap. at 1/4 Corner  
16" Hemlock, now down, S.20°W., 35.0 ft.  
12" D. Fir, now 39", N.65°W., 33.0 ft. Shows good scar.  
New BT - 8" Hemlock, N.44°W., 34.8 ft. scribed 1/4 S25 CS BT.

3/28/73

John M. Powell  
J. Heritage  
C. S. File 56/25  
March 28, 1973

40

WEST 1/4 Corner, Section 30 only, T.21-9.  
Found - 1919 GLO Brass Cap, broken off.  
34" D. Fir, now stump, N.75 1/2°E., 21.8 ft. Shows good scar.  
58" D. Fir, now down, S.20°E., 17.8 ft. shows scar.

Set - Brass cap along side old pipe mkd. County Surveyors  
Office T 21 S  
1973 R 10 1/4 | S30 9  
W W

New BT's - 7" D. Fir, N.60°E., 5.0 ft. Scribed 1/4 S30 CS BT.  
22" Hemlock, S.62°W., 25.0 ft. scribed 1/4 CS BT.  
Note - There were no other good trees to the east for BT's. Old  
Logged unit. BT tag mkd. for 1/4 S30 only on SW BT.

3/28/73

41

Sec. Corner between sec.1 and 2 (North)  
Found: U.S. GLO Brass cap leaning to south after apparent bulldozer damage  
properly marked.  
BT's- no identifiable trace of the SE 1919 BT. The rotting remains of the  
SW 1919 Bt are in their record position with reference to the 1951  
resurvey. This tree is now down and any identifying marks are buried.  
The southeast BT marked in 1951 is down, bearing S42 3/4°E., 23.1 ft.,  
with scribing visible on an unhealed blaze.

We reset the Brass cap and the remains of the 1919 Iron post in the proper  
position and add the following markings to the brass cap. "CS 1975"

New BT's- A 28" Hemlock bears S53°E., 41.7 ft., scribed "T21S R10W S1 CS BT"  
on a double blaze.  
A 17" D. Fir bears S22°W., 35.5 ft, scribed "T21S R10W S2 CS BT"  
on a double blaze .

Note: The SW Cor. Sec. 36 T20S R10W, a Brass cap bears N89°15'W., 86.5 ft.  
This corner is located on a ridgetop near the SW Corner of a clearcut unit.  
Compass Declination Setting: 20° East. 11/12/75

Gary L Langlitz  
Clell E Goodwin  
A Vic. Cangie  
N. Lenora Ladig  
CS 57/39  
11/12/75

1/4 Corner of sec. 2 and sec. 1

Found: Remains of 1" concrete filled I.P. with brass cap (1919) stamped 1/4  
S2 | S1

From Which: A orig. 24" now 26" alder BT bears N24°W., 23.8ft. nothing remains  
of the orig. NE BT.

Set. - Brass cap on a 1 1/2" X 30" I.P. Stamped. T 21 S R 10 W  
DOUGLAS CO. SURVEYOR 1/4 S2 | S1  
1975

We place the remains of old pipe beside corner  
BT's A 22" Hemlock scribed "1/4 S2 CSBT" in single blaze bears S75 1/2°W., 47.4 ft.  
A 12" Hemlock scribed "1/4 S1 CSBT" in a double blaze bears N49°E., 50.3 ft.  
Compass declination 20° East 11/13/75

11/13/75

RE-NEWED SEE CORNER NO # 54