

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 sec. cor. for sections 9 and 10

Found - A 1" diam. iron pipe filled with concrete, rusted and broken off  
4" above ground with brass cap laying along side stamped.

1/4 S 9  
S 10  
1918

A rotted fir snag, 50" now 62" diam., bears N. 82° W., 64.7 ft. with  
no remaining evidence of blaze.

A 30" diam., alder bears N. 6° E., 34.1 ft. (Record, N.6°W., 32.6 ft.)  
barked scribed "1/4 BT"

Set - A 1 in. x 30 in. iron pipe with brass cap set 8 ins. above ground,  
stamped "

COUNTY SURVEYOR OFFICE

T 21 S

1/4

s 9 S 10

1977

Placed orig. B. C. at ground level on North edge of cap. Set orig.  
broken I.P. on South edge of brass cap.

New B.O. A 5/8" rebar with alum. cap set 6 ins. above ground, stamped "B.O. No. 1"  
bears S. 35° W., 10.0 ft.

New BT. A 28" diam. alder bears N. 61" W., 43.7 ft. bark scribed "1/4 S9 CS BT."

48 Rod Kimberling  
Peter Earle  
D.C.S.O.  
C.S. 59/40  
9-13-77

9-31-77

Section corner for Secs. 5 and 6; and Secs. 31 and 32 of T20-10

Set - 1 1/2" x 36" pipe post with brass cap.

BT's - 28" D. Fir bears S.43°20'E., 84.4 ft.

16" R. Cedar bears N.7°W., 28.6 ft.

49

Forrest Hales  
For: International  
Paper  
April 1979  
M 76 - 55

4/79

Section corner for Secs. 1 and 12 only.

Found - 1919 GLO brass cap properly marked, found disturbed, a 1 1/2"  
iron pipe filled with concrete, leaning with upper 1 foot with  
attached brass cap rusted off and laying along side monument.  
This monument is located in an area where old cat work has dis-  
lodged boulders and caused the ground to shift and slide.

A D. fir, 36" now 48" bears N.10°W., 24.4 ft. (measured 24.6 ft.  
at -8° slope). The 1919 record shows tree bearing N.10°W.,  
43 links or 28.4 ft. We partially open well healed blaze and  
find scribing S 1 B",

A dead leaning Fir snag with approx. 10 ft. of bottom covered by  
slide. We are not able to determine the center of the base of the tree  
nor can we locate a blaze or scribing. The tree has a BLM bearing  
tree tag indicating that it bears S.33°W., 42.9 ft. Powell  
indicated that the tree fit record bearing and distance and that  
it was located on top of ridge and would be taken out by new road  
in his renewal #32. We find the tree to bear S.74 1/2°W., 43.7 ft  
and 43 ft. north of the ridge and 31 ft. lower than ridge. All  
bearings and distances taken to portion of tree visible above  
slide material.

A D. fir 17" now 24" bears N.57 3/4°E., 30.3 ft. (Rec. N.59 1/2°E.,  
40.2') Tree has well healed blaze.

Set - This monument is to be destroyed by a logging landing construction  
As the monument has been disturbed we set a PK nail in stone at  
the record bearing and distance of the true corner position from  
the 1919 36" now 48" D. fir bearing N.10°W., 28.4 ft. as described.  
from which the disturbed 1919 monument bears N.8°W., 4.0 ft.

New Accessories:

As the construction will destroy the corner monument and any nearby  
accessories, we reference the PK nail at the true corner position  
as recorded above, bears S.60°E., 436.79 ft. PK nail set in  
30" dia. Spruce stump.

Set boat spike in rock bears S.57 1/4°W., 172.10 ft. scribed  
"B O 2"

9/20/79

#55  
Larry Monrean  
Douglas Co. Surveyors Office  
P. Earle  
Frank Silagy  
Sept. 20, 1979  
C.S. 60/34