

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 21

T. S.

R 10

R.W.W.M.

KONE-CHAPMAN CO., EUGENE, ORE. 21881

51

East 1/4 Corner for Section 1 only.

Found - 3/4" inside diam. concrete filled iron pipe badly rusted with brass cap stamped "1/4 S1 1919. Monument is broken into 3 pieces with lower portion remaining firmly set, protruding 3" above ground.

1919 BT, a 14" D. Fir now a 30" stump 36" high bears S.67°W., 22.1 ft. (Rec. dist. 23.1 ft. checks on slope measurement). We open portion of blaze and find scribing "1/4".

1919 BT, an 11" D. Fir now a 14" stump 14" high bears N.78°W., 13.8 ft. (Rec. N.10°W., 14.5 ft.) We open blaze and find scribing "BT". The only logical determination we can make at this time is that the compass bearing of N.80°W., (being 10° off of cardinal west) was possibly misread. As the stump is leaning, a bearing of N.80°W., and a distance of 14.5 ft. would be a reasonable course to center of tree at blaze height. The blaze and scribing faces monument position. No evidence of tree was found at record bearing and distance.

Set - A 1" x 30" iron pipe with attached brass cap stamped "Douglas County Surveyor" T21S R10W S1 1/4 1981 is set at corner position. Monument is set with cap 4" above ground. Placed pieces of old monument along north and south side underground.

New Accessories:

Set boat spike stamped "BO 1" in pitch ring of 30" D. Fir stump bears S.67°W., 23.2 ft. (1919 BT)

Set boat spike stamped "BO 2" in pitch ring of 14" D. Fir stump bears N.78°W., 14.1 ft. (1919 BT)

Set boat spike stamped "BO 3" in pitch ring of 16" diam. 16" High D. Fir stump bears N.48°W., 19.0 ft.

A D. Fir 14" double blazed and scribed "1/4 S1 CS BT" bears N.15°W., 26.9 ft.

All bearing objects tagged. Corner lies about 25 ft. south of cutting line running along ridgetop E-W.

4/2/81

1/4 Corner for Sections 1 and 12.

Found - A properly mkd. 1919 US GLO brass cap on a rusted & broken 1" diam I.P. which is firmly set & protruding 10" above the ground. Brass cap fell loose from the iron pipe during the investigation of the accessories.

The Orig. 30" Fir northeast bearing tree is now a nearly obliterated stump hole agreeing well in location with original record bearing and distance.

An orig. cedar, 18" now a 20" DBH cedar, bears S.80°W., 19.8 ft. & has an opened blaze with no scribing visible.

From 1957 resurvey, A fir, 70" now a fir stump 30" tall & 72" diam. bears N.63°E., 40.3 ft. Tree has good evidence of a blaze.

A fir, 52" now a 55" D. fir, DBH, bears S.41°E., 75.2 ft. Tree has a well healed & clearly identifiable double blaze.

Set - Found monument location is accepted, referenced out & then removed. In referenced location, is placed a standard DCSO 2 1/2" brass cap on a 1" x 30" I.P. marked COUNTY SURVEYORS OFFICE T21S 1/4 S1 S12 R10W 1981". New cap is firmly set and protrudes 9" above ground.

New BT's- A 10" DBH Hemlock bears S.62 1/2°E., 28.1 ft. and is scribed 1/4 S12 CS BT on a double blaze. Tree also has an injury scar approx. 12" long and 36" above the ground on its north face.

All trees are tagged with DCSO BT tags.

4/2/81

52

Stephen J. Flause  
Deputy, Doug. Co.  
Surveyors Office  
Karen Mosely  
April 2, 1981  
C.S. 61/19

U.S.F.S.  
Ernesto R. Alvarado  
Deputy, Douglas  
County Surveyor  
Colin Long, Survey  
Tech., witness.  
August 21, 1981  
C.S. 61 / 27

Sec. corner for Sec's. 1, 2, 11, & 12.

Found - Douglas County B. C. in good condition marked: T21S  
S2 | S1  
S11 | S12  
(1919 Orig.)  
BT's - 12" rotted Alder stump bears N.40°E., 8.4-ft., R10W  
no scribing. Ren.#3. 1967

Rotted Hemlock stump with broken snag lying 5' down the hill with scribing: T21S R10W S 1 CS BT bears N12°E., 14.9-ft.

12" rotted Hemlock stump bears S.79°E., 25.4-ft., Ren.#3.

No trace of 1919 NW, SE, & SW BT's.

No trace of 1967 NW & SW BT's.

( Continued )

53