

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 11 R. W. W. M.

KOBE-CHAPMAN CO., SURVEY. OFF. - SURE

Richard Hintz
For: International
Paper Co.
M 62-1 9/76

1/4 Corner for Secs. 18 and 19
Found - 1 1/4" Iron pipe Ren. #12
New B.O.- Utility pde, 10C bears N.2°W., 42.8 ft.
22
FO. OK. 11/6/78 K. Reed ce. Surv. Off. C.S. 60/17

115

Larry E. Monrean
Doug. Co. Surveyors
Office
Karen Reed
Earle
S. Flause
F. Silagy
Nov. 15, 1978
C.S. 60/17

Section corner for 18 and 19; and Secs. 13 & 24 of T.21-12
Found - An iron pipe 2 inches diam. 17 inches high set by F.C. Frear
in 1940. Ren. #3.
A 7" now 8" Fir, is tipped out, bears S.70 3/4° E., 7.4 ft.. Tree
partially rotted. scribing visible "19 BT". Ren. #3
An 8" Fir now a 10 foot high stump, bears N.49 1/2°W., 18.2 ft.
Tree partially rotted, has healed over blaze. Ren. #3
A Fir, 10" now 12", bears N.44°E., 21.8 ft. Has healed blaze.
A 16" now 21" D. Fir bears S.8°W., 8.4 ft. Has well healed
blaze. Ren. #32
A 14" now 18" D. Fir bears S.60°E., 24.7 ft. Has well healed
blaze. Ren. #32.
A 13" now 18" D. Fir bears N.72 1/2°E., (Rec. N.77°E.) 26.6 ft.
(Rec. 27.2 ft.) Ren. #32
A 12" now 14" Hemlock, bears N.67°W., 26.4 ft. Tree has partially
healed blaze. Ren. #60.
No new monument or accessories set.
SE OK. 119A, C. Mullins Hills 62 11/15/78

116

Richard Hintz
For: International
Paper Company
June 1979
M 70 - 74

1/4 Corner for Secs. 20 and 29
Set - 1 1/4" Iron pipe with brass cap
BT's - 22" Cedar bears N.13°E., 44.1 ft. scribed.
42" Cedar stump bears S.56°30'W., 13.2 ft. to a 50d nail in face;
scribed.

117

Center 1/4 for Section 29
Set - 1 1/4" Iron pipe with brass cap
BT's - 40" Fir bears N.22°00'E., 47.6 ft. scribed.
28" Maple bears N.73°30'E., 58.1 ft. scribed.

118

Corner for Secs. 29 and 28 only
Found - Orig. Red Cedar BT now 34", bears N.10°E., 23.1 ft. Face
open with brass washer "No. 238 Haines".
Set - 5/8" Iron rod
New BT - 44" Hemlock bears N.16°W., 55.2 ft.

119

Closing Corner for Secs. 31 and 32.
Set - 5/8" Iron rod in mound of sandstone
From which:
50" Maple bears S.3°E., 82.9 ft.
8" Alder bears S.39°E., 28.2 ft.
20" W. Fir bears N.32°30'W., 297.4 ft.

120

1/4 Corner for Secs. 31 and 32.
Set - 5/8" Iron rod
From which:
28" D. Fir bears S.82°W., 5.4 ft.
40" D. Fir bears S.61°E., 15.3 ft.

122

Meander corner Sections 31 and 32.
Set - 5/8" Iron rod
From which:
14" D. Fir bears S.55°W., 16.8ft.
12" D. Fir bears N.87°E., 40.7 ft.

Ronald Stuntzner
For: Moore Mill and Lumber Co.
June 20, 1979
M 78 - 79

RE-RENEWED SEE CORNER NO. #163
RE-RENEWED SEE CORNER NO. #188
RE-RENEWED SEE CORNER NO. #196
RE-RENEWED SEE CORNER NO. #197