

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S.T. S. R. 11 W. R.W.W.M.

MOORE, CHAPMAN CO., EUGENE, ORE. 97401

John C. Bentley
For: I.P. Timberlands Operating Co., Ltd.
Feb. 1995 M121 - 68

Closing Township Corner Amended (NW Cor. Sec. 6) 239
Set - 2" Brass cap on 2" iron pipe for amended closing corner. Cap
is stamped "T20S R11W S31 CC S6 T21S T21S S1 R12W 1995
LS 2656"
New BTs-12" Alder, N.71°E., 27.7 ft. bark scribed "T20S R11W S31CC BT"
18" Hemlock, S.39°W., 45.3 ft. scribed "S1 BT"
8" Spruce, N.84°W., 28.3 ft. chopped "X"
County Surveyor's Brass Cap per C.S. file 54/1 bears
N.89°29'E., 4.97 ft.

1/4 Corner for Section 6 and Section 31 T.20-11 240
Found - 2½" dia. County Surveyor's Office brass cap on a 1½" iron
pipe, 8" above ground. (C.S. 59/40) See renewal # 105.
24" D.Fir, S.19°W., 29.4 ft. Healed face. (rec. S.18°W.,
29.8 ft.)
19" D.Fir, N.31°W., 18.6 ft. Healed face. (rec. 18.3 ft.)
New BTs-
25" D.Fir, N.52°E., 26.2 ft. scribed "¼ S31 BT"
19" D.Fir, S.78°E., 67.9 ft. scribed "¼ S6 BT"

Original closing Township Corner (NW Cor. Sec. 6) 241
Found - 2½" Douglas County Surveyor's Office brass cap on a 1½" iron
pipe. (C.S. 54/1) See renewal # 37.
20" Fir stump, N.6°E., 20.4 ft. (rec. 21.1 ft.)
32" Fir stump, S.19°E., 6.7 ft. (rec. S.20°E., 6.3 ft.)
Uprooted Fir stump, N.43°W., 18.0 ft. to root hole. (rec.
20.5 ft.)
New BTs -
14" Spruce, S.20°E., 34.5 ft. scribed "T21S R11W S6 CC BT"
13" Alder, N.44°W., 2.5 ft. bark scribed "S1 BT"

Original Township Corner (NE Corner Sec. 1, T.21-12) 242
Found - 2½" aluminum pipe (set by Durham in 1964) Menasha records.
BTs per C.S. 54/1 - See renewal # 38.
30" Fir snag, S.88°W., 41.6 ft. (rec. S85°W., 40.9 ft.)
22" Hemlock stump, N.15°E. 29.8 ft. (rec. N.15°½'E. 30.1')
38" Fir stump, N.48°W., 42.2 ft. very rotten (rec. 40.1 ft.)
Rotten Fir stump, N.5°E., 30.7 ft. scribing visible (rec.
N.5½°E., 28.4 ft.)
New BTs -
9" D.Fir, N.39°E., 16.5 ft. scribed "S31 BT"
11" Alder, S.19°E., 20.9 ft. bark scribed "S31 BT"
8" Alder, S.61°W., 21.0 ft. bark scribed "T21S R12W S1 BT"
14" Alder, N.14°W., 10.1 ft. bark scribed "T20S R12W S36 BT"

1/4 Corner for Section 6 and Section 1 T.21-12 243
Found - 2½" brass cap on a 2½" iron pipe (C.S. 58/140 N)
BTs found per C.S. 58/140 N - See renewal # 130.
15" D.Fir, N.24°W., 11.0 ft. Healed blaze. (rec. N.25°W.)
Fir windfall, S.31°E., 48.5 ft. (rec. S.31°30'E., 45.2 ft.)
New BTs -
12" Hemlock, N.61°E., 11.7 ft. scribed "¼ S6 BT"
14" D.Fir, S.26°E., 27.9 ft. scribed "¼ S6 BT"
16" D.Fir, S.62°W., 11.7 ft. scribed "¼ S1 BT"
Fence post 1 ft. north of corner.

244