

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

FOR - Douglas County  
James W. Byron, Doug. Co. Surv.  
Wernon "Ray" Tracy - J. Heritage - E. West  
June 29 - 30, 1967  
C.S. File No. 54/47 Map M 33 - 18

1/4 Corner to Sections 4 and 9. 430  
Found - No trace of Original corner nor BT's.  
From Hub #77 we go N.78°52'40"E. 35.25 ft., the proportional point  
for 1/4 corner as shown in sketch in field notes in file.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S 1/4 S 4 R11W  
Office, 1967 S 9  
New BT's: 9" Spruce N. 56° W. 11.3 ft. mkd. 1/4 S 4 CS BT.  
7" Alder S. 45° W. 23.4 ft. mkd. 1/4 S 9 CS BT.  
Note - This corner lies 10 ft. W. of 2 ft. wide creek, course SE. and  
20 ft. N.W. of fork in creeks, course West.

Section Corner to Sections 4 - 5 - 8 - 9. 44  
Found - Orig. BT's., as follows, with ring count indicating they were  
mkd. about time Thiel was here in 1891. Scribe appears same  
as found in other parts of county by Thiel.  
12" Spruce Stump, S. 67° E. 8.6 ft., unrecorded "9BT" and  
fragmentary scribe.  
22" Fir Stump S. 87° W. 3.0 ft., unrecorded "S8" scribe on log  
that was cut from stump.  
46" Fir Stump N. 37° W. 35.3 ft., unrecorded "T21S R11W S5 BT" scribe.  
40" Fir Stump N. 33° E. 42.2 ft., unrecorded "T21S R11W S4 BT" scribe.  
50" Fir Stump S. 70° W. 13.2 ft., no scribe, possible original  
BT. by Meldrum.  
Possible Stump Holes for SE. & NW. Orig. BT. locations.  
Call on creek to west & ridge top to north fit very well.

Set - Brass Cap at Cor. Mkd: County Surveyor's T21S S 5 | S 4 R11W  
Office, 1967 S 8 | S 9  
New BT's: 9" D. Fir S. 17° E. 16.4 ft. mkd. T21S R11W S9 CS BT.  
18" D. Fir S. 41° W. 11.6 ft. mkd. T21S R11W S8 CS BT.  
15" D. Fir N. 87° W. 25.5 ft. mkd. T21S R11W S5 CS BT.  
14" D. Fir N. 52 1/2° E. 37.7 ft. mkd. T21S R11W S4 CS BT.  
Note - This corner lies on moderate S. slope 22 1/2 ft. E. of creek,  
2 ft. wide, course south.

South 1/16 Corner of Sections 4 and 5. 45  
From Hub #113 we go N. 75°25'10"W. 18.15 ft. to proportional point  
for the south 1/16 corner to sections 4 and 5, see sketch in file.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T21S R11W  
Office, 1967 S 1/16 S 5/S 4  
New BT's: 24" Cedar N. 11° E. 17.2 ft. mkd. S 1/16 S 4 CS BT.  
17" D. Fir N. 23° W. 10.1 ft. mkd. S 1/16 S 5 CS BT.  
Note - This corner lies on top of spur ridge, sloping north.

East 1/16 Corner of Sections 5 and 8. 46  
From Hub #217, we go N.35°32'20"W. 33.49 ft. to the proportional point  
for the E. 1/16 corner of sections 5 and 8, see sketch in file.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T21S S 5 R11W  
E 1/16 S 8  
New BT's: 6" D. Fir S. 8° E. 6.8 ft. mkd. E 1/16 S 8 CS BT.  
14" D. Fir N. 50° E. 14.1 ft. mkd. E 1/16 S 5 CS BT.  
Note - This corner lies on moderate southerly slope.

1/4 Corner to Sections 5 and 8. 47  
Found - No trace of orig. corner nor BT's:  
From Hub #20, we go N.78°50'40"W., 235.40 ft. to proportional point of  
the 1/4 corner of sections 5 & 8, see sketch in file.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T21S 1/4 S 5 R11W  
Office, 1967 S 8  
New BT's: 18" Maple S. 21° E. 57.8 ft. mkd. 1/4 S 8 CS BT.  
10" Db. Cedar (most westerly) N. 23° E. 46.7 ft. mkd. 1/4 S 5 CS BT.  
This corner lies 10 ft. north of E-W fence extended & creek call to  
East side good.

RE-NEWED  
OK 4/27/77 R. KIMBERLING Co. Surveyor's Office - c.s. 59/34