

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE., 91881

48

1/4 Corner to Sections 8 and 9.
From Hub #52-A, we go N.41°42'50"W. 56.0 ft. to proportional
point for 1/4 corner of Sections 8 & 9, See sketch in file.
Set - Brass Cap at Corner Mcd: County Surveyor's T21S R11W #199
Office, 1967
From our corner, a 40" Fir Stump N. 28° E. 9.0 ft., no scribe
found. This is remains of tree called for in Forest App.
notes, 1954, by Fred Stroup.
No trace of N.W. Original BT.
New d BT's: 5" Hemlock N. 8° W. 103.3 ft. mkd. 1/4 S 8 CS BT.
4" Alder N. 25° E. 42.2 ft. mkd. 1/4 S 9 CS BT.
This corner lies on top of spur ridge, course west.

James W.
Byron &
V. Tracy &
Crew
June, 1967
C.S. File
No. 54/47
M 33-18

RE-ENTERED SEE CORNER NO. #199

49

W. 1/16 corner to Sections 21 and 28.
Set - 5/8" Steel Rod, from which:
Bearing Tree: 30" Fir S. 13° W. 11.8 ft.

SEE ALSO -
HINTS CORNER
12/83 M 95-57

Wilford N.
Haines
for L. & H. Lbr.
July, 1967
M 34 = 30

50

East 1/16 to Sections 8 and 17.
This corner set from 38 of traverse line. Back sight 39 &
turned 78° 12' chaining out 119.31. Computed angle should
have been 79° 12' by using the tangent of 1° 06' s
Set - Brass Cap at the East 1/16 Corner Mkd:
County Surveyors T21S R11W
Office S 8 E 1/16
1967 S 17
New BT's: 38" D. Fir N. 32° E. 69.5 ft. mkd. S8 E1/16 CS BT.
6" Maple S. 2° E. 46.8 ft. mkd. S17 E1/16 CS BT.

James W.
Byron &
J. Powell &
Crew
July, 1967
C.S. File
No. 54/47

MICROFILM TO HERE 10/67

51

TOWNSHIP CORNER - Twps. 20 & 21 S., R's. 10 & 11 W. FDOK REC
Found - 3/4" I. Pipe & BT's. as called for in Ren. #25 T20-11W. M109-15
20", now 28" Maple, alive, N.14°W. 15.2 ft. shows good scar. Do not open.
10", now 16" Maple, alive, S.27°W. 11.2 ft., shows good scar. Do not open.
4", now 20" Fir, alive, S.77 1/2° E. 42.9 ft. faint scar
Rescribed: "T21S R11W 1/4 S 36 CS BT" #234 R
Set - Brass Cap at Corner Mcd: County Surveyor's T20S R10W S 36 S 31 10
Office, 1968
Note - This corner lies on very steep S. slope about 300 ft. north of
Smith River Road. Deposit old corner pipe alongside brass cap.
3/27/68

STONTZNER
OCT 1989
C. S.
File
No.
53/66

52

East 1/4 Corner to Section 25, T21-11W.
Found - Concrete-filled I.P. in place but no trace GLO Brass Cap.
Orig. 6", now 22" Fir, alive, S.40°W. 21.1 ft., shows good scar.
We do not open. Rescribe "1/4 S25 CS BT".
Orig. 14", now 22" Fir, down, N.37°W. 17.2 ft., shows good scar.
Set - Brass Cap at Cor. Mcd: County Surveyor's T21S R11W 1/4 S25 R10W
Office, 1968
New BT: 24" D. Fir N. 52° W. 43.8 ft. mkd. 1/4 S25 CS BT.
This corner lies 47.2 ft. S. of the W 1/4 Sec. 30 on very steep NE slope,
approx. 43 ft. S. of top of spur sloping NE.
7/18/68

Verma "Ray" Tracy
Jack Heritage & V. Perron
July 18, 1968
C. S. File No. 54/1

53

West 1/4 Corner Section 30, T21-10W.
Found - 1919 GLO Brass Cap, broken off. Concrete-filled I.P. in place.
Orig. 16", now 30" Fir, alive, N.44°E. 21.1 ft., shows good scar.
We do not open. Rescribe "1/4 S30 CS BT".
Orig. 14", now 24" Fir, alive, S.38°E. 29.7 ft., shows good scar.
We do not open. Rescribe "1/4 S30 CS BT".
Set - Brass Cap at Cor. Mcd: County Surveyor's T21S R11W 1/4 S 30 R10W
Office, 1968
No new trees marked, none close.
This corner lies about 132 ft. S. of small creek, course SE on very
steep NE slope. The E 1/4 Sec. 25 bears S.47.2 ft., record 49.5 ft.
7/18/68