

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

XERO-CHAPMAN CO. KUSHER, ONE, 2181

V. Tracy &  
Crew  
C.S.  
File  
No.  
54/1

West  $\frac{1}{4}$  Corner Section 19, T21-10W. 54  
Found - 1919 GLO Brass Cap, broken off concrete-filled I.P., in place.  
16", now 34" Fir, alive, N.31°E. 29.7 ft., shows good scar.  
We do not open. Rescribe " $\frac{1}{4}$ " S19 CS BT".  
18", now 32" Fir, alive, S.11°E. 77.9 ft., shows good scar. Do not open.  
Set - Brass Cap at Cor. Mkd: County Surveyor/s T21S R11W  $\frac{1}{4}$  S 19 R10W  
(Deposit Old pipe along) Office, 1968  
New BT: 20" D. Fir N.75°E. 63.8 ft. mkd.  $\frac{1}{4}$  S19 CS BT. No other trees close.  
This corner lies on very steep S/slope 16 ft. N. of small crk, course E.,  
Across creek there is mouth of small ravine.

7/18/68

Ronald E. Stuntener  
Timberland Services, Inc.  
Jan. 23, 1969 - Fax/Misc/Rel. & Loc.  
C. S. File No. 55/103

$\frac{1}{4}$  Corner to Sec. 33, T20-11W and Sec. 4, T21-11W. 55  
Set by proportionate measurement. The  $\frac{1}{4}$  corner had been  
searched for but not found.

Set - 1" Iron Pipe  
Bark Scribed 32" Fir N. 50° W. 1.8 feet.  
Scribed 42" Fir N. 82° E. 9.5 feet.  
This corner is approx. 390 ft. east of the Noel Creek Road  
on a spur ridge.

East  $\frac{1}{16}$  Corner between Sec. 33, T20-11W & Sec. 4, T21-11W. 56

Set - 1" Iron Pipe  
Scribed 30" Hemlock N.15° 45' E. 30.3 feet.  
Scribed 24" Cedar S. 49° W. 7.5 feet.  
This corner is approx. 50 ft. west of a long spur ridge, running N-S.

J.W. Byron  
Sept. 1959  
C.S. 49/186  
N-15-63

Renew  $\frac{1}{4}$  cor. sec. 17 and 16. 57  
Found - Both BT's as recorded by Frear, barked scribed  $\frac{1}{4}$  S BT. See Ren. #6.  
Set - Brass cap at cor. mkd: County Surveyors Office 1959.  
I rescribe Frears BT's:  
21" R. Fir N. 48 $\frac{1}{2}$ ° W. 7.8 ft. scribed:  $\frac{1}{4}$  S 17 CS BT.  
17" R. Fir S. 31 $\frac{1}{2}$ ° E. 5.6 ft. scribed:  $\frac{1}{4}$  S 16 CS BT.

9/22/59

Section Corner to Sections 16 - 17 - 20 - 21. 58

Found - Orig. 24", now 48" Hemlock 15' high snag, N.75°W. 20.5 ft. (face)  
scribe marks visible on opened blaze.  
Orig. 36", now 72" Cedar, Alive, N.65°E. 66.0 ft. (face) faint  
scar. We Rescribe "T21S R11W S16 CS BT". Frear's BT., Ren. #4.  
7"?, now 108" Fir alive, S.26 $\frac{1}{2}$ °E. 6.3 ft. (face) "S21" bark scribe.  
We Rescribe "T21S R11W S21 CSBT" (on bark)

Set - Brass Cap at Cor. Mkd: County Surveyor's  
Office  
1970

T 21 S	R 11 W
S 17	S 16
S 20	S 21

New BT's: 30" Hemlock S.33°W. 10.9 ft. mkd: T21S R11W S20 CS BT".  
60" Cedar N.29°W. 33.5 ft. mkd: T21S R11W S17 CS BT".  
No smaller trees available.

This corner lies on very steep, northerly slope.

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
February 1970 C.S. 54/1

Sec. Cor. To Secs. 7 & 18, T21-11W. and Secs. 12 & 13, T21-12W. 59

Found -  $\frac{1}{2}$ " Iron Pipe in poor condition & remains of Orig. BT's.,  
as follows: c.s. 40/169

24", now 36" Hemlock, badly decayed remains of stump, N.23°E.  
10.6 ft., no scribe found.

48", now 50" Spruce, badly decayed stump, N.19°W. 5.9 ft.,  
scribe visible on old blaze.

Other Orig. BT's. would have been destroyed by very old  
logging road, now unusable.

Set - Brass Cap at Cor. Mkd: County Surveyor's  
(Reset old Pipe & old 5/8" Office  
I. Rod found while digging hole) 1970

R	T 21 S	R
12	S 12	S 7
W	S 13	S 18

New BT's: 10" Cedar N.31°E. 26.0 ft. mkd: T21S R11W S7 CS BT.  
12" D. Fir S.53°E. 16.6 ft. mkd: T21S R11W S18 CS BT.  
12" Cedar S.15°W. 5.2 ft. mkd: T21S R12W S13 CS BT.  
12" Cedar N.61°W. 14.3 ft. mkd: T21S R12W S12 CS BT.

This corner lies about 100 ft. N. of slough, course N.W. & 20 ft. No.  
of old logging road, course N.W.

4/3/70

Vernon "Ray" Tracy  
J. Heritage & V. Perron  
April, 1970  
C.S. File 54/100

FD. 1106  
C.S. 63/70  
P. WARD