

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 11 R.W.W.M.

1/4 Corner for Secs. 16 and 17.
Found - 1959 County Surveyors Brass Cap and I.P. Ren. #57
21" Fir, bears N. 48 1/2°W., 7.8 ft. now a stump
cut below scribe.
17" Fir, bears S. 31 1/2°E., 5.6 ft. Now a stump
cut below scribe.
New BT: 24" Fir, bears N. 77 1/2°E., 15.1 ft. scribed
1/4 S 16 BT.

Richard J. Hintz
Nov. 1974
C.S. 58/17

RE-RENEWED SECTION CORNER NO. #160

11/74

Section Corner for Secs. 18, 17, 19 and 20. Ren. #11
Found - 1 1/4" I.P. buried approx. 5" in an open pasture.
42" now 44" Spruce mkd. by Hugill in 1949 bears
N. 27 1/2°E., 74.3 ft. (rec. per C.S. 40/169 is
N. 27 1/2°E., 72.3 ft.) This tree has an unhealed
blaze, we find no scribe mark. We rescribe to
to read "CS BT".
A gate post in an E-W fenceline noted by Hugill
bears N. 52 1/2°W., 139.7 ft.
The white house used by Hugill for a bearing object
is not visible.
New BT: A 24" Spruce bears N. 17°W., 94.6 ft. scribed "T21S
R11W S 18 CS BT".
Note: Compass declination setting: 20° East.

Gary Langlitz
P. Earle
Surveyors Office
C.S. 57/12
Nov. 1974

11/7/74

1/4 Corner for Secs. 18 and 17.
Found - 1 1/4" I. Pipe, firmly set and in good condition. Ren. No. 13
(See survey by H.S. Hugill, C.S. 40/169)
An 8" now 12" Alder marked by Hugill bears S. 18°W., 11.5 ft.
alive and well-healed.
We find no identifiable remains of Hugill's NE bearing tree.
We leave the corner monument intact and mark the following BT:
A 12" Red Cedar, bears S. 75°E., 38.8 ft. scribed "1/4 S17 CS BT".
Compass declination setting: 20° East.

Gary Langlitz,
Surveyors Office
V. Cangie
J. Nordling
1/13/75
C.S. 57/17

1/13/75

1/4 Corner for Secs. 19 and 20.
Set - Iron pipe with brass cap from which:
60" Fir, bears N. 65°W., 16.1 ft. to PK nail in face, scribed 1/4
S 19 BT.
6" Fir, bears N. 42 1/2°E., 14.6 ft. to center scribed 1/4 S. 20 BT.
60" Fir stump, bears N. 16°E., 22.2 ft. to center. Not marked.
3' x 3' Post bears S. 49°W., 3.5 ft.
Corner is approx. 60 ft. West of County Road #195 A.

Richard J. Hintz
For: Douglas County Land Dept.
April 15, 1975
C.S. 58/47

4/15/75

Section corner for Secs. 19, 20, 30 and 29.
Found - 1 1/4" Iron pipe from which: Ren. #10
7" Fir, bears N. 21°E., 3.3 ft. Orig. BT.
14" Cedar, bears N. 1°E., 3.8 ft. to center Scribed S 20 BT.
18" Hemlock, bears S. 14 1/2°W., 26.3 ft. to center. Scribed S 30 BT.
28" Hemlock, bears S. 81 1/2°W., 30.3 ft. to center. Scribed S.
30 BT.
40" Hemlock, bears N. 22 1/4°W., 31.8 ft. to face. Scribed S 19 BT.
Corner is approx 420 ft. South of County Road #195 A.

4/15/75

1/4 Corner to Sections 4 and 9 REN#43
Found 1967 County Surveyor Brass cap properly marked and in good shape.
Old BT's 14" Douglas Fir bears N 55°15'W., 11.6 ft.
New BT's 14" Douglas Fir bears N9°45'E., 23.2 ft. Scribed T21s, R11W, S1/4 S4
14" Douglas Fir bears S9°30'E., 49.7 ft. Scribed T21S, R11W, N1/4 S9
Jan 27 1976

Robert B Ward Jr.
Forest Engineer
U.S. Plywood
Mapleton Or
C.S. 59/2 2/6/76

P.O. OK 4/15/77 G. LANGLITZ Co. SURVEYOR OFFICE
C.S. 59/14