

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 12 R. W. W. M.

Ronald Stuntzner
For: Tahkenitch Tree Farm
August 1994
M120 - 75 A - D; CS 63/145

Section Corner for Sections 1 & 2; 35 & 36 T20-12. 104
Found - 2 1/2" Brass cap properly marked on 2" iron pipe with 1 1/2" iron pipe
lying along side. (C.S. 58/140) See renewal # 62.
Found BTs -
20" Hemlock, with healed face and tag bears S.13°W., 40.2 ft.
(C.S. 58/140)
15" Spruce, with healed face and tag bears N.50°30'W., 53.8 ft.
(C.S. 58/140)
48" Fir stump, bears N.78°E., 1.0 ft. to face (C.S. 58/140)
Bearing Object - An iron fence post bears N.66°E., 1.2 ft.

Closing Township Corner Amended (NW Cor. Sec. 6; T.21-11) 105
Set - 2" Brass cap on 2" iron pipe for amended closing corner. Cap is
stamped "T20S R11W S31 CC S6 T21S T21S S1 R12W 1995 LS 2656"
New BTs-12" Alder, N.71°E., 27.7 ft. bark scribed "T20S R11W S31CC BT"
18" Hemlock, S.39°W., 45.3 ft. scribed "S1 BT"
8" Spruce, N.84°W., 28.3 ft. chopped "X"
County Surveyor's Brass Cap per C.S. file 54/1 bears
N.89°29'E., 4.97 ft.

Original closing Township Corner (SW Cor. Sec. 31 T.20-11) 106
Found - 2 1/2" Douglas County Surveyor's Office brass cap on a 1 1/2" iron pipe.
(C.S. 54/1) See renewal # 18.
20" Fir stump, N.6°E., 20.4 ft. (rec. 21.1 ft.)
32" Fir stump, S.19°E., 6.7 ft. (rec. S.20°E., 6.3 ft.)
Uprooted Fir stump, N.43°W., 18.0 ft. to root hole. (rec. 20.5 ft.)
New BTs -
14" Spruce, S.20°E., 34.5 ft. scribed "T21S R11W S6 CC BT"
13" Alder, N.44°W., 2.5 ft. bark scribed "S1 BT"

Original Township Corner (NE Corner Sec. 1) 107
Found - 2 1/2" aluminum pipe (set by Durham in 1964) Menasha records.
BTs per C.S. 54/1 - See renewal # 19.
30" Fir snag, S.88°W., 41.6 ft. (rec. S85°W., 40.9 ft.)
22" Hemlock stump, N.15°E. 29.8 ft. (rec. N.15° 1/2'E. 30.1')
38" Fir stump, N.48°W., 42.2 ft. very rotten (rec. 40.1 ft.)
Rotten Fir stump, N.5°E., 30.7 ft. scribing visible (rec.
N.5 1/2°E., 28.4 ft.)
New BTs -
9" D.Fir, N.39°E., 16.5 ft. scribed "S31 BT"
11" Alder, S.19°E., 20.9 ft. bark scribed "S31 BT"
8" Alder, S.61°W., 21.0 ft. bark scribed "T21S R12W S1 BT"
14" Alder, N.14°W., 10.1 ft. bark scribed "T20S R12W S36 BT"

1/4 Corner for Section 1 and Section 6 T.21-11 108
Found - 2 1/2" brass cap on a 2 1/2" iron pipe (C.S. 58/140 N)
BTs found per C.S. 58/140 N - See renewal # 64.
15" D.Fir, N.24°W., 11.0 ft. Healed blaze. (rec. N.25°W.)
Fir windfall, S.31°E., 48.5 ft. (rec. S.31°30'E., 45.2 ft.)
New BTs -
12" Hemlock, N.61°E., 11.7 ft. scribed "1/4 S6 BT"
14" D.Fir, S.26°E., 27.9 ft. scribed "1/4 S6 BT"
16" D.Fir, S.62°W., 11.7 ft. scribed "1/4 S1 BT"
Fence post 1 ft. north of corner.

1/4 Cor. Secs. 4 & 33 T20S R12W 109
Found - Corbitt's 1 1/2" I.P. (Ren. # 52) REPLACED pipe with a 2 1/2"x30" Alum.
cap mkd: T20S R12W 1/4 S33 S4 T21S 1994 LS 1091
BTs - 18" Spruce, bears N.45°E., 22.1' (1/4 S33 BT)
30" D.Fir, bears S.50°E., 8.0' (1/4 S4 BT)
10" Spruce, bears S.4°E., 19.4' (X BT)
10" Spruce, bears S.13 3/4°W., 13.6' (1/4 S4 BT)

Robert Ward, LS 1091
For: Siuslaw Nat. Forest
& Tahkenitch Tree Farm
Partnership
April 1995
M 122 - 3 A

John C. Bentley
For: I.P. Timberlands Operating Co., Ltd
Feb. 1995
M121 - 68