

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 12 W. R.W.W.M.

ROSE CHAPMAN CO. EUGENE, ORE. 97101

Milo E.  
Godfrey & Crew  
Nov. 1964  
C. S. File  
No. 53/66

Sec. Cor. to Secs. 13 & 24, T21-12W. & Secs. 18 & 19, T21-11W.  
Found - 2" Iron Pipe mentioned by Frank Cain - (See Ren. #5)  
Pipe extends approx. 12" above ground.  
No trace of any Original Bearing Trees.  
New BT's: 16" D. Fir S. 8° W. 8.4 ft. Mkd: T21S R12W S24 CS BT.  
14" D. Fir S. 60° E. 24.7 ft. Mkd: T21S R11W S19 CS BT.  
13" D. Fir N. 77° E. 27.2 ft. Mkd: T21S R11W S18 CS BT.  
No suitable trees near in Section 13.  
DID NOT SET BRASS CAP. - Corner is approx. 500 ft. W. of Smith River Road.

16

23

Nov. 25, 1964

Ronald Durham  
For Menasha  
Corp.  
March 1965  
C. S. File  
No. 51/311

South  $\frac{1}{2}$  Corner of Section 36, T20-12W.  
Drive 2" x 3" aluminum pipe 2' into the ground, from which:  
45" Red Cedar bears S. 31° E. 11.9 ft. face has been chopped out.  
New BT: 30" Fir bears N. 21° E. 9.5 ft. scribed S36 BT.  
24" Fir Snag bears N. 17° W. 23.7 ft. with a tag and painted red.

17

RE-NEWED SEE CORNER NO. 103

Closing Township Corner:  
Fd. - Orig. 40"?, now 22" Fir Stump, N. 6° E. 21.1 ft., shows "S R11WS" on opened blaze, Tree probably 14" when mkd. Ring count 60+ years.  
Orig. 40", now 48" Fir, tipped out stump laying face, down, N. 42° W. 20.5 ft.  
No trace of SE BT.

18

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967  
New BT: 30" Fir Stump S. 20° E. 6.3 ft. mkd. T21S R11W S6 CS BT.  
No other stumps or trees close.  
Note - This corner lies on very steep, NE. slope, approx. 195 ft. South of Twp. Cor. T20 & 21S, R. 12W, see corner below.  
Brass Cap is set on East Side and under 30" Log.

Township Corner - T 20 S R12W S 36 | R11W  
T 21 S R12W S 1 | R11W  
Found - Orig. 15", now 30" Shattered Fir Stump, N. 5 $\frac{1}{2}$ ° E. 28.4 ft., with "T20S 11W 31 BT", scribe revealed.  
Orig. 15", now 30" Fir, 20' high Snag, S. 85° W. 40.9 ft., shows scar.  
Orig. 12", now 18" Fir, badly decayed Stump with frag. reverse scribe marks, N. 8 $\frac{1}{2}$ ° W. 31.7 ft. N. trace of 30" BT.  
Unrecorded 40" Fir Stump bears N. 48° E. 40.1 ft. mkd. S31 BT. #107  
New BT: 24" Hemlock N. 15 $\frac{1}{2}$ ° E. 30.1 ft. mkd. T20S R11W S31 CS BT.  
No other trees close.

19

Note - This corner lies on moderate SE slope approx. 100 ft. S. of top of ridge. Cl. Cor., see above, bears S. 195 ft. This area logged recently

Sec. Cor. to Secs. 33 & 34, T21-12W. & Secs. 3 & 4, T22-12W.  
Found - No trace of Iron Pipe at Section Corner.  
Orig. 24" Spruce, now 36" rotted Stump, S. 85° W. 11.9 ft., scribe visible "S4 22 R12W".  
Orig. 20" Spruce, now 24" rotted Stump, N. 29° W. 34.3 ft., scribing found "R12W T22".  
No trace of N.E. or S.E. BT's. Distances from Orig. BT's. taken from face.

20

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1967  
Note - B. Cap in 12"x24" Tile which is filled with concrete.  
New BT's: 38" Spruce N. 40° W. 83.6 ft. mkd. T21S R12W S33 CS BT  
38" Hemlock N. 73° E. 90.0 ft. mkd. T21S R12W S34 CS BT.  
Power Pole, bearing object, S. 50° W. 110.7 ft. PP #AG04A - 34.  
Note - This corner lies in middle of draw running E. & W.  
Also north of Forest Hills Road or 22nd., approx. 125.0 ft.

FD. OK 10/87 R. STUMPFNER M101-28

FD. OK 2/12/75 L.A.M. Co. Surveyor Ref. C.S. 54/46  
MICROFILM TO HERE 10/67

21

Warren D.  
Hootman  
For: R.C. Roles  
Map File M 36 - 23

Meander Corner North Side of Umpqua River btwn. Secs. 25 and 26.  
Set - Post 6" x 6"  
Bears S. 36° 36' E. 228.67 ft. from Sta. 2427+97.9 on S.P. RR.  
May 3, 1968

Vernon "Ray" Tracy  
Jack Heritage & E. West  
March, 1967  
C.S. File No. 54/1

James W. Byron, Co. Surv.  
John M. Powell & J. Brady  
August 24, 1967  
C. S. File No. 54/46