

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 12 R. W. W. M.

Meander Corner Sections 16 & 15.

Found - 1" I. pipe with cap mkd M.C. 16/15. Ren. #11
54" Spruce stub, N.20°W., 100.7 ft. Tree opened scribe visible
"3" "M.P."
72" Spruce, now down, S.83°E., 6.8 ft.
24" Spruce, now 32", N.46°W., 65.0 ft. Has rotten face.
New BT - 14" Spruce, West 43.0 ft. Scribed MC S16 CS BT.
Rescribed - 32" Spruce, N.46°W., 65.0 ft. Scribed MC S16 CS BT.
Note - This corner lies on southerly side of dike.
1/2/72

FD OK BY ROADWARD 5-1-93 M117-9 33

Fritz Ingram
John M. Powell
J. Heritage
1/31/72
C. S. File 56/7

Section corner for Sections 9, 10, 16, & 15.

Found - 40" D. Fir, now stag, S.59°E., 105.00 ft. S.D. Bark scribe visible "T21". Ren. #10
50" D. Fir, now stump, N.46°W., 60.5 ft. S.D.
No trace of other BT's.
Set - Brass cap at sec. cor. mkd. County Surveyor's Office
1972 T21S R12W S9/S10 S16/S15
New BT's - 10" Alder, S.43°W., 11.6 ft. Scribed T21S R12W S16 CS BT.
14" Alder, N.75°W. 37.0 ft. Scribed T21S R12W S9 CS BT.
6" Alder, N.42½°E., 8.6 ft. Scribed T21S R12W S10 CS BT.
8" Alder, S.77°E., 12.0 ft. Scribed T21S R12W S15 CS BT.
Note - This corner lies on easterly edge of logging road.
1/31/72

FD OK BY ROADWARD 5-1-93 M117-9 34

Section Corner to Sections 27 - 28 - 33 - 34.

Corner found by field crew, not of record.
Found - 1 3/4" X 23" Axle, flush with ground
Telephone Pole near fence with Yellow Tag S.86½°W. 76.6 ft.
S.E. Corner of Chimney N. 41°W. 162.3 ft.
This corner also tied to triangulation point, Slim.
Note - International Paper also set I. Rods 1320 ft. East & 665 ft. (?) East of 1/16. Not too sure of line, more or less an agreement
1/72

RE-RENOVATED CORNER NO. #85 35

R. L. Ingram
John M. Powell
Jan. 1972
C. S. File 56/7

S. W. Corner to D. L. C. No. 37.

Corner found by field crew, not of record.
This point 5/8" Iron Rod flush with concrete, in driveway on the East side of Highway No. 101.
No trace of Alder Bearing Trees, as mentioned in Ren. #2.
SEE REN. #39

36

1/4 Cor. Sec. 34, T21-12 and Sec. 3, T22-12.

Found - Chisled "+" in concrete on east abutment of bridge bears S.35°16'W., 191.1 ft. Ren. No. 13
Chisled "+" in concrete on east abutment of bridge bears S.55°28'W., 159.0 ft.
Set = Brass cap from found bearing objects, per telephone conversation from Eugene Bloom, 11/8/73.

37

Baughman Surveying
for Lillebo & Holliday
M 49 - 41
April 1973

1/4 Corner Secs. 32 and Sec. 5 of T22-12

Found - O.B.T. 30"x10' tall rotted spruce stub, "BT" scribe visible (also fd. by Epstein, C.S., 1925) Ren. #3
Set - 1 1/4" I.P. (in swamp) scribe "1/4S 3683 BT" on:
18" Alder, N.8°30'E., 18.5 ft.
17" Alder, S.71°30'W., 51.4 ft.

38

Robt. Thompson
for Edin Properties
M 51 - 65
C.S. 55/328
Apr.-Nov. 1973

Meander corner Sec. 22 & 27, on right bank of Umpqua River.
(See Ren. Cor. #2 and 36 and C.S. File 41/180)

Found - 5/8" I. Rod, not of record, set flush in a concrete driveway on the east side of US Hwy #101 in Gardner. This monument was found based on information shown on Oregon State Hwy. Dept. drawings, #4B-26-2, 1B-26-23 and 5B-31-5, filed respectively in the Douglas County Surveyors Office as State Hwy. maps C-8, C-10 and D-1. State Hwy. Dept. officials indicated during a telephone conversation that the field notes of their road surveys do not show this corner as being recovered.

39

Gary Langlitz
P. Earle
C.S. 57/12
11/29/74