

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W R.W.W.M.

110

1/2 Section Corner to Sections 10 and 15.
Found - Orig. 12", now 24" Snag, Maple S. 2° E. 40.3 ft.,
shows scribing "BT".
Orig. 40" Fir, now uprooted stump, N.39°W. 35 lks.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 T22S R4 1/2 S 10
S 15
New BT's: 42" Fir N.53°W. 89.0 ft. Mkd: 1/2 S10 BT.
30" Cedar N.23°E. 55.2 ft. Mkd: 1/2 S10 BT.

111

Section Corner to Sections 7 - 8 - 17 - 18.
Found - Brass Cap at Corner, See Ren. #30. *FO OK 9/92 D. Peck # 25-17*
10", now 11" Red. Fir S.67°W. 41.0 ft., scribing visible.
14", now 17" Cedar S.18°E. 84.5 ft., scribing visible.
12" Red Fir, now stump, N.46°E. 9.4 ft.
14" Red Fir, now stump, N.81°W. 43.0 ft.
New BT's: 6" D. Fir N.31°W. 28.8 ft. Mkd: S7 CS BT.
14" Cedar N.66°E. 58.0 ft. mkd: T22S R4W S8 CS BT.

112

1/2 Corner to Sections 8 and 17.
Found - Orig. 6" Fir, now rotted stump, N.22°W. 64.0 ft., chopped
out, found scribing "1/2 S".
2" Galv. I. P. 2 ft. W. of Corner, unrecorded.
No trace of S. W. tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 T22S R4W 1/2 S 8
S 17
New BT's: 18" Cedar S.19°W. 34.0 ft. Mkd: 1/2 S17CS BT.
16" D. Fir N.83°E. 42.4 ft. Mkd: 1/2 S 8 CS BT.

RE-RENEWED - SEE CORNER NO. #158

113

1/2 Corner to Sections 30 and 29.
Found - Orig. 15", now 21" B.Oak, N.45°W. 77.9 ft., chopped out
found scribing "BT".
10" W.Oak, now rotten stump, N.79°E. 44.2 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 T22S R4W 1/2 S 30/S 29
FO OK 7/75 J. BAIRD, M119-73
New BT's: 12" D. Fir N.79°E. 66.2 ft. Mkd: 1/2 S29 CS BT.
9" Oak N.52°W. 35.0 ft. Mkd: 1/2 S30 CS BT.

114

1/2 Corner to Sections 29 and 28. (Haines' Corner)
Found - Haines' "T" Iron 1 ft. from fence corner. *(SEE N-118)*
12" Cedar N.58°E. 56.4 ft.
45" Fir, probably 8" Orig. BT. N.69°E. 52.1 ft.
Note - This corner was renewed by Haines but not recorded.
Opened 45" Fir, found good scribing, "S".
New BT: 15" Fir S.73°W. 27.0 ft. mkd: 1/2 S29 CS BT.

FO OK 2/97 M 111-66

RE-RENEWED - SEE CORNER NO. #172

115

1/2 Corner to Sections 26 and 35.
Found - 2" Galv. I. Pipe at Corner.
Orig. BT: 8" Fir, now 18" Snag, N.82°W. 12.5 ft., scar
shows good scribing "2". *SEE THEIR'S Book 3 P 634*
No trace of B. E. BT.
New BT's: 13" Cedar S.12°W. 88.0 ft. Mkd: 1/2 S35 CS BT.
9" Cedar N.59°E. 27.3 ft. mkd: 1/2 S26 CS BT.

RE-RENEWED - SEE CORNER NO. #147

Jan. 27, 1965

116

1/2 Corner to Sec. 36, T22-4W. & Sec. 1, T23-4W.
Found - 1" Iron Pipe & 1" Alum. Pipe as recorded in Ren. No. 48.
Bearing Trees all Stumps, not scribed "W" nails only.
New BT's: 10" Hemlock N. 61° W. 68.3 ft. Mkd: 1/2 S36 DCS BT.
7" Hemlock S. 7° E. 58.7 ft. Mkd: 1/2 S 1 DCS BT.
Note - This corner is on Lane - Douglas County Line.

Nov. 4, 1965

Vernon "Ray"
Tracy.
M. Stone &
J. Layne
Nov. 1965
C.S. 54/16

Bruce R. Rogers, Deputy County Surveyor
Jan. 1965
C. S. File No. 53/101