

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R. W. W. M.

Weyerhaeuser Co.
1958 to 1963
C. S. File No. 53/105

117
 1/4 Corner to Sections 3 and 10.
 No trace of Orig. Stone or Post.
 12" Laurel N.47°W. 36.3 ft., gone
 24" Fir S.32°W. 22.4 ft., now 30" Fir Stump, no visible scribing.
 GLO 1903, no mention of 1884 Stone.
 8" Cedar N.10°W. 27.1 ft., scribing visible on 14" ICCedar.
 Found - 1" Galv. I. Pipe used as hub by Woodard Lumber Co.
 New BT's: 52" I.Cedar Stump N. 7°E. 46.0 ft., added "W" Nail & Plate.
 16" Fir S.57°E. 19.0 ft., " " " " " "
 August 26, 1963

118
 1/4 Corner to Sections 17 and 20.
 Found - 20" Fir S.24°E. 9.9 ft., no evidence found.
 24" Fir N.20°W. 39.0 ft., " " " "
 Set - 1" Aluminum Pipe
 New BT's: 6" Fir S.51°E. 15.6 ft., added "W" Nail & Plate.
 6" Fir S.67°W. 36.1 ft., added " " " "
 May 15, 1962

119
 N. 1/16 between Sections 21 and 20.
 Found - Brass cap set by Cadastral, 1963, (record pending)
 Placed 1" aluminum alongside.
 28" Fir N.56°E. 31.6 ft.) Destroyed 2/64 by
 28" Fir N.07°W. 21.2 ft.) Weyerhaeuser
 New BT's: 10" Fir N.31°W. 56.1 ft. (1963 BT) added "W" Nail & Plate.
 32" Fir N.36°E. 34.5 ft. (1963 BT) added 1962 "W" Nail & Plate (2149)

Vernon "Ray" Tracy
Mike Stone & J. Layne
Feb. 7, 1966
C. S. File No. 53/101

120
 1/4 Corner to Sections 9 and 16. FND OK 8/94 BY HOFFENS M121-9
 Found - 1/2" I.P. & Haines' "T" Iron as found & recorded by Godfrey, 1963,
 see C.S. File No. 49/59. - SEE REN #40
 "362" bark scribed on 48" Fir N.32°W. 19.0 ft. This tree
 recorded in Martin's field book, #2, Pg.6. Orig. BT.
 7", now 9" Fir S. 69° W. 9.0 ft., now down & pushed out of
 place, Haines' button on partially healed face.
 No trace of Orig. S. E. BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R4W S 9
 Office, 1966 S 16
 New BT's: 4" W. Fir N. 1° E. 120.7 ft. Mkd: 1/2 S 9 CS BT.
 12" Cedar S. 12° E. 53.7 ft. Mkd: 1/2 S16 CS BT.
 Note - This corner lies approximately 100 ft. South of ridge, course E.-W.

MICROFILM TO HERE - 10/67

Vernon "Ray" Tracy & Crew
C.S. File No. 54/14

121
 Section Corner to Sections 31 & 32, T21-4W. and Secs. 5 & 6, T22-4W.
 Found - 1962 C.S. Brass Cap, properly marked & firmly set, See Ren. #61.
 14", now 15" W. Fir, alive, N.32°E. 18.0 ft., nearly healed FO DE
 blaze, scribing visible. LOS Roberts
 18", now 19" D. Fir, alive, N.50°W. 15.3 ft., nearly healed blaze.
 13", now 14" D. Fir, alive, S.17°W. 58.4 ft., blaze healed. 12/94
 S. E. Bearing Tree down. M121-26
 New BT: 13" R. Fir S.71°E. 91.4 ft. mkd: T22S R4W S5 CS BT.
 Probable Orig. Bearing Tree stump still in place.
 This corner lies N.65°E. 4.5 ft. from fence corner, fences E-W & S.
 12/27/68

Wilford M. Haines
For Whipple, Drain
June, 1961 C.S. M 22-6 (Print)
See Also M 39 - 53

122
 1/4 Corner to Sec. 3, T23-4W. and Sec. 34, T22-4W.
 Found - 18" Fir, now 40" South Fl. 10 lbs.
 Scribed Stake, in place. #149
 Set - 1" x 1" x 36" T. Iron by Stake.

123
 Sec. Cor. to Secs. 3 & 2, T23-4W. & Secs. 34 & 35, T22-4W. #137
 Found - 12" Fir S.40°E. 70.0 ft.
 14" Fir S.66°E. 69.2 ft., not scribed & no record of renewal.
 Set - 1" x 1" x 36" T. Iron & Scribed: 5" W.Oak S.73°W. 33.3 ft.

124
 1/4 Corner to Sec. 2, T23-4W. & Sec. 35, T22-4W.
 Set - 1" x 1" x 36" T. Iron & Scribed: 26" Fir S.70°E. 10.5 ft.
 8" Fir N.37°E. 15.9 ft. Fd 7/88
 D. Post M104-59

RE-RENEWED SEE CORNER NO. #149
 RE-RENEWED SEE CORNER NO. #137