

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

125

Standard Corner of Tps. 22 & 23, Rs. 3 & 4W.,
Perpetuated with a 1/2" Alum. Pipe, firmly set, 12" above ground,
at record bearing & distance from the only remaining Orig. BT:
59" Fir bears N.65°E. 39 lks. with scribe mark "S", & other
illegible scribe marks visible on partially open blaze.
Set - Iron Post 28" long, 2 1/2" diam., 24" in ground with brass cap mkd:
T22S R4W S C R3W
S 36 | S 31
T23S S 1 | S 6
1959

New BT's: 7" Madrone bears N.52 1/2°E. 72 lks. mkd: T22S R3W S31 SC BT.
6" Chinq. bears S.29 3/4°E. 38 lks. mkd: T23S R3W S 6 SC BT.
6" Madrone bears S.36°W. 60 lks. mkd: T23S R4W S 1 SC BT.
6" Madrone bears N.82 1/2°W. 21 lks. mkd: T22W R4W S36 SC BT.
Deposit local corner marker alongside the iron post.

U.S. B.L.M. Dependent Reurvey
N. Btry. T23-3W. June 10, 1959
See Notes C.S. File No. 54/16

126

Section Corner of Sections 3, 2, 10 and 11. Ren. #59
Found: 24" Maple, S.25°E., 31.0 ft. Good Condition.
48" Fir, S.35°W., 6.6 ft. Uprooted and down.
22" R. Cedar, S.32°W., 61.0 ft. Good condition.
27" D. Fir, N.8 1/2°E., 59.3 ft. Stump now, Good condition.
26" D. Fir, S.89°E., 60.6 ft. Uprooted and down.
48" Fir, N.70°W., 5.3 ft. Uprooted and down.
Reset: Brass Cap pulled up by windfall. Reset from BT's. No new
BT's available.

10/8/71

Francis L. Ingram
Deputy Co. Surveyor
R. Tracy & W. Parley
C.S. File 53/101
October, 1971

Jan 1972

Township Corner R T 21 S R
5 S 36 | S 31 4
W S 1 | S 6 W

127

Found - 3/4" Iron Pipe & 4"x4" Post with scribing visible laying beside
the iron pipe. See Ren. #11, T21-3W. REN. #94
30" D. Fir BT, face visible, bears S.25 1/2°E. 6.0 ft. (Rec. 5.0 ft.)
34" D. Fir BT, face visible, bears N.42 1/2°E. 27.8 ft. (Rec. 26.4 ft.)
34" D. Fir BT, face visible, bears N.9 1/2°W. 52.5 ft. (Rec. 51.7 ft.)
28" D. Fir BT, scribes vis. bears S.21 1/2°W. 60.7 ft.
40" Orig. D. Fir BT., burned stub, bears S.11 1/2°W. 132.0 ft.
Set Brass Cap Mkd:
T21S, T22S, R5W. R4W, S36, S31, S1, S6, 1972

8/30/72

128

1/4 Corner to Sec. 6, R4W and Sec. 1, T22-5W.
Set - Brass Cap Mkd: T22S, R5W, R4W, WM
S1, S6, 1/4 S 1972
Found - 30" Orig. Doug. Fir BT., scribing partially visible, bears
N. 80°W. 24.4 ft.
I scribed: 22" Doug. Fir "1/4S S6 BT" bears N.82°E., 9.9 ft.
12" Doug. Fir "1/4S S1 BT" bears S.78 1/2°W., 42.0 ft.

8/30/72

Section Corner R S 1 | S 6 R
SW S12 | S 7 4W

129

Found - Co. Surv. Brass Cap, 1959, mkd. as above. REN. #43
18" Chinquapin BT. scribes vis. bears S.30°E. 14.8 ft.
24" Cedar BT, scribes vis. bears N.16°E. 46.8 ft.
12" D. Fir BT, bears N.62°W. 13.0 ft. (Rec. N.64°W.)
40" Orig. D. Fir BT Windfall, shows rotted face, bears S.18°E. 44.9'.
Orig. 30" Doug. Fir BT., stump hole only, bears N.70°E. 33.7 ft.
I scribed an 18" Hemlock "T22S R5W, S12 BT", bears S.26°W. 112.6 ft.
Found - 4"x4" Post scribed S1, S6, S7, S12 laying by Brass Cap.

8/30/72

130

Witness corner for 1/4 corner, Sec. 19 and Sec. 24 of T. 22-5.
1/4 corner not found. Falls on steep bank. Did not see.
Set - 5/8" steel rod, 59.5 ft. scribe
Scribed - 22" Fir, N.77 1/2°E., 6.9 ft.

8/15/75

Wilford N. Haines
For: Jim Whipple
August 15, 1975
H 57 - 71

RE-RENEWED CORNER NO. #146

1/76