

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 4 R.W.W.M.

138

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
T. Plouff
Feb. 9, 1982
C.S. 61/30

Section corner for Secs. 19 and 30; and Secs. 24, 25 of T.22-5
Found - 1959 County Surveyors brass cap set firmly in ground protruding
4" out of ground, properly mkd. Ren. #44
Stone set by Theil with "+" on top, mentioned in Ren. #44
just east of brass cap. Stone protrudes 4" out of ground.
Orig. 10" now rotted 28" fir stump previously opened bears
N.52°W., 21.8 ft. Scribing no longer visible.
6" now 13" fir bears S.32°E., 26.1 ft. (Rec. S.30°E.) with well
healed double blaze. Ren. #44
7" now 13" fir bears S.4 1/2°W., 41.0 ft. (Rec. S.6 1/2°W.)
with well healed double blaze. Ren. #74
All other bearing trees have been destroyed by recent logging.
Note: Due to wire fence & 2 steel fence posts being within approx.
2 ft. of brass cap, all of my compass bearings were taken on
lines projected back approx. 10 ft. from brass cap.
New BT - 15" fir scribed "T22S R4W S30 CS BT" in double blaze bears
S.63°E., 54.6 ft.
Sketch in C.S. file.

2/9/82

Section corner for Secs. 22, 23, 26 and 27
Found - 3/4" iron pipe (unknown origin) alongside 36" "T" iron
with brass cap attached mkd. "Survey Point #239 Wilford Haines"
Ren. #24 139
Possible orig. 60" fir, now 60" (alive) with bark scribing "T22
R4 S26 BT". This does not appear to be orig. scribing. Tree
bears S.56°E., 16.0 ft. (Rec. S.70 1/2°E., 13.9 ft.)
Possible orig. 52" fir, now 48" stump. No definite scar showing
but I open with saw anyway. No face visible. If tree had been
bark scribed logging would have destroyed it. Tree bears N.26°W
26.9 ft. (Rec. N.19 1/2°W., 27.1 ft.)
24" fir, (unknown origin) scribed "T22S R4W S27 363" in bark.
Tree bears S.4°E., 15.8 ft. (Note: based on my bearing, tree
should have been scribed S26 not S27)
48" cedar (unknown origin) bark scribed "T22S R4W S22 BT". Tree
bears N.65°W., 43.7 ft.
Set - Since I found no evidence to prove that the two big firs were
originals, I did not change the location of the corner but
instead referenced the point set by Haines and set a 1" x 30"
iron pipe with brass cap attached mkd. "Douglas Co Surveyor
T22S S22 S23 S27 S26 R4W 1982" at that location. I reset found
3/4" I.P. and "T" iron alongside new brass cap.
New BT - 7" fir scribed "T22S R4W S23 CS BT" in double blaze bears
N.67°E., 28.4 ft.

10/5/82

1/4 Corner for sections 22 and 27
Found - 36" "T" iron with brass cap mkd. "Survey Point Wilford N. Hai
#239". Monument was protruding 6" out of ground. Ren. #23
30" incense cedar now 32" stump bears S.45°E., 82.3 ft.
Shows good scar.
14" fir, now 21" (alive) bears N.46°E., 34.3 ft. (Rec. N.44°E
34.0 ft.) shows good scar.
Set - I referenced location of found monument then replace it with
1" x 30" iron pipe with brass cap attached mkd. "Douglas Co
Surveyor T22S 1/4 S22 S27 R4W 1982". I place found "T" iron
along northerly side and slightly lower than new brass cap.
Monument is located 0.8 ft. north of corner post of a new wire
fence running south and N.66°E.
New BTs - 6" fir scribed "1/4 S27 CS BT" in double blaze bears S.31°W., 41.6'
7" fir scribed "1/4 S27 CS BT" in double blaze bears S.82°W., 21.0'
14" fir scribed "1/4 S22 CS BT" in double blaze bears N.46°W.,
20.4 ft.

10/4/82

Frank O. Williams
LS #875
For: Weyerhaeuser Co.
May 16, 1983
X 94 - 36

Center 1/4 Section Corner of Sec. 26.
Set - 1/2" x 24" I.R. w/ plastic cap mkd: WEYER CO. in mound of stones.
New BTs - 32" incense cedar S.72°E. 29.0 ft.
27" fir S.28-1/2°W. 39.4-ft. (Dist. meas. to "w" nail).
RE-RENEWED SEE CORNER NO. # 157

141

5/16/83

Gregory Quibell, Deputy, Douglas Co. Surveyors Office
Karen Reed - Terrie Branssen - (Ed Sehlén)
October 4, 1982
C.S. 62/1

(SEE F.B.
H-112)