

Douglas County Surveyor's Record of
Government Corners Renewed

T 22

T. S.

R 4

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

142

1/4 Corner for Sections 9 and 10

Found - 1958 County brass cap on a 1" x 36" long galva. I.P. Monument removed by construction of fire trail is found lying S.42°E., 7.6 ft. from corner position. I.P. rusted near top. Ren. #38
An orig. cedar, 12" diam. now a cedar stump 36" in diam. and 60" tall bears N.58°E., 12.5 ft. No orig. scribing found. Byron rescribe from Ren. #38 has open face and shows scribing 1/4 S10 CS BT. No evidence of other orig. BT found.
A 13" R. fir now a 17" D.B.H. D. fir bears S.41 3/4°W., 46.4 ft. (Rec. per Ren. #38, S.41°W., 47.1 ft.; BLM Rec. S.47 1/2°W., 46.2 ft.)

Set - Monument found is replaced by new cap and pipe because of its rusted condition. Position for new mon. determined primarily from record bearing and dist. from found orig. BT. New mon. is a 2 3/8" brass cap on a 1" x 32" I.P. firmly set and protruding 7" from ground. Cap marked Douglas Co. Surveyors Office T22S 1/4 S9 S10 R4W 1984.

New BTs - 9" D.B.H. D. fir bears S.57 1/2°E., 17.0 ft. scribed 1/4 S10 CS BT on a double blaze.
13" D.B.H. D. fir bears S.15°E., 44.8 ft. scribed 1/4 S10 CS BT on a double blaze.
12" D.B.H. W. fir bears S.76 1/2°W., 22.9 ft. scribed 1/4 S9 CS BT on a double blaze.

Note: Corner is located 80 ft. + North of ridge top accessed from BLM Rd. 22-4-20.0. Sketch in C.S. file.

8/2/84

Dougl. Co.
Surveyors Off.
L.E. Monrean,
Deputy
S. Flause
R. Smith
August 2, 1984
C.S. 62/18

Douglas County
Surveyors Office
Larry E. Monrean
Deputy
Randall Smith
Stephen Flause
April 27, 1987
C.S. 62/40

Donald Peel
For: Weyerhaeuser
Company
Dec. 1987
M 105 - 27

Douglas County
Surveyors Office
Stephen Flause
Randall Smith
Jan. 28, 1988
C.S. 62/50

1/4 Corner for Sections 26 and 27

Found - A W. Haines T-iron with metal washer protruding 1 ft. above ground, bent slightly west. Original stone not found. Ren. #25
16" now 34" dia. 5 ft. high D. fir stump. We open & find scribing "BT" upper face shows good axe marks. Scribing possibly chopped out., bears N.21°E., 25.6 ft. (Rec. N.21°E., 24.4 ft. possible face measurement) Orig. BT.
40" now 38" dia. 4 ft. high D. fir stump axe marks and flat spots found on bark. We open and found no burl, blazes, axe marks or scribing. Bears N.9°W., 38.8 ft. (Rec. N.9°W., 37.0 ft. Possible face measurement) Possible Orig. BT.

Set - A DCSO 2 3/8" brass cap on a 1" I.D. x 32" long iron pipe protrudes 6 ins. above ground marked "Douglas County Surveyors Office T22S 1/4 S27 S26 R4W 1987". Haines T iron, 36" long protrudes 4" above ground reset along north edge of BC/IP. DCSO BC/IP set a found plumb position of Haines T-iron.

New BTs - 37" dia. 4 ft. high D. fir stump, set a boat spike through BT tag bears S.36°W., 61.2 ft.
34" dia. 1 1/2 ft. high cedar stump, set a boat spike through at tag stamped "B0 1" bears N.46°E., 47.9 ft.

Corner lies in a clear cut at bottom of a easterly-westerly ravine.

143

1/4 Corner for Section 18 and Section 13 of T.22-5

Set - 2" x 42" iron pipe with brass cap marked "T22S R5W R4W 1/4 S13 . S18 PLS 752 1987"

New BTs - 14" fir, S.52°E., 16.9 ft. scribed "1/4 S18 BT"
20" fir, S.47°W., 23.2 ft. scribed "1/4 S13 BT".

FD. B.C.
7/92
R. DOLAN
M115-27
12/87

1/4 Corner for Section 30 and 31 *FAK 9/95 BY BAKER. M119-73*

Found - A 2 1/2" dia. brass cap on a 1 1/2" O.D. I.P. firmly set and protruding 6" above ground. (1964 County BC, Ren. #101)

A 6"x16"x10" sandstone loose on ground surface with the marks "1/4" on the bottom side bears N.8°E., 1.5 ft. from the I.P. and BC monument (first noted in Ren. No.5, origin unknown)
Orig. BT, 10" fir now a 40" DBH D. fir with the bark scribing "1/4 S31 CS" (Ren. #5) and an opened blaze with orig. scribing "1/4 S visible, bears S.60°E., 17.8 ft.

(Orig. Northeast BT gone)

A 36" fir now a 43" dia. 4 ft. high fir stump with no scribing remaining bears N.77°E., 58.7 ft. Ren. #5 and 101

144

145