

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 4 R. W. W. M.

ROSE-CHARMAN CO. EUGENE, ORE. 1949

James W. Byron
For Fred Booth
March 30, 1956
C.S. File No. 47/70
M 2 - 32

Section Corner Common to Sections 7, 8, 17, & 18. 30
Found: 3" X 3" Scribed Stake at Corner. - REN. # 11
All BTs scribed by Theil, are down, scribing visible on stumps.
Set Brass Cap marked S 7 | S 8 T22S R4W, County Surveyor's Office, 1956
S18 | S17 ///
From Which: Red Fir 12" bears N.46°E. 9.4 ft. scribed S8 CS BT.
14" Red Fir bears N.81°W. 43. ft. scribed T22S R4W S7 CS BT.
10" Red Fir bears S.67°W. 41. ft. scribed S18 CS BT.
14" Cedar bears S.18°E. 84.5 ft. scribed T22S R4W S17 CS BT.

James W. Byron
M. Godfrey
S. Bilow
Dec. 26, 1957
C. S. File 49/59

$\frac{1}{2}$ Section Corner to Sections 18 & 17. 31
Found - $\frac{3}{4}$ " I. Pipe at corner & 2 BTs. as renewed by Theil but not
recorded: 20" Maple S.82°W. 80.8 ft., open & find scribing.
18" Maple S11°W. 96.3 ft., open face shows good scribing.
See C. S. File No. to check position of $\frac{3}{4}$ " I. Pipe at $\frac{1}{2}$ Corner.
Set Brass Cap at Corner marked $\frac{1}{2}$ S18/S17 T22S R4W, County Surveyor's
Office, 1957. 99
Blazed & Scribed 28" W. Oak N.49°E. 225.0 ft. $\frac{1}{2}$ S17 CS BT.

James W. Byron, Deputy
M. Godfrey
S. Bilow
Jan. 8, 1958
C. S. File No. 49/54

FD. OK 2/25 21 BAKER, M/19-73
Section Corner to Sections 31 & 32, T22S, R4W, and Secs. 5 & 6, T23S, R4W. 32
Found - Both BTs. as renewed by Theil, 1926-1931, See Book , Page 45.
BTs. alive but scribing about gone. Corner 2' North of
East West Fence.
Find base of old cedar stake 12" under at Corner.
BTs. check bearings & distances. No Original BTs. found.
Set Brass Cap at Corner marked S31 | S32 T22S R4W County Surveyor's
S6 | S5 T23S R4W Office, 1958
New BTs: 12" Maple bears N.72°W. 24.8 ft. scribed T22S R4W S31 CS BT.
32" W. O. bears N.83°E. 43.8 ft. scribed T22S R4W S32 CS BT.
16" Ash bears South 31.7 ft. rescribed this BT. T23S R4W S6 CS BT.
24" W. Oak bears S.59°E. 71.6 ft. scribed T23S R4W S5 CS BT.

James W. Byron, Dep. Co. Surveyor
M. Godfrey
S. Bilow
Jan. 8, 1958
C. S. File No. 49/59

Section Corner to Sections 13, 18, 19, & 24. 33
Found - Rotted Fir Stump, 12" diam, N.42°W. 56.8 ft, showing "BT"
scribed when cut open.
Remnants of Rotted Fir stump N.37°E. 35.0 ft., too far gone
to find scribing.
Fir Stump, now 5 1/2" diam. S.52°W. 40.3 (distance from face of
40" tree). This tree had apparently been bark scribed. No
bark left on side of stump facing corner.
Corner lands in fence corner, fences running North, South, &
West.
No trace of S. E. BT. could be found.
At Corner point set Iron Pipe with Brass Cap stamped "County Surveyor's
Office, 1958, T22S S18 | S18 R4W
S24 | S19
Blaze & Scribe Following Trees:
11" W. Fir S.36°E. 25.8 ft. (T22S R4W S19 CS BT) FD. B.C. 7/92
R. DOLAN M115-37
9" D. Fir N.74°E. 27.8 ft. (T22S R4W S18 CS BT) FD. OK Dec 44
7" W. Fir S.36°W. 18.9 ft. (T22S R5W S24 CS BT)
12" D. Fir N.71°W. 80.8 ft. (T22S R5W S18 CS BT) one blaze

James W. Byron
M. Godfrey
S. Bilow
Jan. 27, 1958
C. S. File No. 49/59

Section Corner to Secs. 7 & 18, T22S R4W, & Secs. 12 & 13 T22S R5W. 34
Found - Wooden Stake At Corner. (SEE ALSO THEIL FIELD BOOK #1 PG 12)
30" Fir Snag S.44°W. 62.7 ft. showing old bark scribing. The
figure "13" was all that was legible.
40" Fir, uprooted & down, S.28° or S.30°E. (instead of S.38°E)
69.3 ft., old scribing visible "S18 T22S R4W".
N.37 1/2°W. 21.1 ft. was remains of old Maple Stump with live
Maple tree growing out of one side.
No evidence of N.E. BT. could be found.
At Corner set Iron Pipe with Brass Cap mkd. "S12 | S 7 T22S, County Surveyor's
R5W S13 | S18 R4W Office, 1958.
5" Fir S.45°W. 8.2 ft. scribed "S13 CS BT".
12" Yew N.40°W. 16.8 ft. scribed "T22S, R5W, S12 CS BT"
(cont. over)