

**Douglas County Surveyor's Record of
Government Corners Renewed**

22

T. S.

4

R. W. W. M.

COKE-CHAPMAN CO., EUGENE, ORE. 97106

(continued)

Set Brass Cap at Corner Mkd: County Surveyor's Office,

S25	S30
R5 W S36	S31 R4W

 T22S
1959
New BT's: 62" R. Fir bears N.15°E. 130.0 ft. scribed S30 T22S R4W CS BT.
12" Cedar bears S.13½°E. 92.0 ft. scribed S31 T22S R4W CS BT.
6" R. Fir bears S.78°W. 39.2 ft. scribed S36 CS BT. *To OK Dec 24*

*FD OK M 95-12/83
L. Smith*

Standard Section Corner to Sec. 31, T22S R4W, & Sec. 6 T23S R4W
and Sec. 1, T23S R5W.

Found - Orig. 14" ,now 34" W. Oak N.80°W. 1091.0 ft. Theil
rescribed this BT. years ago. I open back of his
scribing & find Orig. scribing "WR".

Also find 2" Iron Pipe at corner. Turpin says Theil
set this pipe for corner.

Closing Corner 4.59 ch. West, not found.

New BT: 26" Maple bears N.80½°W. 475.0 ft. scribed S36 T22S R5W CSBT.
No other trees near.

½" Iron Rod with 4" x 4" White Post bears S.55°E. 88.2 ft.,
Post marked SHRW L PT 722+72.44.

Jan. 25, 1960

46

James W. Byron
Milo Godfrey
Glete Putman
C. S. File No. 48/42

*FD OK
10/79
CS. 62/63*

*(SEE ALSO)
ROW 227
T23-4*

1/25/60

*FD OK
JAN 1964
L. C. 153/101*

Cor. Common to Secs. 35 & 36, T22S R4W, & Secs. 1 & 2, T23S R4W.

GLO Survey Record, All evidence gone.

County Survey Record, All evidence gone.

By careful retracement of the Township Line to the East & West,
the Orig. Line Trees were found and the corner was re-established
at the prop. dist. between these Orig. Line Trees.

Nailed a 3" x 3" piece of aluminum to a 12" Fir Log for
corner at prop. dist. between the following identified Orig.

Line Trees: 48" Fir East 166 feet - 2 notches on E. & W. sides
42" Fir Stmp. West 166 feet

Referenced by Glen McChesney (Weyerhaeuser Method) Decl. 20°

12" Red Cedar	N.32°E.	22.0'
60" Fir	S.79°E.	39.9'
32" R. Ced. Stp.	S.02°W.	31.4'
66" Fir	N.45°W.	28.6'

*Mar 1965
Ced. Questioned
at 2. Tally
Insignificance
L.L.*

Note - More information in file if needed.

RE-ESTABLISHED CORNER NO. #154

For Weyerhaeuser Timber Co.
By Glen McChesney
Under Lester E. Calder
April 14, 1960
C. S. File No. 51/87

½ Corner Common to Sec. 36, 22S-4W & Sec. 1, 23S-4W.

GLO Survey Record; Post, - Gone.

17" Fir N.22°E. 26.1ks, now 38" Fir windfall-faces are up,
filled with dirt & upper face rotted.

28" Fir S.57½°W. 70 lks., remains of roots of large Fir,
S.58°W. - 46.2 ft.

Found 1" I.P. 6" out of ground for corner, good for dist. &
bear. from GLO BT's. Drove 1" x 30" aluminum pipe beside
this iron pipe.

Referenced by Glen McChesney (Plates & "W" nails only) Decl. 20°

26" Fir	N.71°W.	11.9 ft.
50" Fir	S.75°W.	15.6 ft.

½ Corner common to Sections 35 and 36.

GLO Survey Record: Original, not found.

14" Cedar N.60°W. 21 lks., 36" I. Cedar, scribing visible.

5" Spruce S.40°E. 43 lks., gone, probably meant White Fir).

Found: Mound of Stone around post for corner, not original,
good for distance & bearing from NW BT.

Referenced by Glen McChesney (Plates & "W" nails only) Decl. 20°

14" Fir	N.89°E.	10.2 ft.
36" I. Cedar	N.60°W.	13.1 ft. (Orig. BT.)

*FD 7/88
D. PEEL
M106-59*

48

49

116