

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

Weyerhaeuser Company  
 Lester E. Calder by Robert Barta  
 Sept. 1962 - Filed Oct. 1962  
 C. S. File No. 51/87

Milo E. Godfrey, Deputy  
 V. Tracy & M. Stone  
 Feb. & March 1963  
 C. S. File No. 49/42 & 49/59

1/4 Corner common to Sections 16 and 21. 69  
 GLO Survey Record, 1855 SEE H. EN. 7  
 Post - Gone, replaced by Haines "T" Iron Stake.  
 18" Fir N.15°E. 18 lks. - 38" Fir stump, upper face chpd.out & scbng. visible.  
 20" Fir S.10°W. 59 lks. - 42" Fir, bark scribing visible.  
 Referenced by Robert Barta (Plates & "W" Nails only) Decl. 20°  
 38" Fir Stump N.13°E. 10.6 ft. - Orig. BT.  
 42" Fir S.11°W. 36.7 ft. - Orig. BT.  
 FD OK 3/1993 BY NESS M116-66

Corner common to Sections 16 -17 - 20 - 21. 70  
 GLO Survey, 1855  
 Post - Gone  
 18" Fir N.37°E. 106 lks. - No trace  
 20" Fir S.62°E. 36 lks. - Found rotted stump only  
 30" Fir S.60°E. 84 lks. - 54" Fir Stump  
 60" Fir N.4 1/2°W. 145 lks. - Rotten windfall, no scribing visible.  
 County Survey Record, 1928-Cedar Post in place, scribing visible.  
 8" Fir N.61°10'E. 41 lks. - 20" Fir, healed faces  
 30" Fir S.71°40'E. 11 lks. - 36" Fir, scribing visible. SEE REN = 6  
 60" Fir S.58°25'W. 84 lks. - 45" Fir Stump, healed basal scar.  
 36" Fir N.29°05'W. 300 lks. - 42" Fir Snag, bark scribing visible.  
 Referenced by Wm. L. Wilt (Plates & "W" nails only) Decl. 20°  
 20" Fir N.60°E. 27.4 ft.  
 36" Fir S.85°E. 6.8 ft.  
 14" Fir S.21°W. 29.2 ft.  
 14" Fir N.62°W. 54.8 ft.

1/4 Corner common to Sections 21 and 22. 71  
 GLO Survey Record, 1855  
 Post, - Gone, found Haines' "T" Iron Stake & 1/2" I. Pipe. (SEE H. EN. 6)  
 36" Fir N.34°E. 69 lks. - 42" Fir, bark scribing visible  
 36" Fir N.73°W. 51 lks. - Badly rotted & burned remains  
 Referenced by Robert Barta (Plates & "W" nails only) Decl. 20°  
 18" Fir N.59°E. 5.3 ft. (12" Fir N. 60° E. 6.0 ft.) Haines' BT's.  
 20" Fir S.34°W. 33.3 ft. (10" Fir S. 85° W. 6.3 ft.)  
 FD OK 3/1993 BY NESS M116-66

1/4 Corner common to Sections 20 and 21. 72  
 GLO Survey Record, 1855  
 Post - gone, found brass cap set by Co. Surv. 1961 (Ren. No. 53) #159  
 6" Maple N.62°E. 34 lks. - 12" Maple, chopped on & no scribing visible.  
 40" Fir S.50°W. 23 lks. - 40" x 12" Fir Snag, chopped on & no scbng. visibl  
 Referenced by Robert Barta (Plates & "W" nails only) Decl. 20°  
 12" R. Cedar N.21°E. 9.7 ft.  
 10" R. Cedar S.27°W. 28.0 ft.

1/4 Corner to Sections 14 and 15. 73  
 Found - 32" Fir Snag S.78°E. 22.4 ft, good bark scribing visble, "S BT".  
 No trace of S. W. BT. S.B. T24-4W  
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
 T243 R4W 1/4 S15/S14  
 New BT's: 10" D. Fir N.34°E. 54.0 ft. Mkd: 1/4 S14 CS BT.  
 6" W. Fir S.20°W. 44.9 ft. Mkd: 1/4 S15 CS BT.

Section Corner to Secs. 19 & 30, T22-4W. & Secs. 24 & 25, T22-5W. 74  
 Found - County Surveyor's Brass Cap & Thiel's Rock at Corner. (See Ren. #44)  
 5" D. Fir N.25°W. 31.0 ft., alive & in good condition.  
 8" D. Fir N.20°E. 49.5 ft., " " " "  
 6" D. Fir S.30°E. 26.1 ft., " " " "  
 S. W. BT. is now down.  
 New BT: 7" D. Fir S.64°W. 41.0 ft. Mkd: T22S R5W S25 CS BT.  
 RE-RENEWED, SEE CORNER NO. #138  
 JULY 1963