

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

86  
 $\frac{1}{4}$  Corner common to Sections 24 and 25.  
GLO Survey Record, 1884  
Found - No trace, Post and Stone, destroyed by logging.  
6" Laurel N.  $14^{\circ}$  W. 50 lks., gone  
36" Fir, now 48", S.  $3^{\circ}$  W., 130 lks., scribing visible in upper face.  
Set - 1" alum. pipe, "W" nails & plates. Decl.  $20^{\circ}$   
46" Fir S.  $2^{\circ}$  E. 84.9 ft.  
12" Fir N.  $33^{\circ}$  W. 26.2 ft.

87  
 $\frac{1}{4}$  Corner common to Sec 36, T22-4W. & Sec. 31, T22-3W.  
GLO Survey Record, 1851 Post, gone.  
24" Fir S.  $73^{\circ}$  W. 34 lks, rotted remains of Fir stump, axe marks.  
No trace 8" Maple N.  $76^{\circ}$  E. 27 lks.  
Found -  $\frac{3}{4}$ " Iron Rod  
Referenced Weyerhaeuser Method (Plates, "W" nails) Decl.  $20^{\circ}$   
42" Fir N.  $39^{\circ}$  E. 39.6 feet  
4" Hemlock S.  $79^{\circ}$  W. 23.0 feet.

88  
West  $\frac{1}{4}$  Corner Section 12.  
GLO Survey Record 1855 Post, no trace  
60" Fir N.  $4^{\circ}$  W. 27 lks., 60" Fir snag, old axe marks.  
50" Cedar N.  $85^{\circ}$  E. 36 lks., 50" Cedar Shell.  
Set - 1" Alum. Pipe set by dist. & bear. from remains of Orig. BT's.  
Plates "W" nails, Decl.  $20^{\circ}$   
10" Fir S.  $83^{\circ}$  E. 14.0 ft.  
8" Fir S.  $46^{\circ}$  W. 8.0 ft.

89  
Center  $\frac{1}{4}$  Corner Section 24.  
Found -  $\frac{5}{8}$ " Iron Rod. & 24" Fir S.  $83^{\circ}$  W. 49.7 ft., 18" Fir scribed "BT".  
6" Fir N.  $22^{\circ}$  E. 41.2 ft., 10" Fir, face not opened.  
Referenced, Plates, & "W" nails.  
10" Fir N.  $27^{\circ}$  E. 41.0 ft.  
18" Fir S.  $83^{\circ}$  W. 49.7 ft.

90  
West  $\frac{1}{4}$  Corner Section 24.  
GLO Survey Record, 1884 - Post, gone.  
40" Fir, S.  $27^{\circ}$  E. 48 lks, 42" Fir Stump.  
50" Fir N.  $25^{\circ}$  W. 6 lks., 50" Fir, bark scribed.  
Reestablishment, dates 1952, Found mound of Stone. - Yew Stake in Mound.  
Referenced, Plates, & "W" nails. Decl.  $20^{\circ}$   
42" Fir Stump S.  $28^{\circ}$  E. 31.1 ftl, Orig. BT.  
50" Fir N.  $52^{\circ}$  W. 4.1 ft., Orig. BT.

91  
Section Corner to Secs. 13 - 14 - 23 - 24.  
GLO Survey Record, 1855 - Post, gone.  
8" Cedar N.  $88^{\circ}$  E. 37 lks. rotted, burned remains of down cedar.  
20" Cedar S.  $8^{\circ}$  E. 66 lks., 36" Cedar stump, rotted interior.  
30" Cedar S.  $67^{\circ}$  W. 38 lks., Remains of down broken cedar.  
18" Cedar N.  $55^{\circ}$  W. 36 lks., 40" hollow cedar.  
Found - reestablishment Notes, 1957.  
Set - Pipe & referenced - found  $\frac{3}{4}$ " S.I. Pipe &  $\frac{1}{2}$ " Monel Pipe.  
10" Hemlock N.  $5\frac{1}{2}^{\circ}$  E. 38.0 ft., found O.K.  
8" Hemlock S.  $76^{\circ}$  E. 40.5 ft., now stump.  
30" W. Fir S.  $70^{\circ}$  W. 38.9 ft., down, plate not visible.  
48" Cedar Stump N.  $55^{\circ}$  W. 23.0 ft., found O.K.  
Plates, "W" nails Decl.  $20^{\circ}$   
62" Fir S.  $58^{\circ}$  E. 34.8 ft.  
12" Yew S.  $54^{\circ}$  W. 54.5 ft.

Weyerhaeuser Co.  
by Glen McChesney, Land Agent - Lane County Records  
1960 - 62  
C. S. File No. 53/1