

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

FOUR-CHARMAN CO. EUGENE, ORE. 9787

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Stone
Feb. 1964
C. S. File No. 49/59

1/4 Section Corner common to Sections 34 and 35.
Found - 1 1/2" I. Pipe & 5" sq. Cedar Stake (scribed) at corner. *see c.s. 61/5*
36" Fir Stump N.66°W. 217 ft. opened & fd. gd. scribing "1".
Stump Hole, remains of old cedar lying downhill from it, S.50°E.
46.2 ft., cedar badly rotted & burned, no marks.
24" D. Fir Snag, not Orig. BT., N.69°E. 36.2 ft., scribing in
wood, "1/4 S CS BT", no record of this tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 19 64 *fd. 7/88 D. Poesl M 106-59 6/90 M 110-39*
T22S R4W 1/4 S34/S35
Iron Pipe, badly rusted, Set Brass Cap alongside Cedar Stake.
New BT's: 32" D. Fir N.42°W. 14.3 ft. Mkd: 1/4 S34 CS BT.
15" D. Fir S.20°E. 8.7 ft. Mkd: 1/4 S35 CS BT.
Note - Corner lies on N. slope of hill approximately 460 ft. North of ridge.
Feb. 26, 1964 93

Milo E.
Godfrey &
Crew
C. S. File
No. 49/68

Sec. Cor. Secs. 5 & 4, T22-4W. & Secs. 32 & 33, T21-4W. 93
Found - Small Fir Snag N.7 1/2°E. 15.2 ft., scribing visible on badly,
rotted, exposed face, "T21SR4WS33". BT. scar visible, See Ren. #54
No other Bearing Trees found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T21S	S32	S33
R4W	S5	S4

New BT's: 9" D. Fir N. 2°E. 89.6 ft. Mkd: T21S R4W S33 CS BT.
17" D. Fir N.25°W. 12.0 ft. Mkd: T21S R4W S32 CS BT.
7" Hemlock S72 1/2°W. 24.8 ft. Mkd: T22S R4W S5 CS BT.
No trees convenient S.E. of Corner.
Oct. 23, 1964

B. H. McGillicuddy
July 1953
See Map
C. S. File No. 41/182

TOWNSHIP CORNER

T21S	S36	S31
R5W	S1	S6
T22S		R4W

94
Found - 40" Fir (burned stub) S.11°30'W. 200 links. *SEE ALSO TASH'S BOOK 5 Pg 18*
Orig. S.14°W., old scribed post, BT's destroyed. *RE-RECORDED TOWNSHIP CORNER NO. #127*
Set - 3" I. Pipe & Scribed New BT's:
24" Fir N.42°30'E. 26.4 ft. Mkd: T21S R4W S31 BT.
28" Fir N. 9°30'W. 51.7 ft. Mkd: T21S R5W S36 BT.
28" Fir S.21°10'W. 60.7 ft. Mkd: T22S R5W S1 BT.
26" Fir S.25°30'E. 5.0 ft. Mkd: T22S R4W S6 BT.
Cor. set by McGillicuddy, 1953. In Oct. 1964, M.E. Godfrey, Deputy Co. Surv.,
found 3" Pipe & 4 BT's. still in good condition. -See C.S. 49/68

M. E. Godfrey,
& Crew
C. S. File
No. 49/68

1/4 Corner Sec. 35, T21-4W. & Sec. 2, T22-4W. 95
(On N. Line T22S R4W & on Lane-Douglas County Line)
Found - 1/2" Galv. Iron Pipe extending 12" above ground. - Ren. # 78.
42" Fir Stump S.4°W. 15.8 ft., old bark scribing visible "1/4 S".
Fir stump, uprooted, N.30°E. 2.6 ft., no scribing found.
DID NOT SET BRASS CAP.
New BT's: 17" White Fir N.76°W. 27.7 ft. Mkd: 1/4 S35 CS BT.
10" D. Fir N.49°E. 49.7 ft. Mkd: 1/4 S35 CS BT.
Nov. 16, 1964

Weyerhaeuser
Co.
C. S. File
No. 51/87

1/4 Corner common to Sections 27 and 34. 96
Found - GLO Survey Record 1855 - Post, Gone. *SEE REN. #27 FOR HAINES REN.*
18" Fir S.57°E. 13 lks., not found
12" Fir N.37°W. 41 lks., bark scribed, also face chopped &
scribing visible behind burl. *fd. Mkd 7/88 D. Poesl M 106-59 6/90 M 110-39*
Referenced by G. McChesney (Plates & "W" nails only) Decl. 20°
52" Fir N.66°E. 21.2 ft. O. K.
16" Fir N.37°W. 27.2 ft. O.K.
July 1964