

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD. OK 2/92 BY PEEL
M. 114-60

32

Section Corner to Sections 5, 6, 7, & 8.

Found - Orig. 24" now 30" B. Oak snag S.75°W. 139.9 ft. This BT was found & apparently rescribed by Theil in 1899. See Book #10 Job 17. I open this BT & find Theil's "BT 2" under surface. I cut out this BT and find the orig. BT scribing about 5" under our face.

All other orig. BTs. gone.

I also find $\frac{3}{4}$ " I.R. & old scribed 4" x 4" Post at Theil's Corner from which now 28" R. Fir bears N.45°W. 13.2 ft. I open & find good scribing. $\frac{3}{4}$ " I.R. bears S.20°E. 17.7 ft.

I use record distance & bearing from orig. S.W. BT. to establish this section corner as the evidence at this time indicates Theil was in error in the location of this corner.

Set Brass Cap at corner marked T.22S R.5W. $\frac{S6}{S7}$ | $\frac{S5}{S8}$ County Surveyor's Office, 1958

New BTs.:
10" R. Fir bears S.77°W. 134.8 ft. scribed T22S R5W S7 CS BT.
14" R. Fir bears N.58°W. 118.8 ft. scribed T22S R5W S6 CS BT.
8" R. Fir bears N. 3°E. 139.4 ft. scribed T22S R5W S5 CS BT.
40" B. Oak bears S.4 $\frac{1}{2}$ °E. 168.2 ft. scribed T22S R5W S8 CS BT

James W. Byron, Dep. Co. Surveyor
Chairman: M. Godfrey
S. Bilow
Jan. 7, 1958
C.S. File No. 49/59

33

Section Corner to Sections 13 & 24 T22S R5W, & Secs. 18 & 19 T22 S R4W.

Found - Rotted Fir Stump, 12" diam. N.42°W. 56.8 ft., showing "BT" scribe when cut open.

Remnants of rotted Fir stump N.37°E. 35.0 ft., Too far gone to find scribing.

Fir Stump, now 54" diam. S.52°W. 40.3' (distance from face of 40" tree). This tree had apparently been bark scribed. No bark left on side of stump facing corner.

Corner lands in fence corner, fences running North, South & West. No trace of S.E. BT. could be found.

At Corner Point set Iron Pipe with Brass Cap stamped "R $\frac{S13}{S18}$ | R T22S
County Surveyor's Office, 1958" W $\frac{S24}{S19}$ W

Blaze & Scribe following Trees:

11" W. Fir S.36°E. 25.8 ft. (T22S R4W S19 CS BT)
9" D. Fir N.74°E. 27.8 ft. (T22S R4W S18 CS BT)
7" W. Fir S.36°W. 18.9 ft. (T22S R5W S24 CS BT)
12" D. Fir N.71°W. 80.8 ft. (T22S R5W S13 CS BT) one blaze.

FD. OK
12/87
D. Peel
M. 105-27

FD. B.C. 7/92
R. DeLan
M. 115-37

34

Section Corner to Sections 12 & 13 T22S, R5W, & Sections 7 & 18, T22S, R4W.

Found - Wooden Stake at Corner.

30" Fir Snag S.44°W. 62.7 ft. showing old bark scribing. The figure "13" was all that was legible.

40" Fir, uprooted & down, S.28° or S30°E. (instead of S.38°E.) 69.3 ft., old scribing visible "S 18 T22S R4W".

N.37 $\frac{1}{2}$ °W. 21.1 ft. was remains of old Maple stump with live Maple tree growing out of one side.

No evidence of N.E. BT. could be found.

At Corner set Iron Pipe with Brass Cap stamped "R $\frac{S12}{S13}$ | S 7 R4W T22S, County
1958 R5W $\frac{S13}{S18}$ Surveyor's Office"

5" Fir S.45°W. 8.2 ft. scribed "S 13 CS BT"
12" Yew N.40°W. 16.8 ft. scribed "T22S, R5W, S12 CS BT"
18" R. Cedar N.72°E. 8.5 ft. scribed T22S R4W S7 CS BT"
16" R. Cedar S.48°E. 5.2 ft., found scribing 5 to 10 yrs. old on this tree "T22S R4W S18 BT, I added "C S".

Note - The Maple growing out of stump of old Maple BT. was also scribed 5 to 10 yrs. ago. Scar was mostly covered but could see scribe marks. Bearing N.40°W. 21.1 ft.

FD. OK
12/87
D. Peel
M. 105-27

James W. Byron, Deputy, County Surveyor
M. Godfrey
S. Bilow
Jan. 27, 1958
C.S. File No. 49/59
PEEL RM 1-40 for McGillicuddy Survey

Renew $\frac{1}{4}$ Section Corner to Section 11 & 14.

Found - $\frac{3}{4}$ " I.P. at old anchor post in old N.S. fence line. Bears S.32°E. 4.5 ft. -KEN. #22

Find orig. 50" now 54" Stump, shows old scribing "1" bears S.32°E. 85.8 ft., record 92.4 ft.

Find 60" Fir Stump all bark now gone, checks record dist. & bearing, no scribing found. I believe this is Orig. BT.

Note - Creek at 51 ft. West of Corner, record 150 ft. East of Corner.

D.F. Theil Re-marked N.E. BT.
1902 - see C.S. 64148 pg 15

35