

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

RE-RENEWED CORNER NO. 103 68
Section Corner to Section 3, 4, 9, and 10.
Found Stumps of 2 Bearing Trees and a Stake.
Set 1" x 1" x 36' T. Iron

Wilford N. Haines
May, 1960
M 11 - 68

1/4 Corner to Section 32. (South Side) *FR. OK. 6-81*
Not on Line. *E. BLOOM M 79-79* 69
Found - 2 Stumps that fit for bearing & distance
of Orig. BT's.:
20" Fir Snag, scribed 1/4 S B.T. S.86°W. 13.2 ft.
Set - 1" x 1" x 36" T. Iron 1/4 S32, Not on Line.

Wilford N. Haines
June, 1960
Map. File
M 19 - 6

Corner common to Secs. 33 & 34-21S-5W & Secs. 3 & 4 22S-5W. 70
GLO Survey Record - 1855
Post, gone - 30" Fir S.23°W. 174 lks. Gone
36" Fir S.15°E. 256 lks. Gone
24" Fir N.3 1/2°E. 211 lks. Gone
20" Fir N.80°W. 309 lks. Now 44" Fir Stump,
scribing probably destroyed in logging 97
County Survey Record - 1938 (c.s. 16/2)
2" Iron Pipe - No Trace
12" Chnqpn N.10°E. 271.5 ft. No Trace.
21" Fir N.40°W. 104.0 ft. Now 24" Fir Stump-scribed "BT"
44" Fir N.80°W. 205.0 ft. Original BT
8" Alder S.30°E. 244.7 ft. No 10" & dead-scribing visible.
Set 1" x 30" aluminum pipe for cor. using the two existing
County BT's & the one orig. GLO BT.
Reference by Wm. Wilt (plates & "W" nails only) Dec. 20°
6" Fir S.70°E. 82.2 ft.
4" I. Cedar S.37°E. 36.8 ft.
4" Fir S.78°W. 44.2 ft.
24" Fir stump N.46°W. 104.0 ft. CSBT

Lester E. Calder
For Weyerhaeuser Co.
Dec. 1, 1960
C. S. File No. 51/147

S. E. Corner of D. L. C. No. 38. 71
Found - Orig. 30", now 48" B.Oak N.19°E. 94.4 ft., previously
opened, shows good scribing "22S 5W BT".
Orig. N.83°E. 161.7 ft., not found.
Corner Stone not found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
S.E. Corner DLC 38 T22S R5W
New BT's: 30" B.Oak bears N. 6°W. 23.4 ft. scribed SE Cl 38 CS BT.
12" R.Fir bears S.29°E. 24.4 ft. scribed SE Cl 38 CS BT.

James W. Byron
Milo Godfrey
June 20, 1961
C. S. 49/59

*See C.S. 64/49
Pg 8 For
The set corner
FD 8/81
R. Dean
M 88-15*

Section Corner to Sec.s 6 & 7, R5W. & Secs. 1 & 12, R6W. 72
Found - Rock Monument at corner. Pieces of rotted Oak Wood N.4°E. 101
or 102 ft. (Gov't notes call for Oak Tree N.4°E. 110.0 ft.)
Logging road runs just north of Oak fragments. No stump
hole visible. W. Haines states that he has seen scribing there
several years ago. He couldn't remember whether or not the
tree was standing at the time.
Set - Brass Cap Mkd: County Surveyor's Office, 1961
T22 R6W S1 | S6 R5W
S12 | S7
New BT's: 16" Fir N.16°W. 46.5 ft. Mkd: T22S R6W S1 CS BT.
4" Fir N.39°E. 21.0 ft. Mkd: S 6 CS BT.
12" Fir S.65°W. 9.4 ft. Mkd: T22S R6W S12 CS BT.
7" Fir S.70°E. 16.5 ft. Mkd: T22S R5W S 7 CS BT.
E. & W. fence is 2.5 ft. North of corner.
1 1/2" Pipe bears N.88°E. 14.43 feet.

*see FD. OK
JUNE 1965
B.B.R.*

Milo E. Godfrey, Deputy Co. Surveyor
Vernon Tracey & Clete Putnam
October and November 1961
C. S. File No. 49/143

1/4 Corner to Sec. 7, R5W. & Sec. 12, R6W. 73
Found - 3/4" I. Pipe at corner as called for in former renewal #41
12" Maple S.83°E. 46.0 ft. The 72" Fir S.3°E. has blown down.
New BT: 32" Fir North 52.8 ft Mkd: 1/4 S12 CS BT.