

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Bruce R. Rogers, Deputy Co. Surveyor
Wm. Stoffel & Mike Stone
February 1965
C. S. File No. 53/101

C. C.
Section Corner R 6 W R 5 W
S 36 / S 31 T22S
S 1 T23S
1943

FD. O.K. 6-81
E. Bloom M 79-79
FD OK 2/86
E. BLOOM M100-25 105

Found - GLO Brass Cap at Corner as marked above.
Corner is 2 ft. south of E.-W. Fence.
New BT's: 7" D.Fir N. 4° W. 26.0 ft. Mkd: CC T22S R6W S36 CS BT.
6" Madrone N.62°E. 22.5 ft. Mkd: CC T22S R5W S31 CS BT.

Section Corner R6W S 1 / S 6 R5W T22S
SC T23S
1943

106

Found - GLO Brass Cap at Cor. Mkd. as above.
9" Fir, now stump, S.29°E. 68.9 ft. - No trace of SW Tree.
New BT's: 14" W.Fir S.84°E. 93.0 ft. Mkd: T23S R5W S6 CS BT.
7" D.Fir S.70°W. 34.4 ft. Mkd: T23S R6W S1 CS BT.
Note - Corner is at East-West-South Fence Corner.

1/4 Corner to Sections 15 and 16.

107

Found - Orig. BT.- 10" Fir, now stump, S.80°E. 21.8 ft.
Orig. BT.- 36" Fir, now stump, S.48°W. 37.6 ft.
4 x 4 scribed Post and 1" Iron Pipe at Corner (Ren. #90)
New BT's: 24" White Fir S.29°E. 21.1 ft. Mkd: 1/4 S15 CS BT.
22" Cedar N.68°W. 29.5 ft. Mkd: 1/4 S16 CS BT.

Section Corner to Sections 32 and 33 only.

108

Found - 12" Fir, now 43", N.23°E. 8.0 ft. scribing visible "BT".
No trace of N. W. Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T 22 S # 150
S 32 / S 33 R5W
C C
New BT: 8" Fir N.29°W. 45.5 ft. Mkd: T22S R5W CC S32 BT.
Rescribed - 43" Fir CC T22S R5W S33 CS BT.

1/4 Corner to Sections 19 and 20.

109

Found - 18" Maple N.68 1/2°E. 64.0 ft., scribing visible.
24" R.Fir, now snag, N.44°W. 58.5 ft.
Co. Surv. Brass Cap at Cor., 1958, Ren. #52.
New BT: 24" D.Fir S.19°W. 93.5 ft. Mkd: 1/4 S19 CS BT.

Feb. 1965

Weyerhaeuser
Co.
April 1960
C. S. File
No. 53/105-A

1/4 Corner to Sections 22 and 23.

110

Found - No evidence of 5" Blk. Oak N.28°E. 5.9 ft.
4" Fir S.57°W. 7.9 ft., now 18" fir, upper scar has been
chopped out & scribing "1/4 S" visible.
Corner falls on large root. Drove "W" Nail for Corner. - NOT SUFFICIENT EVIDENCE
BT's: - 16" Fir N.63°W. 17.8 ft. "W" Nail & Plate
18" Fir S.57°W. 7.7 ft. "W" Nail & Plate.
SEE OLD BOOK
PAGE 13
11-7-67
SEE C.S. FILE NO. 53/101

1/4 Corner to Sections 5 and 4.

111

Found - Sandstone Mkd: CS 1/4 S (See Ren. #9)
10" Fir, now 18" Snag, chopped out, shows good scribing.
12" Fir, now 19" N.24°E. 13.5 ft., Rescribed 1/4 S4 CS BT.
Set - " I. Rod on South Side of Stone.
New BT: 12" D.Fir S.39°W. 29.3 ft. Mkd: 1/4 S5 CS BT.

Section Corner to Sections 4 - 5 - 8 & 9.

112

Found - 6" Oak, now 8" N.4°W. 102.6 ft. shows good scar.
11" Fir, now 13" N.26°E. 49.8 ft., shows good scar.
24" R.Fir, down, S.8°W. 26.3 ft.
24" R.Fir, broken, S.40°E. 8.4 ft., shows remnants of scribing.
Corner lands on sandstone, as described in Ren. #66, but Brass Cap is missing.
New BT's: 18" D.Fir S.31°E. 55.0 ft. Mkd: T22S R5W S9 CS BT. (Set 1/4" I.Rod)
16" D.Fir S.39°W. 103.0 ft. Mkd: T22S R5W S8 CS BT.
Note - Corner is approx. 30 ft. N. of Fence Corner.

Bruce R. Rogers, Deputy
Wm. Stoffel & Mike Stone
March 1965
C. S. File No. 53/101