

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22      T. S.      R 5      R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

**154**

Section corner for Secs. 27, 26, 34 and 35.

Found - A 1" Iron pipe protruding 14 ins. out of ground, with brass cap attached marked COUNTY SURVEYORS OFFICE T22S S27 S26 S34 S35 1958. Ren. #45

From which:

- A 36" Incense cedar identified in 1958 as an orig. BT bears N.3°W., 19.8 ft. with scribe marks visible in unhealed rescribe blaze.
- A 14" W. Fir, now a 20" rotten snag bears S.81°W., 38.4 ft. with scribing "22S R5W S34 CS BT" visible on an unhealed double blaze.
- An 18" now 24" D. Fir, alive and well-healed bears S.31°E., 62.0 ft.
- A 4" Yew marked in Ren. #45 bearing N.50°E., 9.8 ft. is gone.

We find no evidence of the orig. monument or any additional orig. BT's.  
New BT's - A 9" Yew bears N.64°W., 29/9 ft/ scrobed "T22S R5W CS BT" in a double blaze.

A 15" Red alder bears S.45°W., 10.4 ft. scribed "T22S R5W S34 CS BT" on a double blaze.

Compass declination setting: 20° East.

6/10/76

Gary L. Langlitz  
A. Vic Cangie  
Surveyors Office  
June 10, 1976  
C.S. 59/15

**155**

1/4 Corner for Sec. 6 and Sec. 1, T22-6

Set - 1/2" Iron pin

BT's - 8" Oak, bears N.61°E., 51.9 ft. scribed.

12" Alder, bears N.06°W., 17.6 ft. bark scribed.

Jan. 1976

Donald Stone, Green  
Empire, Inc.  
For: Don Churchill  
Jan. 1976  
M 60-60

**156**

1/4 Corner for Secs. 4 and 3.

Found - Haines "T" Iron and washer at corner point. Ren. #54-A

From Which:

- A 12" now 18" B. Oak bears S.57°E., 8.7 ft. Tree is alive but in poor condition. Shows healed blaze.
- A 16" now 24" Fir bears N.30 1/2°W., (Rec. N.34°13'W.); 40.4 ft. Healthy and shows healed blaze.

Set - A 1" x 30" I.P. with brass cap stamped: Douglas Co. Surveyor

T 22 S  
1/4  
S 4 | S 3  
R 5 W

We replace found "T" iron on North side of Brass Cap.

New Tree - A 16" R. Cedar bears N.3°E., 27.5 ft. mkd. "1/4 S3 CS BT"

Note: Corner lies approx. 50 ft. South of a SW draw in an old east-west fence.

11/22/76

A. Victor Cangie  
Mike Tompkins  
Do. Co. Surveyors  
Office  
Nov. 22, 1976  
C.S. 59/26

**157**

1/4 Sec. Corner for Sec. 18 and Sec. 13 of T.22-6.

Found - A 7" now 20" B. Oak, alive with well-healed double blaze.

A 15" now 16" B. Oak, alive with well-healed double blaze.

A 1" x 3" x 32" channel iron mentioned in Ren. #63, lying on its side and buried under a N-S fence.

At the corner point as determined by Byron's BT's in Ren. #63:

- A 20" B. Oak bears N.8 1/2°E., 19.8 ft. and a
- 16" B. Oak bears N.18 1/2°W., 168.2 ft.

We Set - A 1" x 30" I.P. 25" in the ground with brass cap attached mkd.:

Douglas County Surveyor      R      T 22 S      R  
1976      6 S 13      S 18 5  
W      1/4      W

We place the found channel iron along the north side of the brass cap.

We do not identify any orig. corner accessories.

This corner is located in a N-S fence line.

12/27/76

Gary L. Langli  
A. Vic Cangie  
Doug. Co.  
Surveyors Office  
Dec. 27, 1976  
C.S. 59/26

FO. OK 12-91  
C. GULF 1992-0079  
FO. OK 4/19/84  
M. NAVIG.  
C. S. 50/114  
FND. OK 10/93 BY BENTZ  
1994-0001