

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Wilford N. Haines  
For: Rick McMullin  
Aug. 1977  
M 66 - 31

Section corner for Secs. 29, 30, 31 and 32.  
Found - 12" Ash, bears N.42°W., 418 lks., now 30", alive but partly  
down, center rotted.  
Set - 5/8" Rebar. Drove steel fence post alongside.

FD. OK 4/94 BY PIESKE  
M 120-4

158

1/4 Corner for Secs. 31 and 32.  
Found no trace of orig. corner. Area has been logged and burned.  
Set - 5/8" rebar.  
New BT's - 12" Fir, N.53°W., 46.7 ft.  
24" Fir, N.74°E., 53.2 ft.

RE-RENEWED SEE CORNER NO. #160

159

Harold Stockhoff  
LS #1663  
For: Milton W.  
Bedortha & Karl  
Hess - August 1979  
M 78 - 78 C.S.58/208

1/4 Corner for Secs. 31 and 32.  
East 1/4 corner sec. 31 was not found. See Ren. #159  
Set - 5/8" iron rod and remeasured dist. to existing BTs.  
12" Fir, N.56°45'W., 46.70 ft.  
24" Fir, N.74°19'E., 51.60 ft.

8/77  
FD. OK 4/94 BY PIESKE M 120-4

160

Bruce Shaner  
For: Woolley  
Enterprises, Inc.  
Nov. 1980  
RM 3 - 40

Northwest Corner D.L.C. #38  
Found - Haines "T" Iron. Ren. #80  
24" D. Fir (stump) BT, bears S.64 1/2°W., 39.4 ft. (Rec. 38.3 ft.)  
18" D. Fir (stump) BT, bears N.44 1/2°W., 35.5 ft.  
24" D. Fir (two stumps) BT., bears N.5°W., 45.3 ft. (Rec. 47.5 ft.)  
Set - Brass cap.  
Reset Haines T iron alongside brass cap.

FD. OK 2/9/1991

11/80

1/4 Corner for Secs. 28 and 33-  
Set - 5/8" x 24" Iron rod  
from which:  
A 15" Fir, bears N.34°E., 37.7 ft. scribed 1/4 S28 BT.  
10" Fir, bears S.29°E., 44.0 ft. scribed 1/4 S33 BT.

Eugene Bloom  
For: Fugate & Payne  
Dec. 1980  
M 79 - 64 A & B

162

Section corner for Secs. 20, 21, 29 and 28.  
Set - 1" x 36" iron pipe with 2 1/2" brass cap stamped PLS 492 1980  
from which:  
A PK nail in a 5' x 6.5' x 4.5' high boulder bears N.57°35'W., 98.8 ft.  
5/8" x 24" Iron rod bears S.68°29'W., 19.65 ft.  
5/8" x 24" Iron rod bears N.74°53'E., 25.58 ft.  
A 14" Fir bears S.52°E., 316.8 ft. scribed T22S R5W S28.

SEE COR. #4

12/80

163

1/4 Corner for Sections 25 and 36.  
Found - BLM brass cap leaning against NW bearing tree.  
34" incense cedar (original) bears N.42°W., 52 lks.  
5/8" iron rod bears N.42°W., 11.89 ft.  
Set - Drove 5/8" x 40" rebar at orig. point for 1/4 corner.  
This point in road about one foot from bank.  
Set BLM brass cap stamped W.P. 17 ft. bearing N.59°49'E., 17 ft.  
from 5/8" rebar.  
New BT - 26" Douglas Fir bears N.59°49'E., 38 ft.

RE-RENEWED SEE CORNER NO. #169

3/10/81

165

Stephen J. Flause  
Deputy, Doug. Co.  
Surveyors Office  
Karen Mosley  
May 13, 1981  
C.S. 61/24

West 1/16 Corner for Secs. 25 and 36  
Found - A 5/8" iron rod as set by Haines (M 80 - 54) is firmly set and  
protrudes 9" from the ground.  
A 40" D. fir now a fir stump, 40" in diam. and 30" tall with  
a metal weather protection cap, bears S.51°E., 62.4 ft. and  
scribing "BT" visible on a partially healed single blaze.  
A 14" D. fir now a fallen 14" DBH D. fir bears S.60°W., 32.4 ft.  
with the scribing "1/16 S36 BT" visible on a partially healed  
single blaze.  
Set - Haines monument is accepted as found.  
New BT's - A double trunk Maple with an average DBH of 30" bears S.20 1/2°W.,  
61.2 ft. and is bark scribed W 1/16 S36 CS BT.  
A 32" DBH D. fir bears S. 71 1/2° W., 36.3 ft. and is scribed  
W 1/16 S36 CS BT on a double blaze.  
Bearing tree tags are placed on new BTs and the fallen 14" Fir.

5/13/81