

Douglas County Surveyor's Record of
Government Corners Renewed

T 22

T. S.

R 5

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97501

Cont - - - -

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 16, 1992
C.S. File 64/24

8" now 22" dia. D.Fir with a fully healed double blaze,
bears N.72°E., 56.0 ft. (agrees w/rec) Ren. No. 60
10" now 14" dia. B.Oak with a fully healed double blaze, bears
S.28°W., 18.8 ft. (agrees w/rec) Ren. No. 60
8" now 11" dia. W.Oak with a fully healed double blaze, bears
N.2°W., 10.0 ft. (agrees w/rec) Ren. No. 60
20" now 39" dia. W.Oak with a fully healed blaze, bears
S.7½°E., 97.9 ft. (Rec. S.7½°E., 95.7 ft. dist. is a face
measurement) Orig. BT.
24" now 24" dia. 1½ ft. high rotted Oak stump with a rotted
blaze, no scribing visible, bears S.13°W., 138.6 ft. (agrees
with record) Orig. BT.

Randall W. Smith and Stephen J. Flause set DCSO 1990 BC/IP during Control
Survey on file in Douglas County Surveyors Office.

FD OK - M121-24 - 11/10/94

197

3/16/92

1/4 Corner for sections 5 & 6
CORNER REPORT ONLY

Found - Haines "T" iron and brass disk.
Fnd BTs- 29" fir, S.51½°W., 26.4 ft. closed face
40" fir stump, S.34½°W., 39.5 ft. - wood rotted out but good face
on bark
Center of root hole of blown down double fir, east 18.5 ft.
no visible varks, but evidence of ax work where tree had
chopped open previously.

198

3/19/92

Donald Peel
For : Weyerhaeuser
PLS NO. 752
Feb. 1992
M 114 - 60

Section Corner for Sec's 4, 5, 8 and 9.

Found - 3/4 " rebar See renewal no. 112
Fnd BTs- 24" fir, N.24°E., 49.1 ft. - closed face
12" fir stump, S.30¼° E., 54.5 ft. - visible scribe.
22" fir, S.41¼°W., 103.0 ft. - closed face.
10" oak, N.5°W., 102.1 ft. - closed face.
22" rotted fir stump, N.41°W., 32.8 ft.

199

3/19/92

1/4 Cor. Section 30; and 25 of T22-6

Set - 5/8" x 30" rebar with yellow plastic cap mkd. "Branch Eng. LS
1138".

200

From which -

34" Cedar bears S.56°W., 204.2 ft. scribed "1/4 S25 BT".
9" Oak bears N.82°E., 154.0 ft. scribed "1/4 S30 BT".
10" Oak bears N.84°E., 177.5 ft.
22" Ash bears N.86°W., 241.4 ft.

11/25/92

Section Corner for 30 & 31; 25 & 36 of T22-6

Set - 5/8" x 30" rebar with yellow plastic cap mkd.
Branch Eng. LS 1138.

201

From which -

(4) 5/8" x 30" rebars with red plastic caps mkd. "ref. Mon.
LS1138" bearing:
N.60°W., 22.43 ft.
S.1°30'E., 18.96 ft.
S.89°30'E., 59.44 ft.
N.12°W., 65.60 ft.

11/25/92

Center 1/4 Cor. Sec. 24

Set 5/8" x 30" rebar with yellow plastic cap marked "Branch Eng LS 1138".
Corner was set at intersection point of the lines through the opposite 1/4
corners of section 24.

202

NEW BTS - 33" Fir, bears N34°E., 43.7 ft. scribed C1/4 S24 Bt with PK Nail
& brass washer "LS 1138"
19" Fir, bears S.52°E., 45.4 ft. scribed C1/4 S24 Bt with PK
Nail & brass washer "LS 1138"

(Cont. Next Page)

James Branch
For: US National
Bank
Jun. 8, 1993
M 117-14; C.S. 63/153

FD OK
By K. Hoffine
M120-79
8/94