

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 6 R. W. W. M.

✓ N.W. EXTER. CORNER THOS. STILLWELL D.L.C. # 45 22  
I identified this location from an original B.T. bearing proper scribe marks. This is a 50" Fir which I chopped down to find the scribe marks. I set a 3/4" x 36" pipe 34" in ground for corner N.80°E. 26 lks. from this orig. B.T. Scribed a 14" Fir, S.80°W. 73 lks. T.22S. R.6W. Cl. 45 C.S. B.T. as a new B.T. Also remarked a 14" Fir, S.84°E. 82 lks. C.S. This tree had been scribed about 30 years ago by someone but not recorded. (Thiel - sec C.S. 64/48 Pg 13) D.C. 50. 11/30/98

April 16-19 Incl.  
 Pen P. Irvine D.C. 5.  
 R. L. Irvine  
 Jess Widly  
 Witnesses  
 C.S. File 2/19  
 1928

✓ N.W. INTER. COR. THOS. STILLWELL D.L.C. # 45 23  
I identified the location of this corner by both original B.T. alive and standing. Scribe marks visible and in good condition. This corner comes at the intersection of an old N. & S. rail fence and a board fence running W. Drove an iron pipe 3/4" x 36" for corner. Set 1 new B. T.

SECTION CORNER SECS. 13-14-23-24 24  
I identified the location of this corner by a stake set by Surveyor Thiel also 2 original B.T.s  
 A 7" Oak S.85°E. 87 lks. dist. and  
 A 7" Oak S.68° W. 32 lks. dist.  
 A. B. Oak bears N.73°E. 233 lks. which appears to be an O.P.F. blazed have been chopped out and marks obliterated Recorded as N.63°E. 133 lks.  
 Set 3/4" x 36" pipe for corner and new B.T.s  
 A 14" Fir N.45E. 51 ft. dist. scribed S.13T.22S. R.6W. C.S. B.T.  
 A 10" Fir S.35°E. 13.5 ft. dist. scribed S.24 T22S. R.6W. C.S. P.T.  
 A 18" Fir S.30°W. 37.3 ft. scribed S.23 T.22S. R.6W. C.S. B.T.  
 A 6" Fir N. 85°W. 26 ft. scribed S.24 T.22S. R.6W. C.S. P.T.

C.S. Vol. 3 P 284

Witness Cor. to S.W. Cor. of D.L.C. #37 25  
Iron Strap as described by rear some rock around  
Set 3"x 7"x 7' 5 Ft. in ground  
Cedar Post  
Scribed W.C. S.W. Cor. D.L.C. #37  
Marked 12" Fir N. E. 35.5 ft.

Nov 7 1944  
 Ben B. Irvine  
 M.E. Godfrey

1/4 COR. BETWEEN 10-15 26  
Set from 20" O. B. T. and X on old bridge, which was made when Reset in April 16, 1928. ~~REN # 16~~  
Set 1" x 40" Steel Rod for corner.

N.E. Richardson  
 Survy.  
 M.E. Godfrey  
 F.D. Smith - Wit.  
 May 1949

N.E. COR. CHAS. PUTNAM D.L.C. Iron pipe	N.W. COR. CHAS. PUTNAM D.L.C. Iron pipe
1/4 SEC. COR. BETW. 10 - 11 Iron pipe	1/4 SEC. COR. 9-10 Stone
SEC. COR. 2-3-11-10 Iron pipe	SEC. COR. 3-4-9-10 Iron pipe
1/4 SEC. COR. BETW. 2-3 Iron pipe	N.W. COR. JAS. PUTNAM D.L.C. Stone
1/4 SEC. COR. BETW. 3-10 Iron pipe	N.W. COR. DAISLEY D.L.C. Stone
1/4 COR. N BDY. 3 Bolt	N.E. COR. DAISLEY D.L.C. Stone
NW COR SEC. 3 Iron pipe	1/4 SEC. COR. BETW. 8-17 RR rail
1/4 COR. 4-9 Bolt	SEC. COR. 8-9-16-17 Bolt
1/4 COR. 4-5 Bolt	S.W. COR. J. PUTNAM DLC Iron rod
SEC. COR. 4-5-8-9 Iron rod	SW INT. COR. J. PUTNAM DLC Bolt
N 1/6 betw. 8-9 Iron rod	

PLAT DATA  
ONLY

Corners as shown on plat of Sunnydale Orchards as filed August 6, 1914.