

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

105

Section Corner to Sections 8 - 9 - 17 - 16:

Found - Iron Bolt $\frac{3}{4}$ " diam, with square head $1\frac{1}{4}$ " sq.

Fir Snag, 36", S.35°W. 27.7 ft. No scar or scribing visible.

Fir Log, nearly buried in fill, base of which bears N.15°W. 19.8 ft.

Remnants of Cedar stump bears S.56°E. 30.4 ft. Too far gone to find scars or scribing - No trace of N.E. BT.

Alongside Bolt Set Brass Cap Mkd: County Surveyor's T22S R6W $\frac{S8}{S17} \frac{S9}{S16}$
Office, 1961

New BT's: 8" W.Oak N.10°E. 766 ft. Mkd: T22S R6W S 9 CS BT.

7" Maple, in clump of maple, N.49°W. 32.5 ft. Mkd: T22S R6W S8 CS BT.

8" W.Oak S.66 $\frac{1}{2}$ °W. 31.7 ft. Mkd: T22SR6W S17 CS BT.

14" Ash S.73 $\frac{1}{2}$ °E. 28.1 ft. Mkd: T22S R6W S16 CS BT.

Corner lies approx, 100 ft. South of centerline of Highway No. 38.

106

$\frac{1}{4}$ Sec. Corner to Sections 5 and 8.

Found - $\frac{3}{4}$ " Bolt with $1\frac{1}{4}$ " sq. head. - Fir Snag, now 34", N. 5°W. 31.7 ft. to face. Shows 2 good scars. Did not cut open.

Cedar tree, now 48", S.17°W. (instead of S.27°W) 18.5 ft. to face.

This tree has been opened previously & good scribing $\frac{1}{4}$ " visible.

Alongside Bolt Set Brass Cap Mkd: County Surveyor's T22S R6W $\frac{S5}{S8}$
Office, 1961

New BT's: 7" D.Fir N.74°E. 19.3 ft. Mkd: $\frac{1}{4}$ S 5 CS BT.

6" D.Fir S.40°E. 22.1 ft. Mkd: $\frac{1}{4}$ S 8 CS BT.

107

Section Corner to Sections 6 - 5 - 7 - 8.

Found - $\frac{3}{4}$ " x 14" Iron Rod. - Fir Tree, now 23", S.23°E. 11.2 ft., shows good scar, blaze & rescribe "T22S R6W S8 CS BT".

Short Fir Snag, 18", N.63°E. 23.1 ft. scribing visible "S5 S22".

Rotted Fir Snag S.44°W. 23.1 ft., good scar but no scribing found.

Stump Hole N.59°W. 19.1 ft.

Alongside Iron Rod Set Brass Cap Mkd: County Surveyor's T22S R6W $\frac{S6}{S7} \frac{S5}{S8}$
Office, 1961

New BT's: Rescribe S.E. BT. (see above)

26" D.Fir N.41°E. 21.4 ft. Mkd: T22S R6W S5 CS BT.

No other trees near.

108

$\frac{1}{4}$ Corner to Sections 4 and 9.

Found - $\frac{3}{4}$ " Bolt at Corner with 1" sq. head. - Rotten Stump of Fir N.14°E. 191.1 ft. Good scribing "BT".

Badly burned Fir Stump S.20°E. 35.0 ft., shows evidence of having been opened previously, no scribing found.

Alongside Bolt set Brass Cap Mkd: County Surveyor's T22S R6W $\frac{S4}{S9}$
Office, 1961

New BT's: 10" D.Fir N.12°W. 137.0 ft. Mkd: $\frac{1}{4}$ S 4 CS BT.

9" W.Fir S.14°E. 113.3 ft. Mkd: $\frac{1}{4}$ S 9 CSBT.

109

Section Corner to Secs. 4 & 3, T22-6W. & Secs. 33 & 34, T21-6W.

Found - $\frac{1}{2}$ " I. Pipe & 28" W.Fir S.40°W. with rotten center & no scribing left visible, 29.0 ft. from I. Pipe, record 35.0 ft. W. Haines says he has seen scribing on this tree.

No other trees found.

Set - Brass Cap Mkd: County Surveyor's $\frac{S33}{S4} \frac{S34}{S3}$ T21-6W 123
Office, 1961 T22-6W

New BT's: 14" D.Fir N.17°E. 10.7 ft. Mkd: T21S R6W S34 CS BT.

10" Yew N.48°W. 49.4 ft. Mkd: T21S R6W S33 CS BT.

26" D.Fir S. 3°W. 37.3 ft. Mkd: T22S R6W S3 CS BT.

15" D.Fir S.72°W. 30.4 ft. Mkd: T22S R6W S 4 CS BT.

110

$\frac{1}{4}$ Corner to Sec. 12, R6W & Sec. 7, R5W.

Found - $\frac{3}{4}$ " Pipe at corner as called for in former renewal. - REN. #60

12" Maple S.83°E. 46.0 ft. = 72" Fir S3°E. has blown down.

New BT: 32" Fir North 52.8 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Clete Putnam
September & October, 1961
C. S. File No. 49/143