

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

118

Wilford N.
Haines
June 1966
C.S. File
No.
51/309

Section Corner to Sections 4 - 5 - 8 - 9.
This section corner in danger of being destroyed by
Road Construction. Therefore, I put in reference points.
Found - Douglas Co. Brass Cap (Ren.#103) & 1" Iron Rod.
Set - Survey Point Disk on 48" Fir S. $83\frac{1}{2}^{\circ}$ W. 22.0 ft.
Survey Point Disk on 10" Fir S. $75\frac{3}{4}^{\circ}$ E. 88.82 ft.
"T" Iron S. $75\frac{3}{4}^{\circ}$ E. 41.91 feet from corner.

June 10, 1966

119

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
Sept. 1, 1966
C. S. File No. 54/14

Township Corner:
Found - Haines' "T" Iron, See Ren. #64, under a 16" Log, set from
Orig. BT, as follows:

Orig. 20", now 28" Fir Snag, N. 59° E. 37.6 ft. Open & find
"31 T21 6W" scribe.
All other BT's. destroyed.

Set - Brass Cap 6 in. South of "T" Iron alongside Log & Mkd:
County Surveyor's Office, 1966
T 21 S R7W S 36 S 31 R6W
T 22 S S 1 S 6
New BT's: 7" Hemlock N. 26° W. 13.2 ft. Mkd: T21S R7W S36 CS BT.
9" Hemlock N. 80° E. 24.9 ft. Mkd: T21S R6W S31 CS BT.
26" R. Cedar S. 61° E. 29.9 ft. Mkd: T22S R6W S 6 CS BT.
No suitable tree close to SW.

Note - Corner lies on steep, N. W. slope.

MICROFILM TO HERE 10/67

120

John M. Powell
Frank Jones
& W. Penley
2/13/68
C.S. 49/143

Section Corner to Sections 11 - 12 - 13 - 14.
Found - 2" Iron Pipe at Section Corner, tied from survey C.S. File 43/142.
Set - Brass Cap alongside I.P. Mkd: County Surveyors Office, 1968
T 22 S R 6 W S 11 S 12 S 14 S 13
New BT's: 8" D. Fir N. 34° E. 31.3 ft. mkd. T22S R6W S12 CS BT.
28" Maple N. 25° W. 49.7 ft. mkd. T22S R6W S11 CS BT.
11" D. Fir S. 50° W. 71.7 ft. mkd. T22S R6W S14 CS BT.
Power Pole #6-54 S. 59° E. 19.9 ft. P.K. Nail in base of pole.
2/13/68

121

Closing Corner to Sections 31 and 32.
Found - 1955 Cadastral Brass Cap, nearly out of ground, properly
marked with Haines' "T" Iron alongside. See Ren. #113.
We Reset Brass Cap.

Haines' BT's: 18" Fir N. $36\frac{1}{2}^{\circ}$ W. 45.4 ft. now dead-scribe visible-
overgrowth of 9 rings.
24" Fir stump N. 20° E. 48.1 ft. scribe visible.
Orig. Cedar BT gone-stumphole & turned out tree to
N.W. still in evidence-we mark New BT.
New BT: 12" Hemlock N. 6° W. 47.8 ft. Mkd "T 22 S R6W S31 CC
CS BT"

No Trees close to NE-This corner lies on very steep Northerly slope
about 350 ft. South of Squaw Creek. 12/23/69

122

Standard Corner to Sections 6 & 5, T.23S. R.6W.
Found - 1955 Cadastral Brass Cap, nearly out of ground-properly marked.
Orig. 54" Fir S. 25° E. 5.3 ft., now stump-blaze burned.
1955 16" now 17" Hemlock S. 29° E. 52.1 ft., now broken off 8 ft.
above ground, record dist. 31.0 ft.
No trace of other BT's. WE Reset Brass Cap. Ren. #114

New BT: 16" Hemlock N. 28° E. 18.0 ft. mkd "SC CS BT".
No Trees south of corner-This corner lies on steep Northerly Slope
about 100 ft. South of Squaw Creek course West. 12/23/69

MARCH 71

FD. 10/90
C.S. 63/127

Vernon "Ray" Tracy
Jack Heritage & V. Perron
C. S. File No. 49/143

SEPT. 68

FD. OK
3/90
M108-14
7/16/77
WILL BE CUT - STUMP
DESCRIBING INTACT.