

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

129

M. Lenora Ladig
A. Vic Cangie
Surveyors Office
March 3, 1976
C.S. 59/8

Section Corner for Secs. 7, 8, 18 and 17
Found - Haines T-Iron and cap in mound of rock. Ren. # 70
An orig. 24" now 26" Maple showing scar. (tree is dying) bears,
S.22°W., 28.0 ft.
An 18" now 24" Fir, alive and well healed bears, N.40°W., 15.8 ft.
A 60" Fir stump. Found no trace of scribing, bears, S.32 1/4°W.,
37.6 ft. to face.

Set - At corner point a 1 1/2" x 30" Iron pipe with brass cap marked:
Douglas County Surveyor 1976
T 22 S R 6 W
S 7 | S 8
S 18 | S 17

with Haines T-Iron on west side. Corner falls in N-S fence line.
New BT's - A 8" Grand Fir scribed "T22S R6W S7 CS BT" in double blaze bears,
N.29°W., 37.8 ft.
A 10" Grand Fir, scribed "T22S R6W S18 CS BT" bears, S.70°W.,
105.4 ft.

No trees near east of line. Compass dec. 20° east.
FD OK, Dec. '94, M121-43 3/3/76

130

Donald Stone, Green
Empire, Inc.
For: Don Churchill
Jan. 1976
M 60 - 60

1/4 Corner for Sec. 1 and Sec. 6, T22-5
Set - 1/2" Iron Pin
BT's - 8" Oak, bears N.61°E., 51.9 ft. scribed.
12" Alder, bears N.06°W., 17.6 ft. bark scribed.

Jan. 1976

1/4 Corner for Secs. 16 and 21. 131
Found - BLM Cadastral Brass cap properly mkd. and firmly set at toe
of road fill (#22-6-15.0)

From which: Ren. #124
A 39" Fir stump bears N.55 1/2°E., 3.0 ft. with visible "S16"
scribing.
A 10" D. Fir snag bears N.30°W., 69.2 ft. with "1/4 S16 CS BT"
visible on unhealed blaze.
A windfall 12" D. Fir bears N.21°E., 65.2 ft with visible
"1/4 S16 CS BT" on unhealed blaze.
New BT's - A 16" D. Fir bears N.3°W., 65.3 ft. mkd. "1/4 S16 CS BT" in a
double blaze.
A 15" D. Fir bears N.33°W., 94.6 ft. mkd. "1/4 S16 CS BT".
Note - There are no available trees to scribe in Sec. 21 as area is in
clear cut. Corner is approx. 30 ft. north of BLM Rd. #22-6-15.0.
12/22/76

132

1/4 Corner for Sec. 13 and Sec. 18 of T22-5.
Found - A 7" now 20" B. Oak, alive with well-healed double blaze. Ren. #62
A 15" now 16" B. Oak, alive with well-healed double blaze.
A 1" x 3" x 32" channel iron mentioned in Ren. #62, lying on its
side and buried under a N-S fence.
At the corner point as determined by Byron's BT's in Ren. #62:
A 20" B. Oak bears N.8 1/2°E., 19.8 ft. and a
16" B. Oak bears N.18 1/2°W., 168.2 ft.

We Set - A 1" x 30" I.P. 25" in the ground with brass cap attached mkd:
Douglas County Surveyor R T 22 S R
1976 6 S 13 | S 18 5
W 1/4 W

We place the found channel iron along the north side of the brass cap.
We do not identify any orig. corner accessories..
This corner is located in a N-S fence line.

12/27/76

133

1/4 Corner for Secs. 33 and 34.
Found - Orig. Stone 3" above ground "1/4" marked on west face. Brass
cap along SE edge of stone is marked "County Surveyors Office"
T22S R6W 1/4 S33 S34 1961. Ren. #82
Orig. 20" now a 36" Cedar stump, bears N.31°W., 7.3 ft. (orig.
S131°W.) Stump is broken off, no scribing visible.
No other BT's found as area has been logged.
Set - Bridge spike in a 42" R. Cedar stump. Spike bears N.71°W., 41.5 ft.
A D. Fir 10" bears S.74 1/2°E., 35.3 ft. Tree double blazed and
scribed "1/4 S34 CS BT".
Note: This corner lies near a N S cutting line. Corner is in clear cut to
the west of line approx. 30 ft.

A. Victor Cangie; Gary L. Langlitz
Mike Tompkins
Karen Cheney
Douglas County Surveyors Office
December 22 & 27m 1976
C.S. 59/26

FD OK 4/19/84
M. HAVIL
C.S. 59/14

3-77

Larry E. Monrean
P.L. Earle
Doug. Co. Surveyor
April 21, 1977
C.S. 59/31

Jan 1978