

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

134

1/4 Corner for Secs. 13 and 24.

Found - No trace of orig. post found.

We find 3/4" I.P. flush in the ground. Ren. #20

1" x 1" T-Iron, extending 18" above ground alongside 3/4" I.P. with copper washer attached marked "Wilford N. Haines 239 Survey Point Drain, Oregon" Ren. #46.

No trace of original BTs found.

A 20" now 40" D. Fir alive and in good condition with well healed double blaze bears S.16°E., 145.9 ft. Ren. #20

A 15" Fir, now a 29" stump with well healed double blaze bears N.45°W., 93.8 ft. (Rec. N.47 1/2°W., 92.8 ft.) Ren. #20.

Set - A 1" x 30" I.P. 28" in the ground with brass cap attached marked: Douglas Co. Surveyor T22S 1/4 S13 S24 R6W 1978.

We place found 3/4" I.P. and 1" T-iron alongside brass cap.

New BT - A 16" D. Fir scribed "1/4 S13 CS BT" on a double blaze bears N.36 1/2°E., 22.2 ft.

Corner located near corner of random fences running N & E approx. 40 ft. West of an old road running NE-SW and approx. 60 ft. east of a small draw, course NE.

Gary Langlitz  
F.C. Silagy  
Doug. Co. Survey-  
ors Office  
March 1978  
C.S. 59/46

3/28/78

135

1/4 corner for Secs. 9 and 16.

Set - Brass cap mkd. T22S R6W WM 1/4 S9, S16, 1978

From which:

24" White Oak scribed "1/4 S S9 BT" bears N.78°W., 163.4 ft.

No trees in Sec. 16 were within range.

Set steel fence post along side corner which falls in field.

6/26/78

Bruce A. Shaner  
For: Mazama Timber  
Products Inc.  
June 26, 1978  
R M 3 - 16

136

Center 1/4 of Section 16.

Set - Brass cap mkd. C 1/4 1978

From which:

28" Oak, scribed "C 1/4 BT" bears N.26°E., 296.3 ft.

16" Oak scribed "C 1/4 BT" bears S.85°E., 131.6 ft.

Set steel fence post along side corner which falls in field.

6/26/78

137

1/4 corner for Sec's. 1 & 2.

Found - 30" dia. stump, decayed (orig. 8" Fir). We open stump and find good scribing " BT ". Other orig. BT not found.)

Set - Brass Cap on a 1" x 30" I.P., set at record bearing & distance of found orig. bearing tree (tree bearing S.58°W., 47.5-ft.), stamped, Douglas County Surveyor T22S R6W 1/4 S2 S1 1981 set 22 in ground.

New BT's  
18" W. Oak blazed & scribed 1/4 S1 CS BT bears S.17°E., 7.5-ft. Aug. 27, 1981  
13" W. Oak blazed & scribed 1/4 S1 CS BT bears S.72 1/2 °E., 47.9-ft. CS. 61 / 27  
11" W. Oak blazed & scribed 1/4 S1 CS BT bears N.52 1/2 °E., 17.5-ft.  
12" B. Oak blazed & scribed 1/4 S2 CS BT bears N.0 1/2 °W., 34.3-ft.

Note - Fence corner S48 1/2 °W., 30.0-ft. Fence running N-S-E.

8/27/81

Larry E. Monrean, Dep.  
Douglas County  
Surveyors Office  
T.R. Plouff,  
Robert G. Dean,  
Don Churchill,  
witnesses.

137

REPORT ON SAME CORNER AS ABOVE:

Set - 1/2" x 24" iron rebar from which:

a rotted 30" fir stump, "BT" visible at base of 8" pitched core, bears S.59°05'W., 47.52 ft. (rec. S.58°W., 47.52 ft.). The bearing is oriented to the south 1/2 mile of the section line and matches the compass bearing by the Doug. Co. Surveyors Office.

a 1" Galv. I.P. with 2 1/2" brass cap by D. Co. Surveyors office 1981 bears S.59°W., 2.32 ft.

an old fence bears west 25 feet.

an old fence bears south 21 feet.

8/28/81

Robert G. Dean  
L.S. 1808  
For: Don Churchill  
Aug. 28, 1981  
M 88 - 65

1/4 CORNER REPORT CONTINUED:

Note: It was pointed out by R. Dean L.S. 1808, that a measuring error was made on our previous ren. (date 8/27/81) while setting brass

L.E. Monrean  
Doug. Co. Surveyors  
Office  
9/8/81 C.S. 61/27