

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21981

137

C O N T - - - -

(1/4 Cor. Secs. 1 and 2)

cap monument from found bearing tree stump. The following is an account of our correction procedure.

Found: A Doug. Co. Surv. Off. brass cap monument set 8/27/81.  
A 1/2" x 24" I.R. set by Dean. (M 88 - 65 and C.S. 58/204)  
A check of the orig. bearing and distance to the found BT stump agrees with the position of the 1/2" I.R. set by Dean to mark the true quarter corner position.

Set - WE REMOVE the 1" x 30" I.P. with attached brass cap and replace it with a 5/8" x 30" I.R. with attached alum. cap.  
WE SET the I.P. monument at the true quarter corner position; cap marked "Douglas County Surveyor" T22S R6W 1/4 S2 S1 1981.  
Set found 1/2" x 24" I.R. along south edge of brass cap monument.  
The Orig. 8" Fir now 30" dia. fir stump scribed "BT" bears S.58°W., 47.5 ft.  
The 5/8" x 30" I.R. with alum. cap (set to mark old position of cap) bears S.58°W., 2.3 ft.

BT's - New bearings and distances to trees scribed Aug. 27, 1981:  
A W. Oak, 18" blazed and scribed "1/4 S1 CS BT" bears S.0 1/2°E., 8.3 ft.  
A W. Oak, 13" blazed and scribed "1/4 S1 CS BT" bears S.70°E., 46.6 ft.  
A W. Oak 11" blazed and scribed "1/4 S1 CS BT" bears N.52°E., 15.4 ft.  
A B. Oak, 12" blazed and scribed "1/4 S2 CS BT" bears N. 2 1/2°W., 33.1 ft.

Fence corner bears S.50°W., 32.6 ft. Fence lines run north, south and east. 9/8/81

Southwest corner Section 1  
CONDITION REPORT ONLY.

Found - An oak root crown and charred stump bears N.40°00'E., 26.40 ft.  
Ashen remains of large fir stump bears S.58°21'W., 8.85 ft. (orig. record 30" R. Fir, S.67°W., 8.58 ft.) (1855 GLO notes)  
Old fence corner post bears S.53°E., 0.91 ft. (f-way intx.)  
New fence corner post bears N.58°E., 0.86 ft.  
an Oak stump (not BT) bears N.36°09'E., 27.57 ft.  
Ridge top bears west 184 ft. (record West, 283.80 ft.)

RE-RENEWED, SEE CORNER NO. 144

138

Robert G. Dean  
L.S. 1808  
For: Don Churchill  
August 28, 1981  
M 88 - 65  
C.S. 58/204

EVIDENCE NOT CONSIDERED CONCERNING EVIDENCE OF ORIG. CORNER TO PERPETUATE. L. MONREAN SURVEYOR 9/16/81

SEE CS 61/27

139

1/4 corner common to Sec. 24 and Sec. 19 of T.22-5.

Found - 26" W. Oak (orig. BT), well defined old face, partially covered with new growth of proper age, no scribes visible, bears S.74°W., 15.2-ft. See M 90 - 2 for additional notes.

Set - Brass Cap marked "T22S R6W R5W, WM 1/4 S24 S19 RLS 430, 1981" from which, the above BT bears.

New BT's-28" W. Oak, I scribed "1/4 S 19 BT", bears S.79°E., 26.3-ft.  
6" D. Fir, I scribed "1/4 S 24 BT", bears N.67°W., 26.5-ft.

Note - 24" W. Oak (orig. BT) that was N.57°E., 81.2-ft. is now gone. 8/81

Bruce A. Shaner  
RLS 430  
For: Eagles View  
Management Co., Inc.  
August, 1981  
M 90 - 2

140

cc.  
Sec. corner for Sec's. 30 and 31.

Found - Brass Cap on a 1" Iron Pipe, properly marked, firmly set, and protruding 8" above ground.

BT's - Orig. 36" Cedar, rescribed by Byron (Ren#63): "T22S R6W S30 BT" legible. This tree now a badly decayed stump with debris piled against it. Stump bears N.83°E., 155.7-ft. to approx. center (Rec. N.83°E., 156.4-ft.).

The orig. 48" Fir, now a decayed stump with no scribing or blaze remaining bears S.29°E., 96.1-ft. to approx. center (Rec. S.30°E., 93.1-ft.).

Snag (orig. 55" Cedar) scribed "T22S R6W CS BT" bears S.76°E., 128.0-ft. (scribe visible).

New BT's-12" D. Fir scribed "T22S R6W S31 CS BT" on double blaze, bears S.28°E., 89.6-ft.

14" D. Fir scribed "T22S R6W S30 CS BT" on double blaze, bears N.88 1/2 °E., 46.5-ft.

16" D. Fir scribed T22S R6W S30 CS BT" on double blaze, bears N.71°E., 42.8-ft.

Note - Haines "T" Iron bears S.8 1/2 °E., 6.25-ft.

Larry E. Monrean  
Deputy Doug. County  
Surveys Office  
T.R. Plouff  
Sept. 21, 1981  
C.S. 61 / 27

9/21/81