

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Larry E. Monrean  
Deputy Doug. County  
Surveyors Office  
T.R. Plouff, witness  
Sept. 17, 1981  
C.S. 61 / 27

141  
Sec. corner for Sec's. 25 and 36 of T.22S.R.7W. only.  
Found - Brass Cap on a 1" Iron Pipe, properly marked, firmly set, protruding 12" above ground.  
BT's - 31" Fir (orig. 20") bears N.71°W., 93.1-ft. rescribed <sup>see T22-7</sup> Ren. #64.  
The scribed "S" visible in partially healed blaze. Tree is uprooted.  
New BT's-22" W. Fir scribed "T22S R7W S36 CS BT" on double blaze bears S.37°W., 22.2-ft.  
16" D. Fir scribed XBO CS BT on double blaze bears S.30 1/2 °E., 38.0-ft.  
16" D. Fir scribed "T22S R7W S25" on double blaze bears N.25 1/2 °W., 52.8-ft.

9/17/81

142  
1/4 Corner for Secs. 25 and 36  
Found - 1/2" I.P. firmly set flush with ground with 3/8" I. rod alongside protruding 18" above ground. Ren. #55  
Orig. 30" black oak now 48" rotted snag approx 25 ft. tall with scribed "1/4" visible on previously opened face bears N.87 1/2°E. 330.2 ft. (rec. N.89°E., 330.7 ft.)  
26" black oak now 36" with good scars bears S.20°E., 223.3 ft. (rec. S.19°E.) Ren. #55  
15" black oak now 24" with good scars bears N.81 1/2°E., 218.8 ft. (rec. N.83°E.) Ren. #55  
Set - At the location of found 1/2" I.P. I set a 1" x 30" I. pipe with brass cap attached protruding 10" out of ground, cap marked: "Douglas Co Surveyor T22S R6W 1/4 S25 S36 1982".  
I place 1/2" I.P. alongside. 3/8" I. rod also placed alongside.  
New BT - 38" cedar scribed "1/4 S 36 CS BT" in double blaze bears S.56 1/2°E., 222.6 ft.  
BT tags put on all trees. Sketch in C.S. file.

Gregory Quibell, Deputy  
Doug. Co. Surveyors Off.  
K. Reed  
J. Powell  
Aug. 3, 1982  
C.S. 62/1

8/3/82

Gregory Quibell  
Deputy Doug. Co.  
Surveyors Office  
Randy Smith  
Nov. 15, 1982  
C.S. 62/1

143  
1/4 Corner for Sections 12 and 13  
Found - Haines "T" iron with copper cap. Ren. #47  
Orig. 6" (maybe 36") now 40" fir with well healed blaze. Also bark scribed "1/4 S12 CS" bears N.14°E., 21.8 ft.  
16" W. Oak now 26" rotted remains of stump bears South, 94.8 ft. Ren. #18  
25" fir, now windfall with partially healed blaze bears N.46°W., 25.8 ft. to root hole. Ren. #126  
Set - I reference found "T" iron, then set 1" x 30" I. pipe with brass cap in its place. Cap marked Douglas Co Surveyor T22S 1/4 S12 S13 R6W 1982". I reset found "T" iron along south edge of brass cap and slightly lower.  
New BTs -15" fir scribed "1/4 S12 CS BT" in double blaze bears N.30°W., 86.9'  
6" W. oak scribed "1/4 S13 CS BT" in double blaze bears S.56°E., 6.8 ft.  
8" double W. oak scribed "1/4 S13 CS BT" in double blaze bears S.70°E., 23.0 ft.  
DCSO BT tags on all trees. Sketch in file

11/15/82

L.E. Monrean, L.S. #1830  
Deputy, Doug. Co. Surveyors Off.  
Witness: J.R. Lundeen  
August 29, 1983  
C.S. 62/9

144  
Section corner for Secs. 2, 1, 11 and 12.  
(Note: See 1981 survey by Dean, M88-65 (Ren. #138) and C.S. file 58/204. Also see "not found" report dated 9/16/81 in C.S. file 61/27)  
Found - No original monument found.  
Found 4-way intersection referenced by Dean's 1981 survey.  
Set - Temporary hub at position, N.53°W., 0.91 ft. from old fence post and S.58°W., 0.86 ft. from new fence post.  
Found - Orig. Oak, now a charred root crown, bears N.40°E., 26.4 ft., no scribing found.  
Evidence of a charred root system at position of original 30" dia. fir, bears S.67°W., 8.6 ft.  
Note: The attached letter and map (See C.S. 62/9) from the U.S. Geological Survey Mapping Division, show a scribed post at the fence intersection in 1952. With this additional information and evidence found on location, we determine to set a monument at the referenced position.  
Set - A 1" x 36" iron pipe with brass cap, protruding 12" above ground. Cap marked: Douglas Co. Surveyor T22S R6W S2 S1 S11 S12 1983