

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 22 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Closing Corner for Secs. 31; and Section 36 of T.22-7
CORNER REPORT ONLY

Found - Corner is a 1956 GLO brass cap 1.0 ft. above ground in good condition.
18" D. fir bears N.38½°E., 60.0 ft. well healed face. We tag.
42" D. fir bears N.39°W., 49.5 ft. well healed face and BT tag.
38" D. fir stump (covered with tin) bears N.16°W., 23.5 ft. scribing visible. NO RECORD. Has BT tag.
Haines T-Iron bears S.38½°E., 14.0 ft. Ren. #27
Painted faces and wrote BT on tree trunks of BTs with flourescent orange paint.
Corner sits on 40% west slope approx. 100 ft. east of Brush Creek Rd.

RENEWED, SEE CORNER NO. #159

155

Ken Hoffine
For: Lone Rock
Timber Co.
Gary Angiolet
Oct. 1990
C.S. 63/127

Closing Corner for Sections 31 and 32 only.

Found - Corner is a GLO brass cap with Haines T-Iron along side.
Corner is loosely set in rock.
12" W. F (rec. Hemlock) bears N.6°W., 47.6 ft. Well healed face and BT tag. Ren. No. 121
New BT - Put Lone Rock Timber Location tag on 6" D. F. bearing N.60°E., 24.4 ft.

FD OK 3-91
M 111-72

156

Painted faces and wrote BT on tree trunks of BTs. with flourescent orange paint. Corner lies on steep N. slope near rock face with pile of rocks around corner and Haines T-iron along side. Small stand of 20-40" timber to the N.W. and Squaw Creek bears North approx. 165 ft.

10/90

Section corner for Sections 19 and 30 only. FD OK 2/94 BY HOFFINE
Found - 1961 County brass cap 0.7 ft. above ground in good condition. Ren. No. 95 C.S. 63/154-5

157

Ken Hoffine
For: Lone Rock
Timber Co.
July 1990
C.S. 63/129

9" D. fir bears S.57°E., 9.6 ft. well healed face and BT tag.
48" D. fir bears N.80°E., 13.5 ft. (old bark scribe and chopped out face) and 4 alum. tags.
8" D. fir bears N.30°E (Rec. N.36°E.) 11.6 ft. well healed face and BT tag.

New BT - Put Lone Rock Timber location tag on a 12" D. fir bearing S.77°E., 2.4 ft. Tree is heavily blaze.

Painted faces and wrote BT on tree trunks with flourescent orange paint. Corner lies on south edge of spur ridge sloping NE very steep east side slope approx. 260 ft. west of creek.

7/90

1/4 Corner for Section 25 and 36

158

Found - A ½" I.D. iron pipe approx 30" long, firmly set, but top is bent approx. 4" southerly from plumb. Pipe protrudes approx ½" above ground. Pipe is first noted in Ren. No. 52; origin unknown.
A 2½" dia. 1982 County brass cap on a 1 3/8" O.D. 32" long galv. iron pipe was found out of position and loose on ground surface by property owner Dudley Walton. A 3/8" dia. 25" long round iron bar with a loop on one end is found loose on ground, down slope from above iron pipe. BC monument and iron bar are from Ren. # 142.

Accessories found measured from plumb position of found ½" I.P. No evidence of orig. bearing trees is found. Clearing of field & road work has removed previously found NE orig. BT.

A 26" B.Oak now a 41" DBH B.Oak with a fully healed double blaze bears S.20°E., 223.3 ft. dist. (agrees w/rec. bearing and distance in Ren. No. 142) Ren. No. 55

A 15" B.Oak now 31" DBH B.Oak with a fully healed double blaze bears N.81½°E., 218.8 ft. dist. (agrees w/rec. bearing and dist. in Ren. No. 142) Ren. No. 55

(From Ren. No. 142, all noted bearing trees are found except the noted origi. BT)

A 38" cedar now a 49" DBH incense cedar with a partially healed double blaze showing the partial scribing "CS BT" bears S.56½°E., 222.6 ft. dist. (as per rec) Ren. No. 142

Set - Found 1/2" I.D. iron pipe's plumb position agrees very closely with record bearings and distances to all found BTs; this position is referenced out, the I.P. is removed and the found brass cap monument is placed at this referenced location.

Douglas County
Surveyors Office
Stephen Flause
Terrie Franssen
May 10, 1991
C.S. 64/10

FD OK BY K. Hoffine
M 120-79 8/94
FD OK 12/2/92
S. BEANCH
M 116-29