

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 T. S. R 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

158

C O N T - - -

Doug. Co. Surveyors
Stephen Flause
Terrie Franssen
MaY 10, 1991
C.S. 64/15

The brass cap is stamped to read: "Douglas Co. Surveyor
1/4 S25 S 36 RESET 1991 1982" The monument is now firmly
set and protrudes approx. 2" above ground. The found I.P. is
placed approx. flush with ground on the north edge of the BC.
The found Iron bar is set protruding approx 18" above ground on
the south edge of the BC monument.
New BT - A 7" D.B.H Incense cedar scribed "1/4 S36 CS BT" on a double
blaze bears S.59 $\frac{1}{2}$ °E., 263.5 ft. distant.
Monument lies in open pasture near a bench on a moderate south facing slope
the BC monument is approx. 800 ft. WNW from a small house, barn and corral.
5/10/91

Douglas County
Surveyors Office
Ed Monrean
Randall Smith
Feb. 14, 1992
C.S. File 64/23

Closing Corner Sections 31, T.22-6; and Sec. 36, T.22-7
CORNER REPORT ONLY
Original monument not found.
Found - USGLO brass cap 2" dia., on 1 $\frac{1}{2}$ " O.D. Iron pipe.
Haines T-Iron bears S.3 3/4°E., 13.99 ft. See Ren. No. 155
All bearing trees found as shown on M 111-72 and report in
County Surveyors file C.S. 63/106
No original BTs found.
2/14/92

159

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 24, 1992
C.S. File 64/24

Section Corner for 3 and 4; 33 and 34 of T.21-6
Found - A 2 $\frac{1}{2}$ " dia. DCSO brass cap on a 1 $\frac{1}{2}$ " O.D. Iron pipe protruding
9" above ground. Ren. No. 109
14" now 10" dia. rotted 1 $\frac{1}{2}$ ft. tall D.Fir stump, scribing visible
"31 CS BT" bears N.17°E., 10.7 ft. (agrees w/rec) Ren. No. 109
26" now rotted Fir stump of indeterminable size, no blazes or
scribing visible bears S.3°W., 37.3 ft. (agrees w/rec) No. 109
15" now down and rotted D.Fir, no blazes or scribing visible,
root hole bears s.72°W., 30.4 ft. (agrees w/rec) Ren. No. 109
10" now 12" dia. Yew with a partially healed double blaze, rottin
scribe visible "T21S R5W S33" bears N.48°W., 49.4 ft. (agrees
w/rec) Ren. No. 109
8" now 13" dia. Maple with illegible barkscribing bears S.48°E.,
10.5 ft. (agrees w/rec) Ren. No. 123
New BTs - 13" dia. W.Fir double blazed and scribed "T22S R6W S4 CS BT"
bears s.58°W., 38.8 ft.
13" dia. W.Fir double blazed and scribed "T22S R6W S3 CSBT"
bears S.18 $\frac{1}{2}$ °E., 33.2 ft.
Corner lies at the intersection of a west and south funning fence lines.
2/24/92

160

Tsp. Corner - NE Corner section 1
Found - DCSO brass cap flush with ground. (Set in 1990)
Note: Renewal of this corner not recorded in 1990. DCSO
BC/IP was set at position of stone. (Set by Haines in 1943
per Ren. No. 59 Stone was set along edge of BC/IP below
ground.

161

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 24, 1992
C.S. File 64/24

40" now 46" dia. D.Fir with a fully healed blaze, bears
S.21°E., 31.0 ft. (agrees w/rec) Ren. No. 59
8" now 22" dia. D.Fir with a fully healed double blaze,
bears N.72°E., 56.0 ft. (agrees w/rec) Ren. No. 59
10" now 14" dia. B.Oak with a fully healed double blaze,
bears S.28°W., 18.8 ft. (agrees w/rec) Ren. No. 59
8" now 11" dia. W.Oak with a fully healed double blaze, bears
N.2°W., 10.0 ft. (agrees w/rec) Ren. No. 59
20" now 39" dia. W.Oak with a fully healed blaze, bears S.7 $\frac{1}{2}$ °E.,
97.9 ft. (Rec. S.7 $\frac{1}{2}$ °E., 95.7 ft. dist. is a face measurement)
Orig. BT.
24" now 24" dia. 1 $\frac{1}{2}$ ft. high rotted Oak stump with a rotted blaze
No scribing visible, bears S.13°W., 138.6 ft. (agrees w/rec.)
Orig. BT.
Randall W. Smith and Stephen J. Flause set DCSO 1990 BC/IP during Control
Survey on file in Douglas County Surveyor's Office.

FD OK - M 121 - 21 - 11/10/94 3/16/92