

Douglas County Surveyor's Record of  
Government Corners Renewed

22

T. S.

6

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21991

177

1/4 Cor. Secs. 5 & 6

Set - 5/8"x30" Iron Pin w/yellow plastic cap stamped "ROBERTS PLS  
1039"  
6" Fir, S.61°W., 16.1' (scribed/washer/painted red)  
6" Fir, S.01°E., 20.5' (scribed/washer/painted red)  
6" Fir, N.54°W., 10.9' (scribed/washer/painted red)  
8" Fir, N.49°E., 27.7' (scribed/washer/painted red)

178

Cor. Secs. 5, 6, 7, & 8

Found - 1961 Douglas County Iron Pipe & Brass Cap (Ren #107)  
18" Fir snag, N.63°E., 23.5' (scribe vis), 1855 BT.  
26" Fir, S.23°E., 11.5' (scribe vis), 1855 BT.  
26" Fir snag, N.41°E., 21.1' (scribe vis), 1961 BT.  
12" Fir, N.61°W., 18.5' (scar vis), 1986 BT. (Ren #147)  
New BTs- 12" Fir, N.61°W., 18.5' (scribed/washer/painted red)  
14" Fir, N.35°W., 29.8' (scribed/washer/painted red)  
18" Fir, S.59°W., 32.8' (scribed/washer/painted red)

179

1/4 Cor. Secs. 6 & 7

Set - 5/8"x30" Iron Pin w/yellow plastic cap stamped "ROBERTS PLS  
1039"  
10" Maple, N.32°E., 19.0' (scribed/washer/painted red)  
12" Hemlock, South 22.6' (scribed/washer/painted red)  
14" Maple, N.88°W., 23.1' (scribed/washer/painted red)  
24" Hemlock, S.72°W., 29.9' (scribed/washer/painted red)

180

Cor. Secs. 6 & 7; & 1 & 12 T22-7

Found - Haines "T" iron set in survey M 3-22 (Ren. #40)  
24" Fir, N.17°W., 21.5' (scar vis.) 1956 BT.  
36" Fir, S.43°E., 51.5' (rec. S.22°30'E., 73.8') (scar vis.)  
1956 BT.  
40" Fir, S.06°E., 45.7' (rec. 70.8') (scar vis.) 1956 BT.

181

NW Township Cor. T22-6 (NW Cor. sec. 6)

CONDITION REPORT ONLY

Found - 1986 BLM iron pipe & brass cap.  
28" Fir snag, N.59°E., 37.0' (scribe vis), 1855 BT.  
1966 Douglas County brass cap, 0.55' south of 1986 BLM iron  
pipe & brass cap. (Ren. #119)  
14" Hemlock, N.26°W., 13.2' (scribe vis.), 1966 BT.  
15" Hemlock, N.80°E., 25.0' (scribe vis.), 1966 BT.  
30" Hemlock, S.61°E., 30.0' (scribe vis.), 1966 BT.

1/9/95

182

Twship. NE cor. sec. 01

Monuments Fd. - 14"x14"x7" stone with a probable "+" mkd. on side,  
stone appears to have been tipped over and is in two  
pieces. stone was found 1 ft. below ground. (set  
by Haines in 1943 see Ren # 60.)

Accessories Fd. - 40" now 47" dia. D.Fir, with a fully healed single  
blaze, bears S.21°E. 31' (agrees w/ rec.) ren. #  
60.

8" now 21" dia., D.Fir, with a fully healed double  
blaze, bears N.72°E. 56' (agrees w/ rec.) Ren.  
#60.

10" now 15" dia., B.Oak, with a fully healed double  
blaze, bears S.28°W. 18.8' (agrees w/ rec.).

8" now 12" dia., W.Oak, with a fully healed sing blaze,  
bears N.2°W. 10' (agrees w/ rec.) Ren. #60.

24" now 24" dia., 14" high rotted oak stump w/ axle  
cont. next page

Les Roberts, L.S. 1039  
For: Seneca Jones Timber Co.  
Dec. 1994 M 121-27

DOUGLAS COUNTY  
RANDALL SMITH  
STEPHEN FLAUSE  
11/2/90  
CS 64/58