

Douglas County Surveyor's Record of
Government Corners Renewed

T 22 S T. S. R 7 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Corner to Sections 19 and 20. 102
 Found - $\frac{3}{4}$ " Pipe set by Evans, 1950, REN. No. #228
 40" Fir Stump, bark scribed, N.67°W. 79.0 ft.
 8" Bl. Oak N.80°W. 58.7 ft. bark scribed " $\frac{1}{4}$ " S20 CS".
 Corner Pipe still in good condition. - Did not set Brass Cap.
 New BT's: 13" D. Fir N.47°E. 35.4 ft. Mkd: $\frac{1}{4}$ " S20 CS BT.
 8" B. Oak N.80°W. 58.7 ft. Mkd: $\frac{1}{4}$ " S19 CS BT. (Evans Tree)
 Note. - Rotted Fir Stump bears N.15°E. 4.0 ft. One Orig. BT.,
 a Fir was N.25°E. 4.0 ft.
 Corner lies on very steep East slope approx. 125 ft. E. of
 top of ridge.

Wit. Corner to Sections 15 and 22. 103
 (By Gordon & Gardiner, 1855)
 Found - Dbl. Cedar, 50", N.11 $\frac{1}{2}$ °W. 27.7 ft., scribing visible
 in previously opened scar, "T22 R7W BT". Cedar has
 been dead for several years.
 Remains of Cedar Stump S.45 $\frac{1}{2}$ °W. 38.3 ft., uprooted &
 center rotted away, no scars or scribing found.
 Set - Brass Cap at Corner Mkd: County Surveyor's T22SR7W WC S15
 Office, 1962 S22
 New BT's: 8" D. Fir S.86°W. 28.7 ft. Mkd: "WC S22 CS BT".
 6" D. Fir N.46°W. 24.8 ft. Mkd: "WC S15 CS BT".

FD. OK 3/87
 C.S. 63/62
 J. Hollingsworth

$\frac{1}{4}$ Corner to Sections 15 and 22. 104
 (By Gordon & Gardiner, 1855)
 Found - Fir Snag, now 78", N.51°E. 94.4 ft., no scribing found,
 but old axe marks in badly burned bark.
 Old Fir Log, almost completely buried in swampy ground,
 bears S.16°E. 95.7 ft.
 Position checks call from Wit. Cor. (Gordon & Gardiner) on bank
 of Elk Creek East of $\frac{1}{4}$ Corner. Also checks tie shown
 on map of State Highway No. 38.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R7W 1855 $\frac{1}{4}$ S15
 Office, 1962 S22
 New BT's: 12" D. Fir S.50°E. 16.7 ft. Mkd: $\frac{1}{4}$ " S22 CS BT.
 8" D. Fir N.28°E. 19.6 ft. Mkd: $\frac{1}{4}$ " S15 CS BT.

FD. OK 2/87
 C.S. 63/62
 J. Hollingsworth
 O.D.O.T
 M/15-28

Wit. Cor. to Sections 16 and 21. (By Gordon & Gardiner, 1855) 105
 Found - Badly burned Fir Snag S.35°W. 2.6 ft., chop open scar
 and find excellent scribing "S21 T22S R7W BT".
 No trace found of Laurel BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's W.C. S16 T22S R7W
 Office, 1962 S21
 New BT's: 9" D. Fir S.55°W. 22.9 ft. Mkd: W.C. S21 CS BT.
 6" D. Fir N.17°E. 39.2 ft. Mkd: W.C. S16 CS BT.
 Corner lies on very steep N.W. slope, approx. 150 ft. West of top
 of hill. Top of vertical rock cliff, 10 ft. high, lies
 4.0 ft. N.W. of corner.

Section Corner to Sections 21 - 22 - 27 - 28. 106
 Found - Haines "T" Iron. & 39" D. Fir N.10°W. 8.6 ft. Chopped
 open & found good scribing "W" on old face. REN. #82
 40" D. Fir N.27°E. 16.5 ft., shows good scar.
 58" D. Fir S.35°E. 76.6 ft. (slope dist.) shows good scar.
 No trace of Dogwood BT.
Did Not Set Brass Cap.
 New BT's: 39" Fir N.10°W. 8.6 ft. Mkd: T22S R7W S21 CS BT.
 40" Fir N.27°E. 16.5 ft. Mkd: T22S R7W S22 CS BT.
 7" D. Fir S. 2°W. 21.5 ft. Mkd: T22S R7W S28 CS BT.
 6" D. Fir S.63°E. 26.2 ft. Mkd: S27 CS BT.
 Corner is in E. & W. Fence Line, on a small bench approx. 300 ft.
 East of Ridge Top.

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy and Clete Putnam
 March 1962
 C. S. File No. 52/14