

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

145

Milo E. Godfrey, Deputy Co. Surveyor  
Vernond Tracy  
Mike Stone  
July 17, 1962  
C. S. File No. 52/14

$\frac{1}{4}$  Corner to Sections 5 and 8.  
Found - Fir, now 17", N.28°E. 4.6 ft., chopped open & fd. good  
scribing "S" on old face.  
Fir, now 21", S.80°W. 7.9 ft., shows good scars. Found bark  
scribing "B". I reblaze & scribe this tree " $\frac{1}{4}$  S 8 CS BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R7W  $\frac{1}{4}$   $\frac{S 5}{S 8}$   
Office, 1962  
New BT: 17" D.Fir N.37°E. 7.1 ft. Mkd:  $\frac{1}{4}$  S5 CS BT.  
Corner lies directly on top of spur running N.50°E. approx. 200 ft.(elev.)  
above creek bottom to East.

146

Section Corner to Sections 5 - 6 - 7 - 8.  
Found - Haines' "T" Iron at Corner with no cap. (No Record)  
Fir, now 42", S.52°E. 92.4 ft. very faint bark scribing  
visible "S8" & "R" legible.  
Fir, now 36", S.10°W. 22.4 ft., shows very plain scar. Didn't open.  
Blaze & Rescribe this tree "T22S R7W S7 CS BT".  
No trace found of N.E. or N.W. trees.  
DID NOT SET BRASS CAP.  
New BT's: 14" Hemlock N.15°W. 36.4 ft. Mkd: T22S R7W S6 CS BT.  
18" D.Fir N.50°E. 26.5 ft. Mkd: T22S R7W S5 CS BT.  
15" D.Fir S.70°E. 21.4 ft. Mkd: T22S R7W S8 CS BT.  
Corner lies on very Steep S. E. Slope.

C. S. File  
No.  
52/14

147

$\frac{1}{4}$  Corner to Sec. 6, T22-7W. and Sec. 31, T21-7W.  
Found - Fir, now 40", N.49°W. 31.7 ft., very faint bark scribing  
visible "S" and part of "B".  
Fir Snag bears S.37°W. 42.2 ft., bark all gone & big hole  
burned in N.E. side. No marks found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$   $\frac{S31}{S6}$  T21S R7W  
Office, 1962 T22S  
New BT's: 16" D.Fir N.75°E. 10.2 ft. mkd:  $\frac{1}{4}$  S31 CS BT.  
10" D.Fir South 31.6 ft. mkd:  $\frac{1}{4}$  S6 CS BT.

August 3, 1962

Milo E. Godfrey  
& Crew  
C.S. File  
No.  
52/14

N. E. Corner D. L. C. No. 44.  
Found - Sandstone Rock 6" x 6" x 12" set by B.B.Irving, 1929. (See Ren. #26 of T22-8)  
("44" chisled on S. W. Face.) See Map File M 6 - 7.  
Rotten Fir Stump N.3 $\frac{1}{2}$ °W. 556 lks., scribing "BT" still  
visible on old face.  
Rotten Fir Stump N.14 $\frac{1}{2}$ °E. 728 lks., scribing "BT" still  
visible on old face.  
Set - Brass Cap alongside Rock at Cor. & Mkd: County Surveyor's  
Office, 1962 T22S R7W N.E. DEC 44  
New BT's: 5" D.Fir N. 5°E. 181.7 ft. Mkd: NE DLC 44 CS BT.  
28" D.Fir S.1°W. 260.0 ft. Mkd: NE DLC 44 CS BT.  
The chimney on Oliver Haines' house bears S.65°W.  
Dec. 12, 1962

149

Milo E. Godfrey  
& Crew  
Oct. 3, 1963  
C. S. File  
No. 52/14

Section Corner to Sections 19 - 20 - 29 - 30.  
Found - 1" Sq. Iron Bar -  $\frac{3}{4}$ " Pipe rusted & broken off at top of ground,  
(See Renewal Cor. No. 100)  
Set - drove in Steel Fence Post, top about level with top of blackberries.  
All Bearing Trees still alive;  
32" Fir N.25°W. 89.6 ft., in good condition.  
18" W. Oak S.60°W. 59.1 ft., in good condition.  
16" Maple. S.89°E. 52.5 ft., in good condition.  
36" B.Oak N.21°E. 143.3 ft., alive, but several big limbs broken off  
by last year's windstorm.

Fd 5/89  
D. Baker  
Mial 55  
FD 10/93  
D. Bentz  
Brass Cap  
2 BTs  
1993-0084