

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

160

Wilford N. Haines
Nov. 30, 1965
C. S. File No. 51/309

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - I. Pipe with Brass Cap set by Co. Surv, 1962. (See. Ren. #113)
Stump S. 89° W. 30.0 ft., some scribing still on stump,
rescribed on N. E. face. *cont. O.K. Feb. 1966*
Orig. Stump, N. E., still there but no scribe.
New BT: 5" Fir N. 12° E. 186.0 feet.

161

$\frac{1}{4}$ Corner to Sections 8 and 9.
Found - "T" Iron in place. See Ren. # 151.
Both BT's. gone.
New BT's: 8" D. Fir N. 71° W. 40.0 ft.
5" W. Fir N. 15° E. 48.9 ft.

162

Township Corner:
Found - Haines' "T" Iron, See Ren. #66, under a 16" Log, set from
Orig. BT., as follows:
Orig. 20", now 28" Fir Snag, N. 59° E. 37.6 ft. Open & find
"31 T21 6W" scribe.
All other BT's. destroyed.
Set - Brass Cap 6" South of "T" Iron alongside Log & Mkd: *#205*
County Surveyor's Office, 1966
T 21 S R7W S 36 S 31 R6W
S 1 S 6
New BT's: 7" Hemlock N. 26° W. 13.2 ft. mkd. T21S R7W S36 CS BT.
9" Hemlock N. 80° E. 24.9 ft. mkd. T21S R6W S31 CS BT.
26" R. Cedar S. 61° E. 29.9 ft. mkd. T22S R6W S 6 CS BT.
No suitable tree to S.W. - Corner lies on steep, N.W. slope.

163

S. E. Corner D. L. C. No. 43.
Found - 2 Original Bearing Trees, both now stumps.
Set - $\frac{1}{2}$ " Steel Rod for corner. - *SEE REN. #166*
Note - N.E. Cor. DLC #41, 92.0 ft. W. of this corner, SEE BELOW.

164

N. E. Corner D. L. C. No. 41.
Found - Orig. 12" Oak, now dead, S. 25° E. 72.0 lks. - Ren. #8
Set - $\frac{1}{2}$ " Steel Rod and scribed:
New BT's: 6" Fir S. 38° E. 4.3 ft.
14" Fir S. 36° W. 29.9 ft.

165

Witness Corner for Sections 17 - 18 - 19 - 20
Set - S. $89^{\circ} 46'$ E. 72.80 chains on Line between Sections 18 and 19.
Found - 20" Fir, now a windfall, N. 28° W. 92. lks.
Set - $\frac{1}{2}$ " Steel Rod in old Cat Road on top of ridge & scribed:
New BT: 12" Fir West 14.3 ft.

Note - Cor. checked by VRT. 4/67, Not sufficient evidenceto renew, C.S. File No. 54/41.

166

S. E. Corner to D. L. C. No. 43.
Found - $\frac{1}{2}$ " I. Rod at Corner, set by Haines, See Ren. #163.
Orig. 10", now 40" Fir, N. 10° E. 38.3 ft., prev. opened many
years ago., "W" scribe visible. We open higher & find
"22S 7" scribe & reverse. Fir, now stump.
Orig. 12", now 40" Fir Stump, N. 80° W. 34.3 ft., not opened,
burl wood visible on top of stump.
New BT's: 12" D. Fir S. 79° E. 18.4 ft. mkd. SE DLC 43 CS BT.
11" D. Fir S. 3° W. 21.4 ft. mkd. SE DLC 43 CS BT.
Note - This corner lies 97.0 ft. East of N.E. Corner DLC #41 & on
northerly slope approx. 150 ft. S. of small stream, course E.

MICROFILM TO HERE 10/67

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
Sept. 1, 1966
C. S. File No. 54/14

Wilford N. Haines
For R. D. Hungerford
March, 1967
Map File M 32 - 72

Vernon "Ray" Tracy
J. Heritage & E. West
April 4, 1967
C. S. File No. 54/41