

County Surveyor's Record, Douglas County, Oregon
Government Corners Renewed

T 22 S R 8 W WM

Ben B. Irving Co. Surveyor
Milo Godfrey Witness
March 1945
C.S. M10-72

Ben B. Irving Co. Surveyor
Milo Godfrey Witness
March 1945
C.S. M10-72

Ben B. Irving Co. Surveyor
Milo Godfrey Witness
March 1945
C.S. M10-72

S.W. Corner, Edward Griffin DLC No. 42 & S.E. COR. **37**
Wm. Helbert DLC No. 43.
Pipe set by Cole, 1915, a 24" Fir S 57° E 18.6 ft.
in place one bearing tree fallen down and rotting.
Marked new BT, a fir 24" dia., which bears N 87° 30' W 19.7 ft. blazed and scribed DLC 42-43 CS BT **113**

NW COR. Edward Griffin DLC No. 42 and NE Wm. Helbert COR. **38**
DLC No. 43.
Post set by Cole 1915 has disappeared OBT N 64° W 70' links entirely rotted away except for roots. -REN#5
OBT Oak 15" diam. S 55° W 215 lks. has been cut and stump nearly rotted away, chopped out BT blaze and found scribe marks BT thereon. **114**
Set a 1/2" x 72" iron pipe 70 in. in the ground for the cor.
Marked new bearing tree, a white Oak 24" Diam. which bears S 59° W 42.3 ft., and Ash 24" diam. which bears N 87° W 65.3 ft. NW cor. DLC 42 CS BT

SE COR Edward Griffin DLC No. 42 and SW Cor. Wm. N. Wells **39**
DLC No. 41.
Location identified from stump of and OBT fir, which is badly rotted but found scribe marks BT. still legible N 22° E 75 links.
Drove a 1/2" x 36" pipe 34" in ground for corner and set new bearing trees.
A White Oak 6" diam which bears N 67° W 79.7 ft.
A Black Oak 4" diam which bears N 35 1/2° E 13.2 ft.
both blazed and scribed SE DLC 42 CS BT

Southwest Exterior Cor. and Southwest Interior Cor. for the South boundary of DLC No. 42 were both gone and all traces thereof lost. **40**
The East and West distance along the south boundary between the Southeast and Southwest corners of the DLC No. 42 failing to agree with the record, I set a 1/2" x 36" iron pipe 33" in the ground for the Southwest exterior corner West of the Southeast corner its proportional distance from which
A fir 12" diam bears N 62° W 24.3 ft. and **120**
A fir 24" diam bears N 10° W 70.4 ft. both blazed and scribed SW Ext DLC 42 CS BT

The Southwest Interior corner DLC 42 a 1/2" x 30" iron pipe **34"** in the ground was set, its proportional distance East of the Southwest corner from which **41**
A fir 24" in diam. bears N 59° W 76.5 ft.
A fir 20" in diam. bears N 86° W 21.0 ft. **112**
both blazed and scribed SW Int DLC 42 CS BT

Northeast Cor. of DLC No. 42 Northwest cor. DLC No. 41
All evidences of this corner having been destroyed a 1/2" x 48" tie rod was set 46" in the ground for the corner from which a white oak 6" in diam. bears N 76° E 19 ft. and ash 6" in diam. bears N 23° W 27.6 ft. **42** **119**
The location of this corner was determined by computation from the Southeast corner of DLC No. 42 and the Meander corner on the left bank of the Umpqua River between Secs. 22 & 23. From such computations these positions were determined and the one which most nearly satisfied local conditions was used.